STELLA MARY'S COLLEGE OF ENGINEERING

(Accredited by NAAC, Approved by AICTE - New Delhi, Affiliated to Anna University Chennai)

Aruthenganvilai, Azhikal Post, Kanyalumari District, Tamilnadu - 629202.

ME8451 MANUFACTURING TECHNOLOGY II

(Anna University: R2017)



Prepared By

Mr. F. X. Aruno Xavier

Assistant Professor

DEPARTMENT OF MECHANICAL ENGINEERING



STELLA MARY'S COLLEGE OF ENGINEERING

(Approved by AICTE, New Delhi, Affiliated to Anna University, Chennai Aruthenganvilai, Kallukatti Junction Azhikal Post, Kanyakumari District-629202, Tamil Nadu.

DEPARTMENT OF MECHANICAL ENGINEERING

COURSE MATERIAL

REGULATION	2017
YEAR	П
SEMESTER	04
COURSE NAME	MANUFACTURING TECHNOLOGY II
COURSE CODE	ME8451
NAME OF THE COURSE INSTRUCTOR	Mr. F. X. ARUNO XAVIER

SYLLABUS:

UNIT I THEORY OF METAL CUTTING

Mechanics of chip formation, single point cutting tool, forces in machining, Types of chip, cutting tools– nomenclature, orthogonal metal cutting, thermal aspects, cutting tool materials, tool wear, tool life, surfacefinish, cutting fluids and Machinability.

UNIT II TURNINGMACHINES

Centre lathe, constructional features, specification, operations – taper turning methods, thread cutting methods, special attachments, machining time and power estimation. Capstan and turret lathes- tool layout – automatic lathes: semi automatic – single spindle : Swiss type, automatic screw type – multi spindle:

UNIT III SHAPER, MILLING AND GEAR CUTTING MACHINES

Shaper - Types of operations. Drilling ,reaming, boring, Tapping. Milling operations-types of milling cutter. Gear cutting – forming and generation principle and construction of gear milling ,hobbing and gear shaping processes – finishing of gears.

UNIT IV ABRASIVE PROCESS AND BROACHING

Abrasive processes: grinding wheel – specifications and selection, types of grinding process– cylindrical grinding, surface grinding, centreless grinding and internal grinding- Typical applications – concepts of surface integrity, broaching machines: broach construction – push, pull, surface and continuous broaching machines

9

9

9

9

UNIT V CNCMACHINING

Numerical Control (NC) machine tools – CNC types, constructional details, special features, machining centre, part programming fundamentals CNC – manual part programming – micromachining – wafermachining.

TEXT BOOKS :

- 1. Hajra Choudhury, "Elements of WorkshopTechnology", Vol.II., Media Promoters 2014
- 2. Rao. P.N "Manufacturing Technology Metal Cutting and Machine Tools", 3rd Edition, Tata McGraw-Hill, ewDelhi, 2013.

REFERENCES:

- 1. Richerd R Kibbe, John E. Neely, Roland O. Merges and Warren J.White "Machine Tool Practices", Prentice Hall of India, 1998
- 2. Geofrey Boothroyd, "Fundamentals of Metal Machining and Machine Tools", Mc Graw Hill, 1984
- 3. HMT, "ProductionTechnology", Tata McGrawHill, 1998.
- 4. Roy. A.Lindberg, "Process and Materials of Manufacture," Fourth Edition, PHI/Pearson Education 2006.

Course Outcome Articulation Matrix

	Program Outcome								PSO						
Course Code / CO No	1	2	3	4	5	6	7	8	9	10	11	12	1	2	3
ME8451 / C212.1	3	2	3	2	3	2	0	0	2	2	2	3	3	2	3
ME8451 / C212.2	3	2	3	0	3	2	0	0	2	2	2	3	3	2	3
ME8451 / C212.3	3	0	3	0	3	2	0	0	2	2	2	3	3	2	3
ME8451 / C212.4	3	2	3	0	3	2	0	0	2	2	2	3	3	2	3
ME8451 / C212.5	3	3	3	2	3	2	0	1	2	2	2	3	3	2	3
Average	3	2	3	1	3	2	0	0	2	2	2	3	3	2	3

Unit-1 Theony of metal cutting

> Single Point Tool (Lathe, slotting, sharer tool) Cutting Tools (-> Multi point tool (Milling Cutters, Broaching tool)

Factors that have a predominant influence on metal cutting :-1) cutting tool Geometry Clearance angle (2) work & cutting Tool material (3) cutting speed (4) feed (5) Depth of cut (b) cutting flinds used. Rake angle & clearance angle :-* "Rake angle" is the angle blu the Rake face of the cutting tool & the line is" to the base of the tool (09) It is the angle b/w the Rake face and the line somel to the machining dine ction.

Significance of the Rake angle !-

I It specifies the ease with which a metal is cut.

2

- (2) Higher the grake angle, better is the cutting and Less are the cutting forces.
- Note:-* The maximum limit for the stake angle is 15°

* zero & repative rake angle in used for giving extra strength to the tool tip. These tools are used for m(cine highly hard material such as Carbides (on) Diamond.



(a) Positive Rake angle



(b) Zero (or) Neutral Rake angle



(C) Negative Rake angle

"Clearance Angle" is the angle b/w the machined surface and the flank face of the tool.

Significance of clearance Angle:-

() It is provided on the tool to avoid the hubbing of the tool on the wip when the machining takes place. Hence it prevents the spoiling of the machined surface. (2) It is used to increase the cutting

Ð

forces.

Single Point Cutting Tool Nomen clature TOP Rake Angle (Back Pake Angle) Bide Rake Angle Rake face FLANK (or) face End clearan learance angle nple Eng Cutting angle Note Side Cutting Angle

1) Shank:-Position of the tool bit which is not ground to form the cutting edges & is Aectanpular in Cross-section. 2 Rake face: -

Surface against which the Chip slides 3 Flank face:

Surface which faces the w/P.

(Nose:-

The point of intersection of Side & End cutting edges. Nose stadious increases the tool life & Surface finish.

(5) Cutting edge :-

It is the junction of the Rake face & the flank face.

a) Side cutting edge

b) End Cutting edge.

(6) Various apples in the cutting Tool:-

O Rake Angle Side Rake Angle

(2) Cleanance Angle (on) Relief Angle
a) End (or) Front Relief angle
b) Side Cleanance angle.
(3) Cutting edge Angle
a) Side Cutting edge Angle
b) End Cutting edge Angle
b) End Cutting edge Angle
(4) NOSE Gladious (or) NOSE angle.

TOP Rake angle:-

* Also called as "Back Rake angle". * It is the angle blue the Rake face of the tool & the line 11" to the base of the tool. This is measured along the length of the tool.

Side Rake angle!-

It is also the angle by the Rake face & the base of the tool. But it is measured along the width of the tool.

End (or) Front Relief angle:_

It is the angle blue the front flank face & the line IT to the base of the

Unit-1 Theony of metal cutting > Single Point Tool (Lathe, slotting, sharer tool) Cutting Tools -> Multi point tool (Milling Cutters, Broaching tool) Factors that have a predominant influence on metal cutting :-> Rake angle 1) cutting tool Geometry (-> Clearance angle (2) work & cutting Tool material 3 cutting speed (feed (5) Depth of cut (b) cutting flinds used. Rake angle & cleanance angle :-* "Rake angle" is the angle blu the Rake face of the cutting tool & the line 11" to the base of the tool (on) It is the angle by the Rake face and the line normal to the machining dine ction.

tool. The Purpose of Providing this angle (7) is to avoid the stubbing of the tool on the upp when the tool is fed along the length of the Job.

Side Relief (or) clearance angle:

It is the angle blu the Side Flank fece and the line I' to the base of the tool. The Purpose of Providing this angle is to avoid the Rubbing of the tool on the w/P when the tool is fed. Cross wise to the w/P.

Side & End cutting edge angle:-

* Side cutting edge angle is the angle blu the side cutting edge and the longitudinal axis of the cutting tool whereas the end cutting edge angle is the angle blu the End cutting edge and the line I' to the longitudind axis.

* these angles will allow only a Smaller Portion of the cutting edge to contact with the w/P and thus Phelents the Vibration and chatter. Normally this angle Varies from 5° to 12°. Nose angle (or) nose Radions:-* It is the angle b] the side cutting edge and End cutting edge

* It is used to increase the tool life and surface finish of the w/P.

Orthogonal & oblique cutting :-



the metal cutting processes are mainly classified into 2 types

> (i) Orthogonal cutting [2-D cutting] (ii) Oblique cutting process [3-D cutting]

* If the cutting edge is at 90° to the it is known as "oblight cutting" line of a ction (or) Path of the * If the cutting edge of the tool is (?) at an acute angle [less than 90] to the line which is normal to the cutting Velocity Vector it is known as "oblight cutting".

Points to be noted !-

* For the same depth of cut & feed,

a) the force which cuts (or) Shears the metal acts on a larger Afrea in case of oblique tool and the oblique tool will have a longer life of the fleat developed Per Unit Afrea due to friction along w/P-tool interface is Small.

b) The oblique tool will remove more metal compared to anthogonal tool.



Exam	rele for orthogonal	8 oblique cuttings
~~~~		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
Orth	ogonal cutting - Sa	Lwing, Broaching,
	SI	otting, parting-off opros.
oblig	me cutting - t	urning opreation in Lathe,
	٢	villing, doubling oppreasions etc.,
Com	Perison blu orthog	
5.00	Or thegonal cutting	oblique cutting.
1.	Cutting edge of the tool in I' to the line of action (or) Path of the tool. The Chip flows like	cutting edge of the tool is at an acute angle to line which is normal to the cutting Velocity Vector. The chip flows like
	a tight flat spiral.	long curl.
3.	Only one cutting edge Contacts with the	Frequently, more than

during the opreation

will during open.

Orthogonal cutting oblique cutting. SNO 4. Only 2 components 3 components of of forces are there forces are there during opreation during operation feed & cutting force) [ feed, cutting & thrust force For the same depth of 5. For the Same depty Cut, the frictional of cut, the frictional force/ vait Anea is high force whit Anea 13 as less area contacts compare tively low as with the w/p during the more area contacts opm and hence tool with the wp during life is comparatively the open and hence less the tool life is Compare tively mohe 6. examples:examples:_ Sawing, Broaching, Lathe turning oprn, Slotting and Lathe Milling, drilling etc., Parting off opens, Shaping oprections.

Chip formation :-

Narious types of chips are formed during metal cutting. The type of chip formed during metal cutting depends on the machining condition & material to be cut.

Factors affecting the formation of Chip:-

- (i) nechanical properties of the material to be cut. If the cutting tool.
- in Depth of cut, cutting speed, feed nate.
- (iii) Geometry of the Tool.
- (iv) Type of cutting fluid.
- (r) M cing temperature in the culting Region.
- (Vi) Co-eff of friction b/w whe & Tool.

Types of chips !-

Continuous Chips (or) Ribbon type Chip.
 The discontinuous Chip (or) Segmented Chip.
 The Continuous Chip with Build-up edge (BUE)

O Continuous Chip (or) Ribbon type Chip:-
* During cutting ductile material, a continuous
ribbon like chips is produced.
* these chips are in the form of Long Curl
and have same thickness throughout its length.
Advantages:-
Good Surface finish, Less Power Consumption,
Mone tool life
Dis Advantager:-
a) chip disposed is not easy
b) the surface finish of finished goods
gets affected
Favourable conditions !-
O Ductile material Such as law carbon Steel,
aluminium, copper etc.,
2) Smaller depth of cut
3 High cutting speed @ Large Rake angk.
(5) proper cutting fluid.
6 Low friction blue tool & chips.



* This type of Chips are produced while machining brittle materials such as bronze, brass & cast Iron.

* Here, chips are produced in the form of Small segmental Separate Pieces.

* The discontinuous chips can also be 16 Produced in cutting of ductile metals at Very low feeds high cutting speeds larger dependent cut & high friction. * If the discontinuous chips are produced from the brittle material, then the Surface finish 11 fair, Power conjumption is but tool life is heasonable. However if it is produced from ductile metals, then finish is Poon & the tool wear is excessive. Conditions promoting the formation of discontinuous chies !-O Machining the brittle materials 2) For ductile metals a) Greater depth of cut b) High Cutting Steed c) how feed d) Smaller rake angle e) High friction blu whet Tool.

is called as "the Built - UP Edge (BUE)". The BUE is a highly strain hardened brittle material. So when the chip flows over the tool face, it will easily break & some Part of it will be carried away with the Chip and the remaining part of it will adhere to the work piece leading to a Poor (7-) Surface finish. Disadvantages of BUE !-O Poon Surface finish. 2 the grake angle of the tool is altered & hence the cutting force of the tool will get affected. Advantages of BUE :-1) The Rake face of the tool is Protected from wears due to the moving chips over the tool face. It may great in increasing the tool life

Conditions Promoting the formation of Built-up Edge (BUE) :-(17-2) Low cutting speed 2) Excessive feed 3 Larger depth of cut. ( Lack of Lubricant (5) Smaller Rake angle High friction bow the tool & w/P. (6)

CHIP BREAKERS !-

During machining of ductile material, long and continuous this that are formed at high cuting speed will affect the machining. It will Spoil tool, work and machine. It will be difficult to she note this types of chip and also it is desperous to safety. Chip breakers are used to break the chips into small pieces for easy nemoval, safety and to prevent Die breater damaging of marchine and work. K land Groove I STEP Conside 7001 Clamp type Grode type step type

This is Very infortant in automatic machines which are running at Very high Speeds. The Chip breaker is provided on the cutting edge as shown in the figure. The difference of the breaker what

on a cutting tool are.

O Step type @ Groad type 3 clamp type.

In step type, a step is fround on the tool face behind the cutting edge. In Groove type, a groove on the tool face behind the cutting edge will break the Chip. In Clamp type, a thin Chip beaker is clamped (or) screwed on the face of the tool. Mechanism of Metal cutting (or) Mechanism of Chip formation :cutting Tool 

* During machining, the cutting tool events a. . Shear, force on the work piece

It the material of the will in stressed beyond its yield point under this . Shear, force.

* this causes the material to deform plassically and finally get sheared off. * The plastic flow takesplace in a localized region called Shear Plane (or) shear zone which extends from the cutting Point to the vncut surface

* The Sheared material begins to flow along the cutting tool face in the form of Small Pieces called Chips.

* when the chip florg over the tool face, high beat is produced by the chip & Tool face. This temperature rise in the tool tends to Soften the cutting edge and leads to failine of the cutting edge

Georetry of chip formation :-

* Generally, the Chip thickness is layer than the thickness of material to be gremoled. Also, the metal prior to cut is longer than the length of the Chip. Hence Volume of metal prior to and after the cut is some

t_1 = Chip thickness prior to Cut t_2 = Chip thickness after cut.

* The specie of chipthickess before cutting to this thickness after cutting is called as "Chip thickness matio (m)".

(ie) Chip thickness spatio,  $n = \frac{t_1}{t_2}$ 

Its volve is always less there one. A hario of 1:2 yield a good result.

Is called " Chip reduction Co-efficient" (12).

* volume of metol } = volume of Chip to be premoved } =

 $t_1 \times l_1 \times b_1 = t_2 \times l_2 \times b_2$ 

tixl, = t2xl2 (: b1=b2)

$$\frac{t_1}{t_2} = \frac{l_2}{l_1} = h = Chip thickness hat is$$

 $\sin \beta = -t \rightarrow AB = -t$ SINB AB

From D. ABD;
$\sin\left[q_0 - \beta + d\right] = \frac{BD}{AB} = \frac{t_2}{AB}$
$AB = \frac{t_2}{Sin(90-B+x)}$
Comparing ( & 2)
STOP = t2 STOP = STO(90-Ptd)
$\frac{t_1}{t_2} = \frac{\sin \beta}{\sin \left( q_0 - \beta t_x \right)}$
$r = \frac{\sin \beta}{\cos(\beta - \alpha)}$
STOR COSP COSE + Sing Sind
r[cosp cosd + Sinpsind] = 1 Sinp
tang trang
r cosd = 1-rsind

tank

tank= rcosk 1- rsind : Shear angle, B= tan - [-rosk] cutting forces in Metol cutting :-( ( Fx ) Feed Fy > feed force Fy > Thrust force Fy > Thrust force Fz > cutting force. In orthogonal authings only two forces are there (ie) Fx - feed force & F2 - Cutting force * reed force (Fx) acts in a direction. opposite to the feed. * Thrust force (Fy) acts in a direction 1 to the generated Surface. * FZ acts in a direction of cutting velocity.

The Various forces acting on the tool and other than the cutting forces in workpiece autig?or the gond



F, F' = Resultant forces for Fn 1 Fg & P, N sessecutely

- d, R, 2) = Rake angle, Shear angle, friction angle respectively.
  - FA = Shear Resisting force
  - Fn = Back-up force on the Chip by the workpiece.
  - P = Frictional force along the rake face
  - is = wormal force acting on the tool when the chip starts flowing over its pake face

Merchant Circle Diagram of forces? This diagram is used to find the relation by Various forces and angles. following assumptions are made while the drawing the merchant circle Diagram. the tool is perfectly sharp and has no (1) along the clearance face. (2) The surface where shear is occurring Considered as a plane. (3) The cutting edge is 1" to the cutting Velocity Vector of generates a plane Surface of the work moles Post it. The chip doesn't flow to either side (or) G no side spread. (5) vacut chip thickness is constant. The width of the tool is greater than the 6) width of the w/P. Ŧ A continuous this is produced without Build-up edge (BUE). (8) The stresses on a shear plane are Uniformly Digtributed.



* Two force triangles is combined together. Their resultant will be given by the resultant force `F'.

* read force (Fx) & cutting force (Fz) are found out by food force dynamo meter & 13 drawn to the Suitable Scale. Their resultant will be given by the resultant force 'F'.

* Merchant Circle is drawn with the diameter "F" & it is passing through the tool point.

coreff of friction (m):-

when the Chip slides der the tool face under pressure, there will be some friction b/w these two. Therefore Kinemanic Coreff of friction Can be expressed as

m= P/s = tand

shear angle (B):tand = rcost I-rsind

Chip-thickness gatio (r):-



ti=) Docut chip thickness t2=) Chip thickness which was cut. Frictional force (P) & Normal force (N):- (28)



P= F2 Good + F2 sind N = F Coso - F Sind F= Resultant force  $= \sqrt{F_2^2 + F_2^2}$ 

8-1

Shear Resisting force (F3) & Back-up force (Fn):-



 $F_{A} = F_{2} \cos \beta - F_{2} \sin \beta$  $F_{A} = F_{2} \cos \beta + F_{2} \sin \beta$ 

Cutting force (Fz):- $GS(p-a) = \frac{r_2}{F}$  $F_2 = F \cos(y-d)$ Fr GSD = FA $F = \frac{F_3}{\cos \theta}$ 8=2-0+8 Substituting F' in Fz equation  $F_z = \frac{F_3}{\cos \theta} \cos (p_d)$  $F_{z} = \frac{F_{3} \cos(\nu - d)}{\cos(\nu - d + \beta)}$ La eff of friction (M):-M= tand = P/J M= Fz Sind + Fz Cosd

F2 cosd -F2 Sind

- by cosd,





Shear Stress, T = Shear force = Frs Afrea As

Sinp=	A	=)	As =	A		
	AS		64	Sinp		

$$T = (F_2 \cos \beta - F_2 \sin \beta) \sin \beta$$
  
A1

Shear 
$$Z = \frac{F_2 \cos \beta \sin \beta - F_x \sin^2 \beta}{A_1}$$




the above figure shows the velocity heletionship in orthogonal cutting. The Varians Velocities are

Cutting Velocity (v)
 Chip Velocity (vc)
 Shear Velocity (vs)

* The chip velocity is the velocity of chip relative to the tool & is directed along the tool

face.

* Shear velocity vs is the velocity of chip relative to the w/P and is directed along the shear place.

$$SinB = \frac{Ac}{OA}$$
  
 $Ac = OASinB$   
 $Ac = VSinB$ 

$$\cos (R-\alpha) = \frac{Ac}{AB}$$

$$\therefore Ac = V_{c} \cos (R-\alpha) - (2)$$

$$V \sin B = V_{c} \cos (R-\alpha)$$

$$ChiP$$

$$Velocity$$

$$Vc = \frac{V \sin P}{\cos(P-\alpha)}$$

$$Vc = \sqrt{9}$$

$$(r = \frac{\sin \beta}{\cos(P-\alpha)})$$

Similarlys

Fron ODAS

$$(\cos d = \frac{\partial D}{\partial A} = \frac{\partial D}{\nabla}$$

$$(\cos d = \nabla \cos d) = \frac{\partial D}{\partial B} = \frac{\partial D}{\partial B}$$
From  $\partial DB$ ,
$$(\cos (B - d)) = \frac{\partial D}{\partial B} = \frac{\partial D}{\nabla A}$$

$OD = V_D \cos(B-\alpha) - (33)$
From (BRA), VCOSA = V1 COS(R-A)
Shear Velocity Vis = Vlosa Velocity
Formulae used in metol cutting:-
O chip thickness gatio, g = ty = lay = Sinp (1) color thickness gatio, g = ty = lay = Sinp
3 chip reduction co-efficient, K=1/2
3 shear angle, B= tan I [ rcosd ]
€ co-eff of friction, M = tand = %
(5) Friction force, P= Fz Sind + Fz 6050
Wormel force, N= Fz. Cosx - Freshol
Shear force, F3 = Fz cosp - Fz Sing
a back-up force, Fn = F2 cos B + F2 SinB
Shear smess, $T = \frac{F_3 \sin \beta}{A_1} = \frac{A_1 \rightarrow Ahea of}{A_1}$
Uncut chip

(a) Cutting force, 
$$F_Z = F \cos(p-d)$$
  

$$= \frac{F_3 \cos(p-d)}{\cos(p-d+R)}$$
(b) Feed force  $F_X = F \sin(p-d)$   

$$= \frac{F_3 \sin(p-d)}{\cos(p-d+R)}$$
(c) Velocity of this  $V_c = \frac{V \sin R}{\cos(R-d)}$ 
(c) Shear velocity  $V_A = \frac{V \cos d}{\cos(R-d)}$ 
(c) Shear strain,  $e = \cot R + \tan(R-d)$   
(c) Shear strain,  $e = \cot R + \tan(R-d)$   
(c) Shear in  $= \frac{W \cos d \cos R}{\cos(R-d)}$   
(c) Shear in  $= \frac{W \cos d \cos R}{\cos(R-d)}$   
(c) Shear strain,  $e = \cot R + \tan(R-d)$   
(c)  $F_z + V = (F_S \times V_A) + (P \times V_c) - (N-m)$   
(c)  $F_Z + V = (F_S \times V_A) + (P \times V_c) - (N-m)$ 

(4) Masterial Grendral J [M.R.R.) (35) gate for turning [M.R.R.) = [Feed in mm/sher) × [Definin] × [Cutting speed in mm/sher) × [in mm/min] - mm3/min (5) Machining (Cm) = 2B+J-d constant (Cm)= In metal cuttings Feed in myley = vncut chip thickness? = ti Depth of cut = Width of cut. M.R.R is defined as the Volume of material

neaded from the workpiece Per Unit time. It is measured in terms of mm³/min. problems on metal cutting:-

1) During an orthogonal turning opreation of C20 steel, the following date were recorded Rake angle = 10°; Chip thickness = 0.48mm; width of cut = 2.0 mm; Feed = 0.25mm/ trev;

Tayentel custing force = 1200N; Feed thrush force = 300 N; Cutting speed = 2.5m/s;

Find the Value of shear force at the shear Plane; find also the Kinematic coneff of friction at the chip-tool interface.

Given Dara!_

d= 10°; t2=0.48mm; b= 2.0mm; f= 0.25 mm/ner; Fz= 1200 N; Fx = 300N;

V= 2.5m Sec;

To find !-Fs =? M=?

shearforce, Fg = Fz cos B - Fz Sin B (aleft of ) M= tan N = 1/N = frictional force friction ) M= tan N = 1/N = Mormal force

Shear anyle (B):-  

$$B = +an^{-1} \left[ \frac{r \cos d}{1 - r \sin a} \right]$$

$$Chie + hickness r = \frac{t_1}{t_2}$$

$$= \frac{0.25}{0.48}$$

$$F = -\frac{0.25}{0.48}$$

$$B = +an^{-1} \left[ \frac{0.5208 \times \cos 10}{1 - (25208 \times \sin 10)} \right]$$

$$B = 29.41^{\circ}$$
Shear force (FG):-  

$$F_3 = F_2 \cos \beta - F_2 \sin \beta$$

$$= 1200 \cos (29.41) - 300 \sin (29.41)$$

$$F_3 = 898.03 \text{ N} - Ans -$$
Functional force (P):-  

$$F = F_2 \sin 4 + F_2 \cos 4$$

= 1200 (Sin 10) + 300 ( 6510)

P= 503.82N 38
mormal force (N):-
N= F2 Cosd - F2sind
= 1200 costo - 300 Sinto
= 1129.67 ~
Co-eff of friction (m):-
$M = \frac{9}{15} = \frac{503.82}{1129.62}$
m= 0.44 _Am_
Friction angle (2):-
M= tand
$: \nu = + an^{-1} (m) = 24.03'$
-d - d - d - d - d - d - d - d - d - d
2 In an orthogonal cutting test with a tool
of gake angle log the following observations were
made
chip thick ness sharts =0.3
Horizonal component of cutting force = 12gon
Vertical component of cutting force = 1650N

From Merchant's thory, calculate the Various components of the cutting forces and the confficient of friction at the Chip-tool interface.

Given Dare :chip mickness mario, r= 0.3 Horizontal component force, Fz = 1290N Vertical component Cuting force, Fx = 1650 N Find !frictional force (P)=? wormal force (N)=? Shear force (F3)=? Back up force (Fn)=? co-eff of friction (m) =?

Same as the previous problem.

(3) In an orthogonof cutting opnearion on a workpiece of width 2.5mm, the Uncut Chip thickness was 0.25mm and the tool stake angle way zero degree. It was observed: that the Chip thickness was 1.25mm. The cutting force was measured to be good and the thrush force was found to be 810 N.

(i) Find the shear angle & shear strength (ii) If M= 0.5, what is machining constant (m=)

given :-



width, b= 2.5mm; Uncut Chip thick, t, = 0.25mm; Chip thickness, t2= 1.25mm; Rake angle, x= 0; Cutting force, F2 = 900N; Thrush force, Fx = 810N; co-eff of friction, M=0.5 Find'-Shear angle, B=? Shear Strength, T=? Machining constant, Cm=? soln:-Chip thickness statio, 12 11 = 0.25 = 0.2; D shear angle, B= tan-1 [rcosk] (2)= ten 1 0.2 Coso R = 11.31 Ans-Shear Strength (Z):-Z= FJ xSin B A, = Ahea of uncut AL= bxt1 A1 = 2.5 × 0.25 mm2

Shear force 
$$F_{3} = F_{2} (os \beta - F_{2} sm \beta)$$
  

$$= 900 (os(11.3i) - 810 sin(11.3i))$$

$$F_{3} = 723.66 H.$$

$$T = \frac{F_{3}}{A_{1}} \times sin\beta$$

$$= \frac{723.66}{(0.25 \pm 2.5)} \times sin(11.3i)$$

$$[T = 227.07 H]mn^{2}]$$
Machining Constant,  $C_{m} = 2\beta \pm y - d$ 

$$= ton^{-1}(0.5)$$

$$y = 26.56^{\circ}$$

$$T = 49.18^{\circ}$$

Tod signatures

Tool angles given in a definite fattern is called "Tool Signature". The Tool angles have been Standardized by the American Standards Association (ASA). As per ASA, the tool signature is given by the following order.

(i) Back Rake angle
(ii) Side Rake angle
(iii) End relieft angle
(iv) Side relieft angle
ev) End cutting edge angle
(vi) Side cutting edge angle
(vi) Side cutting edge angle
(vii) Nose gradions.

example: - A tool having \$\$, 5, 5, 6, 6 and 1 as signature in ASA system will have

> Back grake angle =8' Side hake angle =8' End grelieft angle =5' Side grelieft angle =5' End cutting edge angle =6' Side cutting edge angle =6' Nose Radiany = 1mm.

8. Orthogonal Test in conducted on mild steel tube of Size 225mm diameter and 5mm thickness. The velocity of cutting is losm and feed make is 0.21 million The following observations were made 43 cutting force = 2300 N; Feed force = 825 N; chip twick ness = 0. Imm; Rake angle = -10"; Determine the Shear Strain and energy for whit volne. Given:-D=225mm) += 5mm; V= 105m min; F=0.21mm |nev; Fz = 2300 N; Fz = 825 N; tz = 0.3 mm; d= -10' Soln'_ Chip tickness statio, r= +1 = 0.21 = 0.7 D B = ten [ rcosk ] = 31.57 shear angle, 3 Shear strain, e= cotp + tan (B-d) = 2.513 3 œ shear velocity, vg = vcost = 105 cos(-co) (os(R-d) cos[31.57-(-w)]  $V_{3} = 138.2 \text{ m}/\text{min}$ (5) Shear energy = Txrs Unit volume vxsings Shear stress 761.67 × 158.2 losx Singlist = 1914.87 N/mm2

(9) Mild steel is being machined outmoponally & the following results are obtained cutting force = 1000001; Feed force = 625 m; cutting velocity = 165 m/min; eake argle = 10'; (4) sheer argle = 19';

Determine the following (i) Shear Velocity (ii) Chip flow Velocity (iii) work done Fermin in shearing the metal and work done against friction (it) show that the work input is equal-to som of work done in shearing and against friction. Given:-

Fz= 1000N; Fz= 625N; V=165 m/min;

x=10'; B=19'

Find: v, v, w, wy, wf

Jhear velocity, V3 = rcost = 164.5 m/min

2) Chip: Velocity, Vc = VSinB Cos(B-d) = 54.38 m/min

3) Shear force, Fg = Fz cosp - Fz SinB

F1 = 742N

(4) work done in shear,  $W_3 = F_3 \times V_3 = 742 \times 164.3$  $Q_2 = 122 \times 10^3 N - M m^3 n^3$  -: WA = 2033.33 watts

S Frictional force, P= F2 Cosd + F2 Sind P = 789.15N

(6)

(7)

8

Work input,  $W = F_2 \times V$ = 1000 × 165 = 165000 N-m/min =  $\frac{165000}{60} = 2750 \text{ wattp}$ W = 2750 wattpWS f WF = 715.23 f 2033.33

Hence Proved. (b) while turning a cis steel had of 160mn die at 315MPM, 2.5mn depth of cut and feed mate of 0.16 mm (grev by tool geometry 0,10,8,9,15,75,0, the following observations were made. Tangential conforment (Fz) of the cutting force = 50000 Radial component (Fz) of the cutting force = 50000 Radial component (Fz) of the cutting force = 20000 chip thickness = 20040

(c) Dhaw Schematically the merchant's circle diagram for the cutting forces in the Presencase. (b) Determine the dynamic yield Streight of the

Given'-

Phesens work material.

D= (born; N= 315hm;

depth of cut = width of uncest chip

feed note = trickness of uncut chip [t] = 0.16 m

Rake angle, d = 0° [from tool geometry]

F2 = 500 -> F2 = 2001

chip thickness, the = 0.48mm;

Soln:-

Dynamic yield Strength, T= FJX Sin P A,

where B= Shen angle, A = Alea of Uncut chip

Fy = Shear force

O Chip thickness natio (r)! $r = \frac{t_1}{t_2} = \frac{0.16}{0.68} = 0.33$ (2) Shear angle (B):-B= ton -1 [ r cost ]= 18.43 3 shear force (FS):-FO= F2 COSB -F2 Sing F3 = 411~ () yield smergen (Z):- $T = \frac{F_3 \times SinF}{A_1} = \frac{44 \times Sin(18.43)}{b_1 \times F_2}$ 

 $= \frac{411 \times \sin(18.43)}{2.5 \times 0.16}$ 

T = 324.92 N/mm2

During machining (20 Steel with a conside authing tool having a tool feamenry given by 48 0-5-6-6-8-75-1mm ORS, the following forces have been recorded by a two dimensional dyna mometer: cutting force = 1300 ~ read force = 800 N Find O Frictional force (2) Normal force (3) M Here Rake angle, d= 5" 12) The following data from an orthogonal cutting test is available Rake angle =15' Chip thickness patio = 0.383 vacut chip thickness =0.5mm width of cut, b= 3mm; yield smess of material in shear = 280 mbm2 Average coneff of friction on the 2 = 0.7-tool face ] = 0.7-Determine the normal & tangemial forces on the tool face

Given:-  

$$d = 15'$$
;  $r = 0.383$ ;  $t_1 = 0.5mm$ ;  
 $b = 3mm$ ;  $T = 280 \text{ N/m}^{2}$ ;  $\mu = 0.7$   
Find!-  
Tangential force  $(F_2) = ?$  normal force  $(F_2) = ?$   
Soln:-  
 $\beta = +an^{-1} \left[ \frac{r \cos x}{1 - r \sin d} \right] = 22.3$ :  
 $T = \frac{F_3 \times \sin \beta}{A_1} = 280 \text{ N/m}^2$ ;  
 $F_3 = 1105 \cdot 63 \text{ N}$   
 $\mu = 0.7$  (4:ven)  
 $\mu = +an^{-1}(m) = 25$ :  
Tangential force (or) cutting force  $(F_2)$ :-  
from DAB:  
 $Cos(\nu - d) = \frac{F_2}{F}$   
 $F_2 = F \cos(\nu - d)$   
 $F_3 = \frac{F_2}{F}$   
 $Cos(\nu - d) = \frac{F_2}{F}$   
 $Cos(\nu - d) = \frac{F_1}{F}$ 

$$F_{2} = \frac{F_{2}}{\cos(\nu - d_{4}R)}$$

$$= \frac{1105.62}{\cos(35 - 15 + 22.2)}$$

$$F = 1494.83 \text{ M}$$

$$(utting force, F_{2} = F \cos(\nu - d))$$

$$= 1494.83 \cos(35 - 15)$$

$$F_{2} = (404.68 \text{ M}) - \text{Ans}$$
Feed force (F_{4}) (or) mormed force :-  

$$F_{2} = F_{2} - F_{2}2$$

$$= \int 1494.83^{2} - 1404.682$$

$$F_{2} = 5(1.26 \text{ M})$$

Tool Life!-

* It is defined of the interval of time for which tool works satisfactorily blu two consecutive he sharpenings (grindings).

* Tool life is used to calculate the tool material performance and machinability of the workpiece material.

- * Tool life can be expressed in the followings way.
- r Time period in minutes blus two consecutive gresharpenings.
- ~ Number of Components machined b/w two Consecutive Grindings
- Volume of material grenoled blue two Consecutive Grindings.

Tool life in terms of Volume of material stemotral!-

WKT Volume of material Z = TIDN tf mm3/min genoved/min J = TIDN tf mm3/min

where

52 D - will diameter in ma t - Depth of cut in mm f - feed note in ma gev N - NO of Alvolution [ min If Tool life (T) in minutes, then total volume of material ? Memoved for tool failure ) TDN+fT mm3 (091) = (Vx1000) tfT Volume of material hereded ... Tool life(T) = for Tool failure (V×1000)tf Factors affecting the cutting Tool life !-(a) culting speed (b) feed & Depth of cut (C) Tool Geometry (d) Tool material (e) work material (f) nature of cutting

(9) Rigidity of mic tool & work (b) cutting fluids

(a) Cutting speed :-

* Major factor affecting the tod life.

* It Varies inversely with the tool life which leads to the generation of Parabolic Curve.

(53)

* the helption blue the tool life and cutting speed is invented by F.W. Taylog & hence Sometimes this equation is called as

" Taylon's too life equation".

 $VT^{n} = C \qquad T \qquad V$  V-Cutting Speed(m/min) (m/min)where T- Tool life Tool life(7) -> C - Constant n - Tool life index, which depends on (b) Feed & Depth of cut: (b) Feed & Depth of cut: (ceramic tooly) Infortant fore meter affecting the tool life * They are inversely proportional to tool life.

$$V = \frac{257}{T^{0.19} \times f^{0.36} \times t^{0.8}} m/min$$

54

V can also expressed as  $V = \frac{c}{f^{a} \times t^{b}} = \frac{f^{-} - feed in mn}{f^{-} - pepth of cut in mn}$  C = Congtant.

a, 6 - Constant which depends on mechanical properties of workpiece material.

(C) Tool Geometry: -* Tool angles of the Cutting Tool affect the tod performance by Tod Rife. * If the take angle is increased in a Positive distections then the Cutting force and heat generation is greduced which increases the tool life whereas if it is too large, then it meduces the mechanical strength of the tool and hence tool life.

- + Hence the take angle should be in between -s to tio where - sign indicates
  - Negative rake angle (55)
- * Relief (or) clearance apple are used to prevent the stubbing of the tool flank against the wIP & if it is too large, weakening of the tool occurs. Generally it Varies from 5° to 8°.
- * Cutting edge angles also affect the tool life in the Similar way. Hence it is kept in between 5° to 8°.
- * Nose gradious increases the abrasion which helps in improving the surface finish tool strength & hence tool life

(d) Tool material!-(5) * Tool material which can with stand maximum Culting temperature without losing its mechanical Properties & geometry will ensure maximum Tool life * Hence higher the mechanical properties ( mainly hardness and toughness) in the tool material, longer be the tool life. (e) work material! -Higher the handness of the work material, Greater will be the tool wear and hence Shorter tool life (f) Nature of Cutting :-* Tool life is also affected by cutting nature (ie) whether it is continuous (on) intermittent. * In continuous cutting, the tool life is

mone than the intermittent cutting.

(3) Rigidity of the n/c tool & work: - (57)

* M/c Tool & W/P both Should Genein Gigid while machining operation.

* If they are not Rigid, then Vibrations are developed and hence Cutting tool will be subjected to intermittent cutting instead. of Continuous cutting and hence tool life will be shorter.

(f) Cutting fluids:-

* for efficient performance of the opreation, Cutting fluids are used. * Cutting fluids greduces the heat blue the tool & the work, greduces the friction, improves surface finish, helps in grendval of Chips & heree increases the tool life. The Taylorian tool-life equation for mechining C-40 Steel with a 18:4:1 H.J.J culting tool at a feed of 0.2 mm/min and a depth of cut of 2 mm is given by VTⁿ=c, where n and c are constants. The following V and T observations have been noted.

> V(n|min) 25 35 (58) T(min) 90 20

calculate !-

() n and c

(ii) Hence recommend the cutting speed for a desined tool life of 60 minutes.

Soln:- $V_1 = 25 \text{ m/min}; V_2 = 35 \text{ m/min}$ 

Ti = gomin; T2 = 20min;

Taylor's equation: -  $VT^{2} = Constant$  $: <math>V_{1}T_{1}^{2} = V_{2}T_{2}^{2}$   $25(9)^{2} = 35(20)^{2}$  $\binom{90}{20}^{2} = \frac{35}{25}$ 

$$(4.5)^{2} = 1.4$$
  
 $\log 4.5 = \log 1.4$   
 $n = \frac{\log 1.4}{\log 4.5} = 0.223$ 
  
 $\int \log 4.5 = 0.223$ 
  
 $\int \log 4.5 = 0.223$ 
  
 $\int \log 4.5 = 0.223$ 

Constant, 
$$C = V_1 T_1^n = V_2 T_2^n$$
  
 $C = 25 (90)^{0.223}$   
 $C = 68.19 - Ans - 1000$ 

During Straight turning of a 24mm diameter steel bar at 300 g. P.M. with an H.S.S. tool, a tool kife of 9 min was obtained. when the Same bar was turned at 250 g. P.M. the tool life increased to 48.5 min what will be the tool life at a Speed of 280 J. P.M?

 Givenin
 Diameter of bar, D = 24mm; Speed of bar, N = 300 r. P.M;

Tool life, Ti = 9 min

Speed of bon N2 = 250 h.P.m; Took life, T2 = 48.5 min;

Find!-Tod life T=? when N=280 A.P.M

Soln:-() speed in m/min (v):-For NI = 300 9. P. mg VI = TD NI m/min  $V_1 = 22.61 \, \text{m/min}$ sor N2 = 250 9. P.ms V2 = 18.84 m/min

For N= 2809. P.M. V= 21.11 m/min

(1) To find n and c in Taylor's equi-  
Taylor's equi- 
$$VT' = C$$
  
 $: V_1 T_1 = V_2 T_2^n$   
 $(22.61)(q) = (18.84)(48.5)^n$   
 $(\frac{q}{48.5}) = \frac{18.84}{22.61}$   
 $(0.1855)^n = 0.8232$   
 $n \log (0.1855) = \log (0.8332)$   
 $i = 0.1833$   
 $constant, c = V_1 T_1^n$   
 $= 22.61 (q)^{0.1083}$   
 $Constant, c = V_1 T_1^n$   
 $= 22.61 (q)^{0.1083}$   
 $Constant, c = 28.68$   
 $VT^n = c$   
 $21.411 (T)^{0.1083} = 28.68$   
 $T = 16.93 min$ 

A cutting Tool when used for machining who 2 at a cutting speed of 50 m/min lasted for 100 minutes Taking n= 0.26 in the Taylor's tool life equation, determine (1) the life of the tool for an increase in cuting speed by 25% (2) The cutting speed to obtain a tool life of 180 minutes. Soln:-V= 50 m/min ; T= 100 min; 1=0.26 VTn = constant (Toylors eqn) 50 (100) 0.26 = 165.56 C= 165.56 () Took life (T) when V=1.25 (50)!-V= 62.5 m/min 62.5 (7) = 165.56 T= (165. 56/62.5) %.26 T= 42.38 min 2 cutting Speed (v) when T=180 min:-V (180)0.26 = 165.56 V= 42.91 m/min

( The following equation for Took life is given for a turning oppearion

VT 0.13 f 0.77 0.37



A 60 minute tod life was obtained while cutting at V=. 30m[min, f=0.3mm[hev; d=2.5mm

Determine the Charge in Tool life if the cutting Speed, feed, and depth of cut are increased by 20%. Individually and also taken together

VT -13 f 0.77 d 0.37 = c 30 (60) [0.3] (2.5) = C C= 28.37

O Tool life if v is increased by 20% :-

Soln:-

: 36  $(T)^{0.13}(0.3)^{0.77}(2.5)^{0.37} = 28.37$ 

(2) Teol life if fin in creased by 20%. :f = 1.2 (0.3) = 0.36 mm | here

Surface finish :-

65

Generally, Surface finish of any component produ -ced by making depends on the following main factors.

> a) cutting speed b) feed c) Depth of cut d) M.R.R.

a) cutting speed !-

* It is defined as the grate at which the cutting edge of the tool passes over the surface of the wip in unit time.

* It is expressed in m/min.

If the cutting speed is too high, then the tool gets overheated & the cutting edge may blunt quickly which affects the surface finish.

* At the same time, if it is too low, then relating time is more & hence productivity decrease b) Feed!-

It is defined of the distance travelled by the tool along (or) into the WIP for each Pass of tool Point.

If seed shall be within centain range to get a good Surface finish. 66) () Depth of cut !-* It is the Penetration of the cutting edge of the tool into the material of the will, which is measured it to the machined surface. Depth of cut = D-d 2 * If the depth of cut is highly it will affect the Surface finish of the will. d) M.R.R :-* It denotes the volume of material henoved per vnit time.

M.R. E = feed x depth of cut + velocity = f x t x V mr 3/min
Machinability:-



"The ease with which the fiven material can be worked with cutting tool is "Machinability"

when it is stated that the material 'P' is more machinable than material 'Q', it means that * Less power is required to machine material

"P! * Less tool wear is obtained with material" P! * Better surface finish can be achieved with material "P!

Parameter affecting the machinability :-

* cutting speed, feed & depth of cut * Tool material. \$ | * Tool Geonetry. * Cutting fluid * cutting Type [Intermittent (or) continuous]

work piece material Upriables

* Handness of the material

* Chemical composition of material

* Tensile Strength

- f Strain handening
- * Shape & Size of the UP.
- * Rigidity of the w(P.
- General criteria for evaluating the machinability are as follows.

68)

1. Tool fife !-

Longer tool life at a given cutting speed indicates better machinability.

@ surface finish:-

Better the Surface finish, higher is the machinebility

3) Power consumption:

If the power consumption is low, it indicates better machinobility.

( cutting force! -

Lesser the cutting force for removing the material, higher is the machinability.

5 Shear angle :-



× 100%

Larger shear angle gives better machinability.

Machinability Index!-* It is used for comparing machinability of different material.

M. I = Cutting speed of metal for 20 min of tod life Cutting speed of standard free cutting Steel for 20min of-tool life

Cutting Tool material: [P. no: 71]

characteristics that the tool material

Should have

(3) Toughness

1) Hot handness

(2) wear resistance

( Cost & easiness in fabrication

Types of cutting Tool materials: [P. no: 71] 1) Carbon steels (2) medium alloy steels 3 High speed steels (H.S.S) (4) Stellites (5) Cemented Carbides (6) Commits (7) Diamonds (8) Abrasilles. (79) Cutting fluids: [P. no: 76] Purpose !-1) To cool the tool & w/P 2) To Inbricate & neduce friction 3) To improve Surface finish ( To protect the finished Surface from Corrosion (5) To cause the Chip break up into Small Parts To worsh away the Chip from the tool.

properties of cutting fluids:-

7)

High heat absorption Good Indricating qualities  $\binom{2}{2}$ High flogh point 3 () Nentral () odourless 6) Hamless to the Skin of the opreators 7 NON-CORRASIVE to the work (Tool | machine (8) Transparency 9 Low Vincosity () Low cost. choice of cutting fluid!-() Type of opreation (2) M.R.R. (3) naterial of w/P & Tool. @ Surface finish requirement. (5) Cost of cutting fluid. Types of Cutting fluids:-() water (2) soluable oils (3) Straight oils Mixed oil 5 Solad Lubricants etc., (4)

where heat is generated.

Amound Shear Zone
 Tool - Chip Interface
 Tool - U/P Interface



1) Shear zone :-

* called os " primary deformation Zone" in which

Shearing of the metal (or) playtic deformation of the metal takes place.

* Heat produced in this zone is carried by the Chip & workpiece 2 Tool- Chip Interface! _

* called of "Secondary deformation zone" inwhich the heat is generated due to the friction between the Chip & tool face.

* The Heat produced in this zone is carried by the Chip & the tool.

3 Tool - W/P Interface !-

* This is the contact Agree byw the flame face of the tod & the workpiece.

* Here, the heat is generated due to the friction 5/w the flank face of the tool & the workpiece

* when the cleanance angle is not Sufficiently provided on the tools the heat generated in this Afrea will be more. Tool failure !-

If the tool is not giving the satisfactory performance, then it is an indication of the "tool failure" which causes the following adverge effects.

* Poor Surface finish of the w/P.

* High power consumption.

* Inconnect work dimension

t overheating of the cutting tool & the workprece

The main causes of the failure of the tool are as follows.

(a) thermal cracking & So Ftening

(b) Mechanical Chipping (c) Tool Wear (c) Tool Wear (c) Tool Wear (c) Chank Wear (c) Chemical Wear.

(a) thermal cracking & softening!-

* During metal cutting, high heat is generated at the cutting edge & the tip of the tool. Due to thiss plastic deformation takes place at the cutting edge to the tool tip. Due to this, the tool cutting edge & its tips will become soft & it will lose its cutting ability. This is known as "softening". (75)

* Sometimes, due to the high heat, there may be a chance of the Cracks which is developed on the cutting edge of the tool. This is known as "thermal cracking".

(b) Mechanical chipping:-

It denotes the breakage of the tool nose due to the high cubting pressure, Mechanical impact, excessive wear & high Vibration etc.,



Tool wear :-

Sometimes, when the tool is in use, it will loose its weight, which means it has lost some material from it due to wear which are of the following types.

(i) Crater Wear:-



* The dephession on the tool face is known os " crater wear". This type of wear takepplace during mechining of ductile material inwhich Continuous Chip will be formed.

* The main cause for this depression (or) creter is due to the pressure by the hot chip sliding on the tool face.

in Flank Wear :-* The flank face Portion below the cutting edge is the Region where an appreciable amount of wear occurs. * "Flank wear" is due to the abrasion blu the tool flank face & the wP. * this type of wear mainly occur when machining brittle material. Flank wea , iii) Chemical wears_

* This type of wear occurs when a cutting fluid used is chemically reactive.

* Dive to third, the Chemical Preaction takes place b) the cutting Tool & cutting fluid & the crossion takesplace on the cutting tool.









Head Stock Mechanismi-

- 1) Back Geared Head Stock
- 2 All yeared Head Stock.

Back Geared Head Stock :-



[Lock Pin Engaged] []

-----

3



Tumbler Gear Reversing Mechanism



⊕

ħ,













Follower Rest

steady Rest













orming !-



11

(Recessing, undercutting, necking)



Square Groat



Rand Grooke

Bevelled Groove

T





Spinkle speed
 = ½ (speed of turning)
 Slow cross-feed.







02



(a) form tool method (b) Tailstock set over method (C) Compound Rest method (d) Taker turning Attachment method (e) by combining feeds.

(a) Form Tool Method !-



(C) Tail Stock Set der method!-Carch Live WP 600 camer Feed D-> Max. taper Die d - Min topper Dia over) R= D-9 XL = 1 -> Taper length . tand L- ) Length of w/P d -> Helf toper angle (d) Taker turning by giving combined feed !-Agular # Resilian [ combination of Cross & Regituding fead]



Thread cutting! -(16) Hend Stock Spindle Lead Sere. formula for calculating the change steels (years) :-Dhive teeth lead Screw special Pinch of Screw to be cur 0 Spindle speed Driven teeth Pitch of the lead Sure In English measurements theread Arr inch [t.P. ] of W/P. Driver teeth 2 Priver teets thread Farinch [t. P. 1] of Leadscreek Heres pitch -No of thread inch







* So, the custing of metric twend on a lathe with a English leaf screw may be carried our by introducing a traslating year of 127 teets.

Simple and Grand Gerrain:



Simple (per train



Often engine Lattre are equipped with a set of Georg raying from 20 to 120 teets in a Stepsof. 5 teets and one year with 127 teets

## Problem:-

I the pitch of a head screel is bom & the pitch of the thread to be cut 1 mm. Find charge years

> = Driver teeth = Pitch of work Driver teeth = Pitch of lead sized

$$=\frac{1}{6}=\frac{1\times20}{6\times20}=\frac{20}{120}\left[\frac{1}{100}\right]$$

So, Driver year Should have 207 & Driver year Should have 120 teeth

(19) 2 Pitch of Lead Screw - 6 mm and Pitch of thread to be cut is 1.25mm. Eind the change needy Soln:-

Daver	teeth	2	pitch e	f work	1.25
Driven	teath		Pitch of	lend sure	6

$$=\frac{1.25\times4}{6\times4}=\frac{5}{24}$$

$$= \frac{5\times5}{24\times5} = \frac{25}{120} \begin{bmatrix} 5:mple & Geor \\ +moin \end{bmatrix}$$

$$(ar)$$

$$= \frac{5 \times 1}{6 \times 4} = \frac{5 \times 10}{4 \times 10} \times \frac{1 \times 20}{6 \times 20}$$

$$= \frac{50}{40} \times \frac{20}{120} \left[ \frac{A}{B} \times \frac{1}{3} \right]$$

: Driver ARC = SOT & 20T

187 B

Driven BXD = AOT & 1207

3. It is required to cut a Screw having 7mm pitch on a lattre having a lead scred of 4 threads Per inch. calculate years.

$$\frac{Dniver + eetn}{Dniver + eetn} = \frac{560}{127} = \frac{140}{127}$$

$$= \frac{70 \times 2}{127} = \frac{70 \times 2 \times 20}{127 + 20} = \frac{70}{127} \frac{40}{20}$$

Steps involved in thread cutting opreation: -

O Remove the excess material from the usp to make it ) diameter equal to the major diameter of the thread.

21)

- (2) Change georg of correct size are then fitted by the spindle and the lead screw.
- (or) form of the thread.
- (F) For a metric thread, the included angle HJ. the cutting edge of the tool is 60'.
- (5) The nose of the tool should be set at the Same height as the center of the u(P.
- ( A thread tool gauge is usually used against the turned surface to check the cuting tool So that each face of the tool is equally inclined to the centerline of the workpiece



- (7) The speed of the spindle is neduced by (2) One-half to one-fourth of the speed negwined for turning according to the type of maxemal being machined.
- The Deam of cut which usually Varies from 0.05 - 0.2 mm is applied by advancing the tool It to the axis of the work (or) at on anyle equal to one-half of the angle of the thread and 30' in case of metric twead by Suivelling the compand rest. Different Methods of Applying Depthof cut







Applying Depm of cut I to the latter axis by cross-slide

Applying Doom of cut inclined to the axis by compound rest

(9) Alfter the tool has produced "helical Grooke" who the end of the work, this is quickly witholdown from the cross-slide and the tool in brought back to the starting position to pive a fresh cut.

- Before piving a freshout, it is necessary to ensure that the tool is at the starsing point of the thread. Otherwise the job will be spoiled. Several cuts are necessary before the full depth of thread is reached.
- (1) Making the tool being at the start point of the thread when the fresh cut is given is called "Pick-up of thread".
- Based on the "Pickmp of thread", Thread Cutting methody can be classified of
  - () Thread anoting by reversing the m/c (2) Thread anoting by Manning the lathe Farts (3) Thread anothing using Chasing dial (or) Thread indicator (4) Thread indicator

() Reventing the mic: -

After the end of one cut, the tod is brought back to the starring Position by reversing the machine keeping half-nut fermanently engaged. This method requires considerable time.

2 Marking the lathe Parth:-Marking lead Screw, Gear wheely starring Position of the corriage on the bed.

Using charing diel (or) thread Indicator !-3 comoje Die O chosing did (or) thread Indicator consists of a work gear which is in mesh with a lead screw. 8.1.1-1.1. 2 With a worn Geor amached a vertical shaft connecting the dial gampe. worm year (3) when the lead screes natates, the deal gauge will also gotate. ( By using this, the store Point of the to-1 can be easily Referre Point identified.

( Thread cutting by using thread chaser -



K Work O A chater is a milti Point tureading tool having the Same form and Pitch thread of the thread to be choser chased.

> ( It is Used to finish a paroly cut thread to the Size & Shape Dequired

3) Thread Charing is done 1/2 to 1/2 of the speed of the turning.

Classification of threadrs:-O Based on the standards

1 whitworth [ British Standard]

Depth = 0.6403 XP

Angle = 55' to the Lathe axis

2 Bhitish Association [BA]

Depm = 0.6 XP

Angle = 47.5'

3 Metric thread [ISO]

Max  $DePth = 0.7035 \times P$ M.A  $Depth = 0.6855 \times P$ 

Angle = 60°

## ( ACME [ American Standards] ()

Height of thread = 0.5P + 0.254 mm Angle = 29

3 Based on the pitch of the lead screw & work

1) Even thread

- Pitch of work is an multiple of the Pitch of Lead Screw. 2 Odd thread

> - pitch of work is not an multiple of pitch of Lead screw.

3) Based on the thread Position

SHHHHHS

@ Single Stars & Multi-Stars twreaded screw

Single Start threaded Screw:-

Right hand & Left hand thread

For one complete turn round the screed, if there is a molement of one thread, the screw is called single start turnead. * "Lead" is the distance a screw thread advances along its axis in one turn. (27)

* So, In single storm thread, Lead = Pitch

Mufti-Start thread !-

* For one complete ting when there is a move -ment of more than one thread it is called multi Start thread.

* In case of, say, a ture-Start thread, for one complete turn, the thread advances three time as if it was a single thread.

Application:-(D) House hold fancet's & taps (2) Milk bothles & vater bothles (3) Medicines. etc. Driver Geor Lead of the work Driver Geor Pitch of the Lead Scient


It when cuting Right hand thread, the carriage

* For Left hand thread, the Corriage must make away from the Head stock and towards the tail Stock.

* The job moves as always in anticlarwise direction when viewed from the tail Stock.

topered Surface Whing tope Thread cutting ana turning Attachment :-29 Porte Motion Halt anyte of toper 20 Bad MIC Spindle compound nest 81 4444 Lead Screed Gear train Movement of cross-slide compound year Movement of corrige checking a screw cutting set up! 1) The Gear train must be correct. 2) Tumbler years must give the comiage the in the gright divection 3 The spindle should be arrayed to five nequired has custing steed. I The feel shaft must be disengaged The appron feed mechanism must be an neutral 5 Finally Half-out must be exaped to 6 the lead Screw.

SPECIAL Atto. chments:-1) Milling Attachment: @ For cutting grooves & key ways w|P - cross slide; Milling cuter-Chuck Depth of cut - Provided by Versical Slide in the Attachment. ( For cutting multiple grootes & year wheels :wip - held blu certers; Attachment - Cross-slide; [ Brixen by separate motor] No of Groovey - by notating the work gear - Universal Dividing head attached to near end of the Spindle 2 grinding Attachment !-* Abrasive wheel called as "Grinding wheel" work - bli centers for external * Grinding. + work - chuck (or) face plate + Depth of cut - by moving cross-slike

Calculation of Machining time & power for cuting :-3.) Formulaely Turning oprestions 1) cutting seed, V = TDN m[min V - cutting speed in m/min D - Dianere of whe in mm N- Rotational speed of will in mem. 2 Diameter of whe D = DitDa in m Di - Max (or) Blank Diameter De - Dinneter after making (or) Minimum Danese of up 3 M/cing Time for Single Pass, t= L+20+4 min L= Length of Job Lo = over travel beyond the length of the job to help in setting of the tool in mm 4 = Tool Approach Dissonce in m f = feed state in multer ~ = Rotational Speed in hem. 4) Power required for cutting, P= Kxdxfxr watts

Material being cut K (N(mm2) Steel, 100- 150 BHN 1200 Steel, 150-200 BHJ 1600 Steel, 200- 300 BHA 2400 Steel, 300-400 Bard 3000 Cast Iron 900 Brass 1250 Sponze 1750 Aluminium 700

K= Constant depending on the work mal

d = depen of cut in m; f = feel name in m [nev; v = cutting speed in m [sec]

Probler :-

Au-May-2012

32

A Blank 180mm long and 70mm diameter is to be machined in a later to 175mm long and bomm diameter. The workpriece Protected at 450 51. P.M. the feed is 0.3 mm [mer; and the maximum depth of cut is 2mm. For turning opreation, the approach plus over tracked distance is 6mm. Alsuning that the facing oriention is done after the turning, Calculate the machining time. Soln:-(fiven:-Legeth & w|P; L = 180mm; Dir of blank, Di = 70mm; Dir of ulp after mechining, Dz = bomm; The feed rate, f = 0.3 mmforev Depth of cut, d = 2mm; Approach f over travel (Lo-ELI) = 6mm;

> Die of will  $\mathbf{P} = 70m$ ; Length of Tool  $\frac{1}{2}$ ,  $L = \frac{1}{2} + (Lo+Li)$ travel  $\frac{1}{2}$ ,  $L = \frac{1}{2} + (Lo+Li)$

> > = 35 + 6 $\left[ L = 41 \text{ mm} \right]$

cross reed note for facing is not Given

So, Assume, f= 0.3 mm (ner;

Soln:-

Maing time for turning opening

MICing time, to L+ Lo+4 fri

minutes

$$N = \frac{1000V}{RD} \quad from = 450 \ N.P.M$$
  

$$N = \frac{1000V}{RD} \quad from = 100 \ A.S \ N.P.M$$
  

$$Maching \ time } t = \frac{180 + 6}{0.3 \ X45.}$$
  

$$\frac{1}{100} \quad from \ time \ for \ facing \ organized = 3}{000 \ Rass} \quad for \ ore \ Rass$$
  

$$Micry \ time \ for \ facing \ organized = 3}{Derm of \ cup}$$
  

$$t = \frac{L}{fri} \quad minutes$$
  

$$L = \frac{10}{2} \ t \ (L0 \ 4Li)$$
  

$$= \frac{16}{2} \ t^{6} = 36 \ mm$$
  

$$\therefore \ t = \frac{36}{0.32 \ H50} = 0.84 \ minutes$$
  

$$N = \frac{1}{6} \ Rass \ required = 3$$
  
No of Rass \ required = 3
  
No of Rass \ required = 3
  
No of Rass \ required = 3
  
Total micry time   
for one Rass   

$$I = \frac{100}{100} \ for \ cup \ for \ one \ Rass \ for \ cup \ for \ one \ Rass \ for \ cup \ for \ micry \ for \ cup \ for \ cup \ micry \ for \ cup \ for \ cup \ micry \ for \ cup \ micry \ for \ cup \ for \ cup \ for \ cup \ micry \ for \ cup \ for \ cup \ for \ cup \ for \ cup \ for \ for$$

Formulaes :-····· [Di-D]/2 Dependent(d) Number of passes neguired = (4) Di - Mar (or) Blank die (mm) D2 - Minimum Dramerier (mm) Totel Machining time = [M|cing time for] ~ [no of Parsey] Single Pass) ~ [nequired] 5 ( For facing opreation Diameter of w/P= Dia of blank diameter (or) .D.a of finished will Length of rool travel = D/2 + (Lot4) (LotLi) = Approach + der travel Problem !- 2

Estimate the ectual machining time required for a component shown in figure: The available Spindle speeds are 70, 110, 176, 280, 440, 700, 1100, 1760, and 2800. Use a roughing speed of 30m/min and finish speed of bom/min the feed for roughing is 0.24 mm/nev, while that 36 for finishing is 0.10 mm/nev. The maximum depth of cut for roughing is 2 mm. Finish allowance may be taken as 0.75 mm. Blank to be Used for machining is 50 mm diameter



Soln:-

Shock to be hereaved =  $\frac{50-42}{2} = 4$  mm Finish allowance = 0.75 mm

Rough: np!-

Roughing Stock = 4 - 0.75 = 3.25mm

 $\therefore$  NO of Passes =  $\frac{3.25}{2} = 2$  Passes

Given cutting speed, v= 30 m/min

: Spindle Speed N= 1000×30 = 207.599.PM

Meanest rpm from the (:st, N= 176 r.P.M

 $M_{c}$  time for one Fass =  $\frac{120+2}{0.24\times176} = 2.898 \text{ mm}$ 

Fin: shing!

(37



1. Hexagonal turnet 2. Index place 3. Bevel year 4. Indexing retchet 5. Turnet Spindle 6. Beveled Finion 7. Indexing Paul 8. Screw type Stop had 9. Lathe bed 10. Can II. Pinion Shaft 13. Player pin Up. Player 15. Pluger Spring.

Bar feeding Mechanismi-

Turnet Indexing Mechanism



Tool Layour !-

Planing of Sequence of oppeation & preparation of turnet & capsion Lathe as per the Sequence of oppn to be carried out on the work

It includes three stages.

Preparation of opreation sheet (or)
 Process planning sheet.
 * component drawing
 * sequence of oprin
 * selection of Tool
 * selection of V, f, d for each oprin
 * Tool Travel legeth
 Tool layout

3 Tool Sequence Cham

Feed depth of cut, cutting speed for Various oprim:

3.00	OPreather	Mild steel			Aluminium			
		۷	7	1	V	4	9	V. m
<b>1</b> .	Plain turning	50	0.10	2	200	0.10	2	\$-m
2.	som turing	40	0.05	-	200	0.05	_	d - m
3.	thread curry	7	0.05	2:	7	0.05	2	-
4	Drilling	40	0.05	-	200	0.0	-	

Dhaw the tool payour for manufacturing knucked B Screw and nut as shown in figure on a turnet lathe



Joln:-

Stope:-1 [ Preparation of oppression sheet] 1. The component drawing is obtained 2. The total length of the work is calculated & 14mm is provided for clearance 4++4 = Cleanarce for paring tool 6 = cleanarce for chuck & paring 3. Number of oppression is fisted.

- 5. Material Mild Steel.
- 6. Tool is selected & Tool length is a dissed by stopper

Stage: - 2 [ Tod - hayour]

Tool fayour is drawn as shown in figure

Front tool post of crass -slide Stage:-3	- Cress A B C Tool Schedling	slike 2 2 y cha		ションと	A A A	
5 5	Machines- Moterial Mild S	turner ) teef	athe			
openation Sequence	Description	Tool Fosition	Tools	V	+	d (mm)
۱.	Holding the prequired bar in the collet & Setting the prequired length of 52 mm [ 35+14+3]	Turnet Position	Bar Stop	-	-	-
2.	Turn to lomm dia to a length of \$60mm from slipht and	Front Tool Post [Aosition] A	Turning teol	50	0.1	2

OPreation Sequence	Desciption of opheation	Tool Position	Tools	V MA	+	3
З.	Turn to smedie & from the highwend of the bolt for a Senten of 26.5 mm	- Turnet Position 2	Roller Steady: box Turningtool	50	0.1	2
4.	Facing the right end to a length of 1.5mm	Front Tool Post+ (Position A)	Turning tool	50	0.1	aş
5.	Externel turead autring of som die to a length 23mm from the sight end	Turnet Restition 3	Self opening die head with thread Chaser	7	0- 05	8
6.	knulige on the required legan	Rurret Position A	Knowling tool	7	0.05	0.57
A 8 9	chanfering the bolt head Chanfering the end Parring off the bolt	Front Tool Ret B A Rear Tool Abbr	Chamfering Tod (Form Tod) Turning tool Parring off Tool (In inverted Position)	40 50 40	0.05	2
10	sacing the hight lide of the nur to 1.5 mm	Front Tool Page Rosation à'	Turring tool	50	0.1	0-9
'tı-	Drilling the nut	Registion 15:	Drilling Tool	40	0.05	-

deretter Sequence	Descuption of operation	Za-1 Rospin	Tady	v	F 4
12	threading by Top	Pesition'6	Topping Tool	40	0.05 -
13	Parsing off the	Rear Tool Rogt	Permiyoft	40	0.05 -
	ant	Teol Post	201	40	0.05



1, 11, 11, 11, 11, 1, 11 - Spindles 1, 2, 3, 4, 5, 6 - Cross slides







Comparison of Single Spindle & multi spindle Anto Lather

12	Single Spindle	multi-spindle
1.	one spinelle	2, A, S, 6 (or) & Spindle
2.	only 1 w/p machined at a time.	no of workpieces machined at a time.
3.	Production mate is low	High
*	Accuracy is high	Lover.
5.	Tool Setting time is less	More
۶.	Tooling case is loss	more
7	It is more ecromical for shorter as rell as forger runs	It is note economial for longer much only.
8.	The time required to Produce one composed is sun of the times operection times.	Time of honfers cut in any spindle
۶.	Tools in three are indexed.	action type)

Comparison blus Parallel Action & propressive multi spudle Late:-

Progressive Action st Parallel Action machine Machine 00 Different opins on jobs Same oppeations 6. one after the another in all sandles In one cycle, no for every indexing of component, 2. of components produced one component is produced. simboreasly is equal to no of sp. nolley 3. Pare of Productioning Moderate. high 4. It Anyoning goos wrong The Production is in one station, the completely affected in Production is ther an Station. Particular Station 55 only affected. Small Parts of Simple 5. Parts of complicated snapes are produced. Shapes

Unit-I

SHAPER, MILLING & GEAR CUTTING Machines

Introduction !-

The shaper is a Reciprocating type of machine tool intended primarily to produce flat Surfaces. These Surfaces may be horizontal, Vertical (or) inclined.

2 Feed of a shaper is measured in terms of mm | stroke. It is defined as the movement of the cutting tool (or) workpiece per stroke of the cutting tool.

(3) The cutting type of a shaper is a intermittent type as the cutting tool cuts the workpiece periodically during its stroke.

classification of a shaper:-

O According to the type of mechanism used for giving reciprocerting motion to the rem a) Crank type b) Geared type c) Hydrauliz type (2) According to the position of the vertical of the ram a) Horizontal type b) Vertical type c) Travelling head type

According to the molement given to the table
 a) Standard Shaper b) Universal shaper
 According to the type of cutting stroke
 a) Push type b) Draw type.

Crank Shaper:-

This is the most common type of shaper in which a single point cutting tool is given a speci proceeting motion equal to the length of stroke desired while the work is clanped on an adjuste -ble table. This shaper enploys a Crank mech -onism to change a Circular motion of a large geor could "bull gear" incorporated in a machine to seciproceeting motion of the sam. The bull gear seceives power from an electric motor. Geored type:-

Here, the neciproceting motion of the fram

is obtained by a shack & pinion. The shack teeth which are cut below the sam mesh with a spur Geor. This type of shaper is not widely used. 3

3 Hyd naulic shaper: -

Here, the reciprocating motion to the fram is obtained by Hydraulic Power. Oil under high Phessure is Punped into the hydraulic Cylinder fitted with a piston. The end of the Piston hod is connected to the fram. The high Phessure oil first acts on one side of the Piston and then on the other causing the Piston to Reciprocate and the motion is transmitted to the fram. The piston speed is changed by Varying the amount of liquid delivered by the pump.

Advantages of a hydraulic Shaper: _

() It offers Great flexibility in speed control. (2) It Eliminates shock by Permitting slowingup of motion when the cutting tool is overloaded, thus protecting the parts (or) the tools from breakage.

3) The machine does not make any noise and opreates very quietly.

( Horizontel Shaper:-

In a horizontal shaper, the ham holding the tool reciprocates in a horizontal axis. This shaper is mainty used to produce flat surfaces.

( Vertical shaper: -

In a Vertical Shaper, the Sam holding the tool speciprocates in a Vertical axis. It may be crank driven, shack driven (or) hydraulic driven. The work table of a Vertical Shaper can be given cross, longitudinal & shaper can the tool used in a Vertical Shaper is entirely different from Horizontal Shaper. Vertical Shaper is very convenient for mechining

e) Internal Surfaces Such as Keyways, Sbts (or) Grookes.

b) Large Internal & external Georg by indexing arrangement of Rotary table @ Travelling head shaper:-

In this shaper, the sam carrying the tool while it reciprocates moves cross-wise to give the sequired feed.

5

(2) Heavy jobs which are Very difficult to hold on the table of a standard shaper and fed past the tool are held on the basement of this shaper while the Sam Deciprocates and supplies the feeding movements.

7) Standard Shaper:-

A shaper is termed as standard (ar) Plain when the table has only two movements for table. Overtical feed @ Horizontal feed.

( Universal shaper:-

In Universal Shaper, in addition to the two movements provided on the table of a Standard Shaper, the table can be swivelled about an axis parallel to the ham ways and an axis perpendicular to the fram ways. As the work nounted on the table can be (6) adjusted in different planes, the machine is most suitable for different types of work and is given the name " universal". A universal shaper is mostly used in tool from work

9 Push type shaper:-

this is the most general type of shaper used in common practice. Here, the metal ig hemoved when the ham moves away from the column (ie) Pushes the work.

that is, here forward stroke is a cutting stroke and the return stroke is an idle stroke.

(10) Draw Cut Shaper:-

In this Shaper, the metal is hendled when the sam moves towards the column of the machine, ie) draws the work towards the machine. Here, the forward Stroke is an idle stroke and the stetum stroke is a cutting Stroke Here, the tool is set in a neversed diffection to that of a standard shaper.
(3) Here, the nam is generally supported by an overhead arm which ensures nipidity and eliminates deflection of the tool.

( In this Shaper, the cutting Phessure acts towards the column which relieves the cross-hail & other bearings from excessive loading and allows to take deep cuts. Vibration in these machines is practically eliminated.

Quick neturn mechanism!-

In shaper, the ram moves at a comparatively slower speed during the forward cutting stroke whereas during the neturn stroke, the nam moves at a faster speed to neduce the idle neturn time. This is called as " Quick neturn motion" and the mechanism used to obtain this is called as " Quick neturn mechanism". Generally there are 3 types of Quick Neturn mechanisms used in a shaper. They are (3) a) Crank & slotted link me chanism b) whitworth Quick Stetum mechanism c) Hydraulic mechanism.

Principle of shaper:-

In Shaper, the metal is cut by the Pleci -Procating movement of the cutting tool over the workpiece which is fixed on the table. The following feeds are available in a Shaper.

1) cross feed :-

It denotes the movement of the table Perpendicular to the nam movement Per stroke of the cutting tool. It is obtained by moving the saddle over the guide ways of the cross-shail.

2 Verted feed :-

It denotes the movement of the table in a vertical direction per stroke of the cutting tool. It is obtained by moving the cross-frail over the Vertical guide ways of the column by notating the elevating screw (or) by moving the tool head Vertically by notating the down feed Screw. The Vertical feed of the shaper is used to produce Vertical plane Surfaces. (9)

3 Angular feed :-

It denotes the movement of the cutting tool in a Vertically Angular diffection Per Stroke of the cutting tool. It is obtained by first tilting the tool head to the grequired angle & then teeding the cutting tool in a Vertical diffection by gotating the down feed screw. The angular feed is used to produce angular surfaces.

Note:-

the angular feed & the Vertical feed of a Shaper is given only after tilting the apron to some angle. This is done to give the clearance blue the cutting tool & the work piece to avoid the studing of the cutting tool with the work piece during machining.



1) Down feed handwheel @ Swivel Base 3) clapper box. 1) Down feed handwheel @ Ram Locking handle @ Ram 1) Tool Head (8) Table (7) Table Support (10) Elevating Screw 1) Cross-hail (12) Paull& Ratchet mechanism (13) Feed dise (14) Driving Fulley (15) Base (11) Afthon clamping bolt

Fig 3.1 - Construction of a Shaper

Construction of a shaper:-A shaper consists of the following principal Parts.

1) Base 2) column 3) Cross-rail (4) Saddle (5) Table (6) Ram (7) Tool Head 1) Base:-

It is necessary bed (or) support Required for all machine toold. It may be highly bolted to the floor (on) on the bench according to the size of the machine. It is so designed that it can take up the entire load of the machine and the forces set up by the cutting tool der the work. It is made of cast Iron to Resist Vibration and take up high compressive load.

(2) column:-

It is a box like casting mounted upon the base. It encloses the som driving mechanism. Two accurately machined guideways are Provided on the top of the column on which the sam speci procates. It has two Vertically machined guideways on its front face, which serves as the guide ways for the cross-shail for its Vertical movement. The other side of the column contains levers, flandles etc., for operating the machine. 3 cross-shail:-

It is mounted on the Vertical guideways of the column. It has a accurately machined Guide ways on its top, which is perpendicular to the ham axis. The table may be given a vertical feed by notating an elevating screw. A Horizontal cross feed screw which is fitted within the cross-hail and parallel to the top guide ways of the cross-hail actuates the table to move in a cross-wise direction.

12

## 4 Saddle:-

The saddle is mounted on the cross-shail which holds the table firmly on its top. Cross wise movement of the saddle by notating the cross-feed screw by hand (or) power causes the table to move sideways.

5 Table !-

The table which is bolted to the saddle speceives cross wise and Vertical movements from the saddle & cross-shail. The table has T-slots both on the top and sides for clamping the work. In a universal shaper, the table can be tilted about on axis parellel to the sam ways and an axis perpendicular to the sam ways. 6 Ram :-



The Ram is a preciprocating member of a Shaper. This is seni-cylind sical in form. It Slides on the accurately machined dove-tail guideways on the top of the Column and is connected to the seciprocating mechanism contained within the Column. It houses a screwed shaft for altering the Position of the sam with suspect to the work and it holds the tool head at its front end.

(F) Tool head :- [ Refer figure 3.2 in P. no: 15] (1) The tool head of a sharper holds the tool rigidly , provides the Vertical and angular feed movement of the tool and allows the tool to have an automatic relief during ity return stroke.

The Vertical slide of the tool head has a swivel base which is held on a circular seat on the gram. The swivel base is graduated in degrees, so that the vertical slide may be set Perpendicular to the work surface (or) at any desided angle. By notating the down feed screw handles the Vertical slide carrying the tool executes down feed (or) angular feed movement while machining Vertical (or) angular surface. The amount of feed (or) depth of cut may be measured by a micrometer dial on the top of the down feed screw.

(3) the Aption consisting of clapper box, clapper block & the tool post is clamped upon the Vertical slide by a screw. By Releasing the aption clamping screw, the aption maybe swivelled either towards right (or) left with respect to the Vertical slide. This arrangement is necessary to provide relief to the tool while making Vertical (or) Angular cuts.

The two Vertical wally on the a Phon called clapper box houses the clapper block which ig connected to it by means of a hinge Pin. The tool post is mounted on the clapper block. on the forward cutting stroke, the clapper block fits securely to the clapper box to make a grigid tool support. On the greturn stroke, a slight frictional digag of the tool lifts the chapper block out of the chapper box a sufficient amount Preventing the tool cutting edge from dragging & consequent wear. The work surface is also prevented from any damage due to dragging.



feed direction

Fig 3.2 - Tool Head of a Shaper
SHAPER MECHANISMS !-

In a Shaper, notary movement of the drive is converted into the reciprocating motion of the nam by the mechanism contained within the column of the machine.

(2) In a Standard Shaper, the metal is hendled during the forward cutting stroke and the neturn stroke is an idle stroke as no metal is nemoved during the neturn stroke.

3) To reduce the total machining time, it is necessary to reduce the time taken by the return Stroke.

I thus the Shaper mechanism is so designed

that it can allow the nam holding the tool to move at a conparatively slower speed during the forward cutting stroke whereas during the neturn stroke, it can allow the nam to move at a faster nate to neduce the idle neturn time. This mechanism is known as "quick neturn mechanism".

5 There are 3 types of quick geturn mechanism used in the shaper.

Crank & slotted link mechanism
 whitworth quick setum mechanism
 Hydraulic drive mechanism

Crank & slotted link mechanism

the motion (or) Power is transmitted to the bull gear through a pinion which receives its motion from an individual motor through a stepped cone pulley b belt drive (or) a set of Gear train. Speed of the bull gear can be charged by shifting the belt to various pulley in case of belt drive (or) by various gears in case of Gear drive.



Bolted to the center of the bull geor is a stadied slide which carries a sliding block into which the crank pin is fitted. Rotation of the bull gear will cause the crank pin to state at a Uniform speed. Another Sliding block is also there into the slot provided in the slotted link (on) Rocker arm. It is fitted to the sliding block

in the Radial Slide by a crank pin. The rocker orm is pivoted at its bottom end and is attached to the frame of the column. The upper end of the rocker arm is forked & connected to the sam block by a pin. As the bull gear notates, the Crank pin will notate on a Crank pin Circle. As the sliding block is connected with a crank pin, it also grotates along crank pin circle, which will give the spocker arm a stocking movement. As the rocker arm is connected to the ram by ram blocks the sam gets a seciprocating motion from the slocking movement of the slocker arm. Thus the gotary motion of the bull pear is converted to the neciprocating movement of the Ram.

To get quick geturn motion from Crank & Slotted link mechanism:- [Refer 3.4 on Page 90! 2]

From figure 3.3.3, it can be understood that when the link is in the Position PM, the han will be at the extreme backward position of its stroke & when it is at PN, the extreme forward Position of the fram will have been reached. PM& PN are tangent to the Crank Pin (20) circle at the extreme position of the forward be Return stroke. The forward cutting stroke takes place when the Crank pin rotates through the apple Cikc2 and the neturn strake takesplace when the crank gotates through the angle C2LC1. It is evident that the angle C,KC2 made by forward (or) cubling strake is preater than the angle Cell, made by the neturn strake. As the angular velocity of the crank pin is constant, the geturn stroke is completed within a Shorter time.

cutting time =	Angle of CIKC2
Return time	Angle of C2LLI

Cutting time to Return time Pratio usually Varieg between 2:1 and 3:2. From the figure 3.3.2, it can be understood that, the cutting speed ig minimum at the extreme Position of the Pan & is maximum when the Procker arm is Vertical. The only disadvartage of this method, cutting speed and Return speed is not congrant throughout the Stroke.





O Position of the sliding block ② Center of bull gear
 ③ Shorter Crank Pin Circle ④ larger Crank Pin Circle
 A→ Shorter Stroke length
 B→ Larger Stroke length

The Stroke length of the ram can be adjusted by moving the bull gear Sliding block towards (or) away from the center of the bull gear. The bevel gear (1) is placed at the center of the bull gear. It can be notated by a handle. When the bevel gear (1) is notated, the bevel gear (2) will solate causing the lead screw to notate. Thus the bull gear sliding block which engages with the

lead screw can be moved towards (or) away from the center of the bull gear based on the diffection of notation of the lead screw. The closer the crank pin is brought to the censer of the bull fear, the Smaller will be the crank gradious and hence the Smaller will be the stroke legath. The forther the crank pin is brought away from the center of bull gear, the biffer will be the crank hadions & hence the larger will be the Stroke length. Maximum Stroke legeth is obtained when the Crank Pin is shifted towards the forthest end of the slide

Adjusting the position of the stroke: [see Fig: 3.3]

Inside the ran of a Shaper, there are screwed shaft, Ran block, Beved gears. The Position of the 9mm with respect to the work piece can be adjusted by notating the screwed Shaft of the ran. For rotating the screwed Shaft of the rang first the clamping lever for the 9mm block is loosened & then the fever for the bevel gear is notated. Now, the screwed Shaft Starts notating. As the ran block which acts of a nut is a 24 stationary one, the sam of the shaper will move forward (or) backward with respect to the sam block based on the dispection of station of the screwed sheft. Thus the Rosition of the sam with steppect to the workpiece is adjusted.



Fip: 3.7

Figure 3.7 illustrates the arrangement (25) of Various elements in whitworth quick neturn mechanism. The sheft of an electric motor drives the pinion which rotates the bull gear. The bull gear has a sliding black which is fitted on the bull year by a crank pin. The slotted crank plate is eccentrically pivoted on the bull gear at point "S" the sliding black in the bull gear slides into the slot of the crank plate. A connecting god connects the crank plate by a fin at P on one end and the gram at the other end M. when the pinion gotates, the bull pear is also notated along with the sliding block which slides into the slot of the Crank plate. It makes the have to move up & down [Reciprocating motion] by the Connecting Rod.

position of the Creak Pin 'A' :-

O when the Crank pin A is at Xy the Sam will be in forward Stroke. At that time, the bull pear States in the Anti Clock wise direction at an apple"d". (2) when the bull gear rotates further in the same direction from y to x at an angle of B, the return stroke will take place. Here, the angle of B is less than d. So, the time taken for the return stroke is reduced.

Reason for making the stroke length greater the work piece length in a horizondal shaper:- 2 Mark () To allow Sufficient time for giving cross-feed. (2) To allow Sufficient time for the clapper box to attain its Proper Seat for cutting. (3) To allow the Sam for obtaining the Proper cutting speed. (4) To allow the Subbigs of the tool on the

work Surface during the Acturn Stroke.

To obtain the good Surface finish. 5



() oil Reservior (2) Oil Pump (3) Throttle Valve (*) Ran (5) Cylinder (6) Piston Rod (7) Piston (8) Reversing dog (9) Reversing lever (6) Reversing lever Pivot (1) Relief Valve (2) Diffection Control Valve.

O In a hydraulic shaper, the sam is moved forward & backward by a piston sod attached with a piston which is moving inside a hydraulic Cylinder placed inside the sam.

2 this mechanism consists of

3) constant oil discharge rump.

(a) Hydraulic Cylinder (28)

(3) The Position of the DCV is changed by a reversing dog at the end of each stroke. At one Position of DCV, the oil flows through the Piston side of the Cylinder making forward Stroke of the Stan taking place. At another Position of DCV, the oil flows through the Piston Rod of the Cylinder making the Steturn Stroke of the Stan taking place.

(P) The purpose of oil pump is to suck the oil from the reservion & discharge it to the cylinder through DCV at high pressure

(5) The volume of the cylinder in the Piston Rod side is less than the volume of the cylinder in the Piston Side. So, when the some amount of oil flows through the Piston had side, the phessure developed will be comparatively high, which in turn increases the speed of the sum during the stetum stroke. Thus, the quick Return motion of the Ram is achieved.

( The speed of the fram can be increased (0, 1) decree sed by controlling the amount of oil discharged to the tank. This is done by adjusting the throttle volve. When the oil flows through one side of the cylinder, the oil in another side of the cylinder will be discharged to the tank through the throttle Volve For example, when the throttle Value 13 Partially closed, the speed of the cylinder will be reduced. At the same time, the outlet pressure will be increased. In this time, the helief value will open and discharge excess oil to the tank, thus maintaining the constant Phessure in the System.

Advantages of the Hydraulic drive :-

1. The cutting & return smoke speeds are practically constant throughout the stroke. This permits the cutting tool to work uniformly during the cutting Stroke The Neversal of the ham is obtained quickly without any shock as the oil on the other end of the cylinder provides cushioning effect. 30
Flexibility in obtaining Various cutting speeds.
The helief Value ensures safety to the tool & the machine when the machine is overloaded.
The opreation is Smooth & Silent.

Feed Mechanism:-

O Hand feed -> Angular feed by the tool head mechanism > Vertical feed for the table > Horizondal (at) cross -feed for the table

2 Auto-feed -> Horizondol (or) Cross-feed for mechanism the table.

Unlike lathe, the feed mole means in a shaper are provided intermittently & is given at the end of veturn stroke only.

Hand feed mechanism for the table of the shaper:-Vertical Guide ways Table - Cross-mail K of the column cross-feed screw Bevel Georg Base Horizondal god Base Elevating Screw

1) Vertical Hand feed :-

When the horizonal rod is rotated by a Key, the Power will be transmitted to the elevating Screw through a set of bevel gears. The Rotation of the elevating screw make the cross-hail of the Shaper move along the Vertical Guide ways of the Column, thus giving the Vertical feed to the table. (a) Horizondal (or) cross feed by hard:when the cross-feed Screw is rotated by

a keys the cross-feed screw will notate. The

Solution of the cross-feed screw make the 32 Saddle move along the horizondal flat guideways of the cross-shail, thus giving the horizondal cor) cross feed to the table of the shaper.

Pin (2) Spring opreated _ Helical spring plunger -Paul Retchet wheel T-slot Cross **>**Ø ; -Dhiving feed. Disc Screw _ Center of Crank damigedisc e Rocker Connecting Nor god Rocker

Arm connecting pin (1)

The above figure illustrates the automatic cross-feed mechanism of a shaper. The driving disc is connected to the bull gear. So, when the bull gear notates, the Driving disc will also gratate. The driving disc has a T-slot along

its diameter. The one end of the connecting had is connected to the driving dige eccentrically by a crank pin. The other end of the connecting had is connected to the bottom end of the vocker arm by a Pinci). The nocker arm is (33) ful crumed at the center of the ratchet wheel which is Keyed to the cross-feed screw. The top portion of the Mocker arm has a spring opreated pawl which is straight on one side and slant (or) Bevelled on the other side. The Pawl is into the space between the teeth of the ratchet wheel. when the driving disc solutes through half of the nevolution in a clockwise dinection, the nocker top Portion arm starts rocking in a clockwise dinection as it is connected with the driving disk by connecting God. During the clockwise direction of the nocking army the pawl in the nocker arm just slips over the the teeth of the natchet wheel imparting no movement to the table of a Shaper. When the driving disc notates through another half in top Portion a clockwise direction, the nocker arm will start

nocking in the Anti Clock wise direction. In this conditions the straight side of the pawl engages with the teeth of the rotchet wheel & notate it. In the notchet wheel is keyed to the cross feed screw, cross-feed screw will also notate when the notchet wheel notates. Thus, the cross-feed is given to the table automatically. this cross-feed is given during the networks.

The following Points is worth noted. diffection of the O To neverse the cross-feed of the table, the Prin(2) of the nocker arm is lifted from the slot & notated through 180° so that the Position of the famil is reversed & the Pin is again put into the slot. Now, the direction of Auto cross feed is neversed.

2 The anount of cross feed may be altered by shifting the Position of the Chank Pin with nespect to the Center of the driving disk. Greater the throw of Eccentricity, more will be the Jocking novement for the nocker arm and the Paul will notate three (or) four teets on the natchest wheel at a time in Parting greater feed (35) movement.

Work holding devices of a shaper:-

The top & sides of the table of a Shaper have T-Slots for clamping the work. The work may be supported on the table by the following methods depending on the nature of the w/p.

() clamped in a Vise

2) changed on the table

3 clamped to the angle plate

@ clanged on a V-block

(3) Held between the centers.

1) shaper vises !-

* A vice is a quick method of holding and locating grelatively small & gregular shaped workpieces.

* It consists of base, screw, fixed

and movable jaws. # The base has a projection (or) tongue which fits into the Slot of machine table. # For properly securing it to the table lugs are provided for Clanping the Vice by T-bolts. # The work is Clanped b)w the fixed & movable jaws by a screw.



A machine vice is classified into 3 types 37

Switch vice
 Driversal vice

Plain vice:-

It is the most simple of all the types. The Vice may have a single screw (or) double screws for actuating the movable jaw. The double screws add gripping strength while taking deeper cuts (or) hardling heavier sobs

Swivel vice:-

In this vice, the base is graduated in degrees and the body of the vize may be Swivelled at any desired angle on a horizontal plane. The Swivelling arrangement is useful for machining horizontal bevelled Surface of the workprece.

Universal vice:-In this vice, the body of the vice can be Swivelled on a horizontal plane like a swivel vice In addition to that, the body can be tilted in a Vertical plane up to go" from the horizontal plane. It is used for Vertical Angular machining. (38) Parallels:-

* Parallels are Square (or) rectangular bars of Steel (or) Cast Iron which is handened and ground with opposite sides Parallel. * when the height of the job in less than the height of the jaws of the Vice, Parallels are used to graise and seat the work piece above the jaws. * Porallels are available in Various Sizes

tor seating the workpiece of different heights and are always used in pairs.

Hold-downs:-* Hold-down is a hardened wedge shaped piece with the taper angle of 5: * Hold-downs are placed blue the two is aws of vice & the work piece. * It is used for holding this pieces of work in a shaper vise. It is also used for holding the work of smaller height than the vice jaws where Suitable Parallels are not available.

3 clamping work on the table:-

when the workpiece is too large to be held in a vise, it must be fastened directly on the shaper table. The different methods employed to clamp different types of work on a shaper table are

O T-bolts & clamps

2 Stop Pins

3 stop pins & toe dops

( Strip & Stop Ping.

O T-bolts & clanes:-



() step-block 2 T-bolt 3 chanp () work Figure illustrates the use of T-botts and clamps for holding the work.
T-bolts having are fitted on the T-Stots of the table. The length of the threaded Portion is sufficiently long in order to accomplate different heights of work.

- * The clamps are made of steel having slots at the center for fitting the bolt. One end of the clamp rests on the side of the work while the other end nests on a block.
- * To hold a large work on the table, a series of clamps and T-bolty are used all gound the work.

2 Stop pins:-





O Body @ screw

* A stop pin is a one leg screw clamp * It is used to Prevent the work to get pushed out of its Position during forward Cutting stroke of the tool.

* The body of the stop pin is fitted in the hole (or) Slot on the table & the screw is tightened till it forces againgt the work.

(3) stop pins & toe dops:-

* while holding the thin work pieces on the table, Stop ping in conjuction with toe dops are

used

* A top dop in similar in shape to that of a center punch (or) cold chisel. The head end of the top dop is dhilled slightly so that the end of the stop pin screw may fit into it. (4)





(4) strip & stop Ping !-

It the above figure illustrates the working of Strip & stop pin for holding the work.

* work having Sufficient thickness is held on the table by Strip & Stop Ping.

* A strip is a long bar having a tongue with holes for fitting the T-bolts.



- * For holding 'L' Shaped work piece, angle plates are used.
- * Angle Plates are made of cost Iron & hos two plane Surface bent at angle of go?. One of the sides of the Angle plate is fitted on the table of the Shaper. Another Side of the angle Plate hold the 'L' shaped work piece by bolt & nut.

* For Rolding Yound nodn, V-blocks are used. * work may be supported on two V-block at two ends & M clanged to the table by 7-bolts & clangs.





* This is a special attachment for cutting equally spaced Grooves (or) splines on the Periphery of the sound work. It may be also used for cutting georg.

* After cutting each Grooke on the Cylindrical workpiece, the Crank of the index plate will be notated donp a selected hole circle to a predetermined arount so that the peripheny of the will is equally divided.

* Here, the work is held blu the centers by means of catch plate & Dog carrier.

Shaper opreations:

A shaper is a Versatile machine tool primarily designed to generate a flat surface by a Single point cutting tool. But it may also be used to perform many other operations. The different operations which a shaper can perform are as follows

- ( Machining horizontal Surface ( Machining Vertical Surface
- 3 Machining angular Surface
- (4) Cutting slots, Grooves & Keyways.
- (5) Machining irregular surface
- ( Machining Splines (or) cutting georg.



* The above figure illustrates machining horizontal flat surface on the w/P.

* Procedure for making horizontal flat Surface on the wip

I After the work is properly held on the table, a planning tool is set in the tool post with minimum overhung.

2) The table is haved till there is a Cleanance of 25mm to 30mm between the tool of the workfield. 3 the length by the position of the Stroke are then adjusted.

2) the length of stroke should be nearly 20mg fonger than the work

b) The Position of the stroke is so adjusted that the tool beging to move from a distance of 12 to 15mm before the beginning of the cut and continues to move 5 to 8mm efter the end of cut.

(F) Proper cutting speed & feed in then adjusted. (5) then the depen of cut is given by govering the down feed screes.

- () Then the shaper is switched on The cross feed is given at the end of return stroke.
- 7 Both noughing & finishing cuts are performed

to complete the job.

Note:-

Tor rough cuts cutting speed is decreased while feed & depth of cut is increased.

for wough work }=) 1.5 to 3mm



on the table.

- 3) The surface to be machined is carefully aligned with the axis of the ham.
- A side cutting tool in set on the tool past and then position, keypty of stroke is adjusted.
   The vertical slide is set exactly on zero angle position.
- ( The apron is Swivelled in a direction away from the Surface being cut. This is necessary to enable to move upward and away from the work during the return Stroke. This also Prevents the side of the tool from dragging on the planed

Vertical Surface during the neturn Stroke. (1) Then the machine is switched on. At the end of neturn Stroke, down feed of about 0.25mm is given by trotating the down feed Screw. (8) Both noughing & finishing cuts are performed to complete the job.

- Steps involved in machining of Angular Vertical
- O Fig: 2 illustrates the machining of Angular Vertical Surface.
- (2) The work is set on the table and the Vertical slide of the tool head is Swivelled to the hequired angle either towards Right (or) left from the Vertical Position.
- (3) Then the appron is suivelled away from the work. (F) Then the machine is switched on. The Angular down feed is given at the end of the neturn strake by notating the down feed Screw.
- ( Angular machining can also be machined in a Universal shaper (or) by using Universal vice without Swivelling the tool head.

(3) cutting sbts & keyways:-





( Vise 2 Tool 3 WORK

Cutting External keyway

1) Tool bit 2 work 3 Vise.

cutting Internal keyway

(50)

Cutting External keyway 1) For cutting slots (or) keyways, a square nage tool Similar to the Parting tool is selected.

2 External keyway are cut on a shaft by first doubling a hole at the blind end of the keyway. The dianeter of the holes Should be 0.5 to 0.8 m oversize that the width of the keyway and the depth Should be about 1.5m larger than the depth of the keyway. This is necessary for the cleanance of the tool at the end of the neturn Stroke

(3) The length & Position of the Stroke is carefully adjusted So that the Stroke will terminate exactly at the cleanance hole. The speed is reduced while cutting a keyway.
(5)
Cutting a Internal keyway:

D Internal keyways are cut by holding the tool on a Special tool holder so that the tool post will not hit againgt the work at the end of the Stroke. (2) Clapper block is locked in the clapper box to prevent the tool from lifting during the Stetura Stroke.

3 Lubrication is necessary on the work to Phevent the cutting edge of the tool from wear due to dhapping.

Marchining Irregular Surface!

(i) a convex (or) concave (or) a combination of any of the above Surfaces.
2 To Produce a Small contoured Surface, a forming tool is used. 3 If the curve is sufficiently large, power cross-feed in conjuction with manual down feed is so adjusted that the tool will trace the Required Contour. ( If the contour has too many ups & down, both of the feedy are operated by hand. A gound nose tool is selected for machining integralow surface. 5 For Shallow cut, the appending be set Vertical. But if the curve is quite sharp, the apponing Swivelled towards Right (or) left away from the Surface to be cut. The following figure Shows mechining of concave surface using a gound nose tool.





Here, After each footh is Cut, the crank of the index plate is moved to a pre-determined amount along a selected hole circle so that the workpiece will be equally divided. Here, a formed tool is used for cutting floors (or) SHAPER SPECIFICATIONS:- Splines on the Shaft.

Maximum length of stroke 0 Maximum cross-wise molement of the table 2

- (3) Maximum Vertical adjustment of the table
- @ Type of driving mechanism
- @ Power of the motor
- (6) speed & feed a vailable
- 7 Type of Shaper plain (or) Universal
- (8) Floor space required.
- () Total weight of the Sharer
- (1) Ratio of Cutting Stroke time to return Stroke time

cutting strake time cuting any Return Stroke time m~ 2:1 to 3:2

Machining time colculation in a shaper;-54) Formulae's used !-1) Cutting speed (V) !-Length of cutting Stroke (L) in mm Time taken for ]= Cutting Stroke ]= Cutting Speed (V) × 1000 in majorin 1000XV (b) The nation by it is a Return time neturn to cutting time - Cutting time -: Return time = ma cutting time = MxL loooxr (C) : Time taken to complete? = <u>L</u> [1Fm] one double Stroke ]= booxr [1Fm] (a) Number of double Stroke (on) Number of Nevolution of bull ) n= gear per minute 00024 L(1+-)

(e) .: auting speed, v= n2(1fm) m/minute where 1 -> nomber of double strake ( min L) Length of the Smoke -) Ratio of Return time to Cutting fine (2) Machining time :-L= Length of the Stroke in mm B = Breadth of the work in mm S = feed in my double smoke m= the hatio of return to cutting time V= cutting speed in m/min a) Time taken to complete )= <u>L</u> [1+n] one double Stroke )= 1000xv [1+n] b) Total number of double] = B Stroke ]= J C Total machining time = LXB [1+m]

Problems:-In a Shaper work, the length of the Stroke is 200mm, number of double smokes Per minute is 30 and the gratio of return time to cutting time is 2:3. Find the cutting speed. Given!-L= 200mm; n= 30; m= 2/3; v=? Soln:  $\Pi = \frac{1}{\frac{L}{1 + m}} = \frac{1000 \times r}{L(1 + m)}$  $V = \frac{n \left( 1 + fr \right)}{1000} = \frac{30 \times 200 \left( 1 + \frac{2}{3} \right)}{1000}$ V= 10 mmin 2 Find the time negnical for taking a complete cut on a plate book goom if the cutting speed is 9 m ] min. The networn time to culting time natio is 1:4 and the feed is 3mm. The Cleanance at each end is 75mm.

Given: (57) V= 9 m/min; m= /4 ; feed, s= 3 mm; clearance at each ] = 75mm; end )= 75mm; Machining time Required for book goomn w/p?

Soh:-

In a Shaker, a Stroke leggth of more than goomm is not ordinarily a Vailable. So the work is placed on the table to take a cut of boomn plus the clearances.

: smoke length, 
$$L = 600 + 75 + 75$$
  
[ $L = 750 \text{ mm}$ ]

Machining time = 31.25 minutes. For Single Pass

Drilling Machine

It is the machine used to don: 11 a hole on the work piece quickly at a low cost.

Here the Role is generated by the notating edge of the cutting tool known as don'll bit which exerts large force on the work clanged on the table.

Types of doilling machine:-() Portable dailling machine 2 Sensitive drilling machine (3) UP9ight doubling machine (4) Radial devilling machine (-) se -vniversal > Universal (3) Gang devilling machine ( Multiple spindle drilling machine 7 Automatic desilling machine (8) Deep hole dhilling machine



- * It is snall & confact in size & can be taken to anywhere & the holes (on be produced on the workpiece in any pasition.
- * The maximum size of the daill that it can accomplete is not more than 12 to 18mm.



- * used to produce small holey of dia from 1.5 to 15.5mm at Righ speed in light jobs.
- * The base of the machine may be mounted on a bench (or) on the \$10091.
- # It consists of
  (1) horizontal table mounted on a piller
  (2) Vertical spindle for holding the da: 11 bit.
  (3) Vertical column (or) piller
  (4) Base (5) Mechanisms for driving the Vertical Spindle
- * The Various Speed for the Spindle is achieved by means of Belt & Pulley drive.
- * Here, there is no automatic feed. Feed is given manually.
- * Hand feed Permits the opreator to feel (or) sense the Progress of the dhill into the work so that if the dhill becomes worn-out (or) jams into the work, the pressure on the dhill may be heleased immediately to prevent it from breaking.
- * As the operator senses the cutting action at any instants it is called " sensitive desilling machine".



F19:4

(3) UPStight destilling machine [ see fig: 3] (2)

* Designed for handling medium sized jobs

* In construction, it is similar to sensitive drilling machine but it is larger & heavier than Sensitive drilling machine & is supplied with Power feed arrangement.

* A large number of spindle speeds & feeds are available in this machine for drilling different types of work.

* The table of the machine have different types of adjustments.

* It is mounted on the floor.

* It consists of the following Party O Base 2 Vertical column

3 Horizontal Am & the table

(4) spindle (5) driving mechanisms for Spindle

1) Base :-

It is a supporting member made up of cost Iron. It has T-slots on its top Surface for nounting the farge workpieces dimectly on it. B Column:-

* Vertical member manual on the base & cornies the Radial arm brasle, spindle brits driving mechanisms. * It may be af gound type (or) Box type. (Pillar)

3 Radial arm & table :-

* The table is nounted on a Radial ann which is mounted on a Vertical column.

* It had following notenents
() The motenent of the Radial armina Vertical direction along the column
(2) The Swivelling notenent of the Radial arm around the Column up to 180°
(3) The Switcelling of the table about its own Center up to 360°.

* By means of the above novements, the workpiece Can be dhilled in Various positions.

() Spindle:-

* used to hold the dhill bit of Uprious Sizes

* The Various Speed for the Spindle is achieved by Step cone pulley to belt drive * The following feeds are available for spindle () Sensitive hand feed () Quick traverse hand feed ()

- 3 Auto -feed.
- (F) Radial dhilling machine:- [See: Fig.4]
  - * This desilling machine is intended for medium to large & heavy workpieces.
  - * This machine consists of the following Party O Base @ Column 3 Radeof Ann () Dhill head () spindle mechanisms.
    - Base, * It is a large nectangular casting * It Supports the Vertical Column & Table. * The top Surface of the base is accurately machined with T-Slots to mount the

large Size workpieces on it.

Delimining the consists of heavy, sound, vertical column mounted on a large base.
* The column Supports a Indial arm which can be traised (or) bowered over the column & Swong around

column. * An elevating screw is provided on the side of the column to move the radial arm up & down by a motor. (3) Radial arm :-* It is mounted on a Vertical Column * It can be moved up to down over the column and can be surg around the column It Supports the drill head. * It has horizontal flat guide ways to move the drill head along a radiafarm. * By meany of the above movements for a

radial army the workpiece can be machined at different Positions.

Dr:11 head :-

* It is mounted on a radial arm.

* It has a me chanisms for driving the spindle & noving the drill head along the guide ways of the radial arm.

* the Anill head has a spindle which carries the daill bit. (5) Me chanisons for driving the spindle:(6)
* The different speeds for a Spindle is achieved
through a georbox.
* The following feed for the Spindle is available
(1) Sensitive hand feed
(2) Quick traverse feed

3) Automatic feed.

Radial dhilling machine may be classified with respect to the movement of radial arm & tool head. () Plain type (2) Seni-Universal type (3) Universal type.

O Plain type !-The following movements are available for

a plain type nadial drilling machine

- * UP & down movement of the hadred arm over the column.
- * Switcelling movement of the radial arm around the
- * movement of the tool head along the hadiaf

2) Seni-universal type:-

* In this type of radial dhilling machine, in addition to the above three movements of the plain type radial dhilling machine, the dhill head can be swung about a horizontal axis Perpendicular to the arm.

drilling hole to the horizontal place other than the normal Position.

3) vniversal type:-

* In a vniversal machine, in addition to the asove four movements, the arm holding the dhill head may be notated on a horizontal axis.

* AM these five novements in a runiversal mechine evodes it to daill a work piece at any angle.

(5) Gazz dailling machine !-

* when a number of single spindle defilling machine columns are placed side by side on a common work table which is mounted on a common base, the mechine is known as " gang defilling machine".

- * Four to six spindles may be mounted side by side.
- # In some machines, the denill spindles are permanently placed 18 in others the position of the Column may be adjusted so that the Space between the spendle may be varied. (68)
- * the speed & feed of the spindles are controlled independently.
- * this type of machine is specially adapted for Production work.
- * A series of opreations may be performed on the work by Simply Shifting the work from one Rossition to the other on the work table.
- * Each spindle may be set up properly with different tools for different oprections.



6 Multiple spindle drilling machine:-

* This is used to daill a number of holes in a Piece of work simultaneously & to reproduce the same pattern of holes in a number of identical pieces in a mass production work. (3)

* It has several spindle driven by a single motor & an the spindles holding drills are fed into the work simultaneously.

* Feeding motion is usually obtained by haising the table (or) lowering the took head.

* The center distance blu the spindles can be Varied based on the different opreations required. () Automatic dhilling machine:-

* It can perform a series of machining opreasing at successive Units and transfer the work from one Unit to the other Unit automatically.

* Once the work is headed at first machine, the work will move from one machine to the other where different opreations are done and the finished work comes out from the fast enit without any manual handling.

# It is used Purely for Production Purposes.

Deep hole don: 1/1ing !-

* Deep hole drilling is the opreation of making a of 4/2 ratio from 6-30. deep holes in a long shaft such as Rifle barrely, Crank Shaft etc.

* Deep hole dhilling machines is opteated at high speed & how feed.

* Sufficient quantity of hubricant is pumped to the cutting points for removal of Chips and cooling the cutting edges of the drill.

- * A long shaft is usually supported at several points to prevent any deflection.
- * Here, the work is usually rotated while the dhill is fed into the work. This helps in feeding the dhill in a Straight Path.
- * In some machine, both the dhill be the work are rotated for accurate location.

* The machine may be horizontal (or) Vertical type.

* In Some machines, Step feed is applied. The dhill is withdrawn automatically each time when it Penetrates into the work equal to its diameter. This Process Permits the Chip to clear out from the work.



Azis:- The longitudinal centerline of the dhill.
 Body: Portion of the dhill extending from its extreme point to the commencement of the neck
 Shank:-

Partion of the dhill by which it is held into the spindle & dhiven. The most Common types of shark are the taper shark & the straight shark.

(+) Tanp:-

The flattened end of the taper shakk intended into a spift slot in the spindle. The tang engures Positive drive of the drill from the drill spindle.

5 Necki-

The diametrically undercut Portion between the body and the Shank of the dhill. Diameter and other Particulars of the dhill are engraved at the neck (b) Flutes!

It denotes the produes in the body of the drill

the function of the flutes are 1) to form the cutting edges of the dhill (2) To allow the Chips to escape (3) To cause the chies to curl ( To permit the cutting fluid to reach the cutting edge

() Flank :-It denotes the Surface on the drill point.

(8) Face:the Portion of the flute Surface in the point The chip impinges on the face of it is of the drill. cut from the work.

D Lip (cutting edge):-The edge formed by the intersection of flank & face.
O chisel edge:-The edge formed by the intersection of the flanks. It is sometimes called of "Dead Center". A great amount of axiel thrust is required to cuta

hole by a chisel edge.
(1) Body cleanarce:-
the Portion of the body Surface which is
reduced in dianeter to provide diameteral cleanance.
12 Heel:-
The edge formed by the intersection of flute
Surface of the body cleanance
3 Lords:-
The cylindrically ground Surface on the
edges of the dhill flutes.
(F) Heel:-
The edge formed by the intersection of
body clearance & the flute
(5) Point:-
the Sharpened end of the dhill, which is
Shaped to Produce lips, faces, flanks and chisel
edge

( Drill angles )_ Following are the Anill angles which are ground on a twigt drill for efficient removal of metal. O chisel edge angle 2 Helix angle (or) pake angle 3 Point angle @ Lip Clearance angle

chisel edge agele:-

the obtuse angle included b/w the chisef edge & the lip as viewed from the end of the drill. It varies from 120° to 135°.

Helix angle (or) Rake angle :-

* It is the angle formed by the leading edge of the land with the axis of the drift.

* the usual argle of the name = 30°-45°

Point angk !-

* It is the angle included between the two kips. The usual point angle is 118°, but for harder Steel alloys, the angle increases. Lip clearance angle:-

The apple formed by the lip and a place at hight apple to the drill axis. The clearance apple is 12° in most cases.

Specification of Drilling machine !-

- O Maximum Size of the doill in mm that the machine can hold.
- (2) Table Size in Square meter.
- 3 Maximum Spindle trakel.
- (F) number of spindle speeds & range of speeds in A.P.M
- (5) number of auto Spindle feed & feed hange in mm/nev
- 6 Morse taper number of the dhill spindle taper Portion
- 7 Power input of the machine in H.P
- (8) Floor space neguired in Square meter
- () wet weight of the machine in Tome.

10.0 (on) Feed mechanism Mechanism Quill Spirale worm & worm wheel TOP Shaft Bevel Georg Power from motor through set of yorn wheel Gear train Sliding key lever Quill - Cone Georg - Bevel Gears 6191 - Botton Shaft worm Quick Clutch Daill Chuck feed Two Gearboxes Hand wheel sensitive feed anilable Hand wheel O steed year box 2 read year box there are 3 types of feed which can be obtained in dhilling Machine 1) Automatic feed for spindle 2 Sensitive Hand feed Quick tra Verse Hand feed. B

1) Auto feed for spindle:-* The automatic feed is applied while drilling large diameter holes as the cutting pressure required is sufficiently great * The power from the top shaft is transferred to Six speed feed box through worm & worn wheel. the * In the feed boxs () six Georg mounted on the worm geor Shaft are constantly in mesh with another Six geors mounted on the deliver shaft. 3 Georg on the driven shaft are all Keyed to the Shaft & notate with it. 3 Gears on the worn gear shaft are all free to notate, but may be keyed to the Shaft by a sliding key only by one gear at a time. when the sliding key is in the first geory the

motion is transmitted to the driven shaft from the

first gear. Other gears on the worn shaft she volve freely

with their mating year on the dhiven shaft.

* Thus Siz different speed for the driven shaft are obtained by Sliding the key to engage with Siz different georg on the worn geor shaft. * The motion from the driven shaft is transmitted

to the bottom Shaft through a set of bevel georg. * The worm at the end of the bottom Shaft Receives the power by a clutch on the bottom

shaft.

* when the worm at the end of the bottom Sheft States; the worm wheel meshing with that also Notates. At the end of this worm wheel Sheft; there is a pinion. This pinion meshes with the Shere is a pinion. This pinion meshes with the Sherk which is bolted to the quill (or) spindle.

* The Notation of the pinion Causes the quill to move up & down giving spindle feed.

2) Sensitive Hand feed :-

It when the sensitive hand feed is applied, the clutch is disconnected.

* The sensitive hand feed wheel is attached to the great end of the bottom shaft. * So, the notation of the sensitive hand wheel will cause the worm of worm gear to notate and a slow but a sensitive feed is obtained.

3 Quick traverse hand feed :-

* Quick traverse hand feed is obtained by notating Quick traverse hand wheel which is attached with Pinion

* One turn of the Quick traverse hand wheel will cause the Pinion to notate through one complete nevolution giving quick hand feed movement of the spindle

* Clutch should be disergaged when giving the

quick traverse hand feed.





Dinectly holding the tool! - [ see fig:1] * AM general Purpose drilling machine have the spindle to a Standard taken to neceive the borred out toper shark of the tool.

* The taper used in the drill spindle is usually Monse standard toper which is approximately 1:20.

* while fitting the tool, the shank is forced into the tapered hole & the tool is gripped by friction. * The tool may be notated with the Spindle

by friction between the tapered surface of the spindle

and Shank of the tool; but to ensure a Positive dhive, the tang (or) tongue of the tool fits into a Slot at the end of the taper hole of the Spindle. * The tool may be removed by pressing a tapened

spindle. (83)

* It can be noted that the spindle should not be affected while the dhift is pushed to take out the dhill bit. Usually a mallet should be used in stead of a farmer.

## Sleeve: - [Fig: 2]

* The doi: M Spindle is suitable for holding only one size of the Shank.

* If the taper shank of the tool is smaller than the taper in the spindle hole, a taper sleeve is used.

# The outside taper of the sleeve conforms to the dhill spindle toper and the inside taper of the sleeve holds the shark of the Smaller size tools. # The sleeve has a flattend end (or) tang which

fits into the slot of the spindle.

* The tags of the tool fity into the slot provided

* The took from the sleeve & the sleeve from the Spindle may be grenoved by forcing the drift into the Connesponding slot by a mallet. (84)

* Different sizes of tool sharks may be held in the spindle by using different sizes of sheeve

* The taper on the outer surface of the sleeve doesn't charge but the inner taper surface varies with different sizes of the tool shanks.

3 Socket :- [see fip: 3]

* when the tapered tool shark is larger than the Spindle taper, dqill Sockets are used to hold the tool. Dqill Sockets are much longer in size than the dhill sleeves.

* the tapered shank of the socket conforms to taper hole of drill spindle & fits into it. * The body of the socket has a taper hole larger than the drikl spindle taper into which the taper shank of any tool may be fitted. ( Three jaw self centering chuck: - [ see fig: 4]

* this type of chuck is particularly adaped for holding the tools having straight sharks. (85)

* three Shots are cut 120° apart in the Chuck body which houses three jaws having threads cut at the back that meshes with a gling nut.

* the ging nut is attached to the sheete.

* Bevel teeth are cut all yound the sleeve body

* the sleeve may be notated by notating a key having bevel teeth cut on its face which meshes with the bevel teeth on the sleeve

to notate in a fixed position and all the three jaws will move Simultaneously by the same amount. and hold the dhill bit having Straight Shanks. Drilling Machine operations:-() Dhilling (2) Reaming (3) Bohing (4) Counter Bohing (5) Counter Sinking (6) Spot facing (7) Tapping (8) Lapping (9) Grinding (10) Tre Panning.



* Dhilling in the opreation of Producing
a Cylindnical hole by feeding the
Notating dhill into the work Piece.
* Before dhillings the center of the
hole is located on the wip by drawing
two lines at hight angle to each other
& the center punch is used to Produce

an indentation at the center. The drift point is pressed at this center point to produce the Required hole. * Drilling does not produce an accurate hole in a work piece and the hole so generated by drilling becomes nough and the hole is always shiphtly over Size than the drift used due to the vibration of the Spindle & drift.

* A 12 mm dhill may produce a hole which 0.125 mm ollesize

A 22mm dhin may produce a hole which 0.5mm ollersize



* It is the operation of Sizing & finishing a hole which has been already dhilled. The tool used for this operation is called as for this operation is called as feul "Reamer" (or) "Reaming tool".

* In order to finish a hole be to bring it to the accurate size, the hole is drilled slightly undersize

* The Spindle speed is made half of the speed for drilling oppeation & auto feed may be given.

- * Reaming tool (or) Reamer has multiple cutting edges and it does not originate a hole. It simply follows the Path which has been already drilled and renoves a Very Small amount of metal.
- * For this neason, a greaner cannot connect a hole
- * The material Removed by this Process is around 0.375mm.

Bosting! -

* It is the opprestion of enlarging the already dhilled hole by an adjustable cutting tool with only one cutting
edge called " Bosting tool".



- * Bosting opreation is performed in a drilling machine for the following steason.
  - O To enlarge a hale by an adjustable cutting tool with only one cutting edge. This is necessary where Suitable Sized drill is not available.
  - @ To finish a hole accurately & to bring it to the required Size.
  - 3) To machine the internal Surface of a hole already Produced in the casting.
  - ( To connect out of houndness of a hole.
- 5 To connect the location of the hole as the boning tool follows an independent path with hespect to the hole

* Here the cutting tool is field in a boring ber which they a taper shank to fit into the spindle socket.

Counter boring !-



* It is the operation of enlarging the end of a hole cylindhicolly. * The enlarged hole forms a Square shoulder with the original hole. It is necess any in some cases to accompdate the heads of bolts, studs, Ping etc.,

* The tool used for counterbohing oppeation is called as counter bohe. It is made with takened (or) straight shark to fit into the dhill spindle. The cutting edges may be straight (or) spiral teeth.

* The tool is guided by a Pilot which fits into the Small dianeter hole having running clearance & maintaing the dignment of the tool.

* these pilots may be interchanged for enlarging different sizes of holes.

Counter Sinking :-

It is the oppression of making cone-shared

enlagement of the end of the hole to phonide necess for a flat head screw (or) countersunk nivet. * The tool used for counter Sinking operation is called as Countersmik. * Standard Counter-Sinks have wip bo", 82° (or) 90° included angle. * The cutting speed for thig opreation is 25%. Less than that of

drilling.

SPot facing -1 /il i+

Tapping :-

* It is the opreation of Smoothing and Squaring the Surface around a hole for the Seat for a nut (or) the head of Screw.

* A counter boke (or) Special Spot facing tool may be employed for this purpose

It is the oppeation of culting internal into the alneady drilled hole twreads by means of a cutting tool called a "tap".



* A top may be considered as a bolt with accurate thready cut on it.

* The threads acts as cutting edges which are frankened and ground.

* when the tap is screwed into the hole, it hemovey metal and cuts internal threads which will fit into

the external thready of the same Size Tap da: 11 size :-

# As the size of the thread is the outside dianeter of the threads, the drilled hole must be smaller than the tap by twice the depth of the thread.

* Tap dhill size may thus be derived from the following

formula D=T-2d T-) Die of tap

D-> Dia of dailled hole d -) depth of thread of the tap

Trepannings:-

# It is the opprestion of producing a hole by renoving the metal along the circum ference of the



# It is performed for producing bigger holes # Fewer Chips are removed when machining. # Tre-Panning opreation are done at higher

Speeds.

a bigger hole

Feed, cutting speed, depth of aut of a dhilling oprection:-

Cutting speed ! -

It denotes the Peripherof Speed of a cutting point on the Surface of the dhill in contact with work

Feed:-

It denotes the distance the drill makes into the work at each revolution of the Spindle It is expressed in malther (or) malmin.

The feed perminute can be calculated as

$$S_{m} = S_{m} \times n$$

$$S_{m} = \text{ feed in } mm | \min$$

$$S_{m} = \text{ feed in } mm | \text{shey}$$

$$n = 9.9.m \text{ of the dhill.}$$

Depth of cut!-

Depth of cut is generally taken as one-half of distill dianeter

$$t = d_2$$
  $t = depth of cut in m.$ 

Machining time in dhilling :-T= L axsz n = r.P.m of the dhill Sy = feed of the dhill in mn her L = Length of bavel of dhill in ma T= Machining time in min. L= l, fl2 the fly where l, = length of the wip l2= Approach of the dhill lz= legan of the daill Point (0.29d)

ly = over travel.



1) Plain (or) Horizontof milling machine!-



* Base make of grey C.I berles as she services for cutting fluid. * Column Supports & Guides the knee. Motion & other driving mechanisms are housed in it. * Olleram Supports

V

the outer end of the arbor to Prekent it from bending.

(2) Vertical milling machine !-Spinkle Colom Suddle (2) Cuther Colom Suddle (2) Eleventing unee 1 Screw Cuther (2) Base (2) Base (2)



Common feeds O Longinding by Table 2 cross by saddle 3 Vertical by knee A Rotation of Spindle with this makements quide the spindle head at an angle. * Mainly used for end milling and face milling opreations.



Universal miling m(c -> with all the opting done on plain milling m/c, Itelical years, Spinaf bevel gears, twist drilling, Reamers, milling cathers, all types of milling, dhilling, Shapingoping



Applications :-

Taper Spiral Grookes in reamens & sevel Georg, Twist Drill, Spir Ritelical Gearn, milling custers & AM types of milling, drilling & shaping oping. Bed type Milling m/c:-

> * comparatively large, heavy in construction * Vertical motion imparted to Spindle instead of Table * Dep on 70 of Spindle, Simplex, Duplex Triplex bed Type milling m/c.

() Simplex (Fixed bed type) Milling m/c:-



Sime the bed is fixed, it Can not more up, down The spindle head Carries the spindle, which Can be moved

5

up & down along the Column ways.

Table -> Cross-wise makement

(2) Duplex head fixed bed type milling m/ci-



3 Tripler head fixed bed type milling machine !-

Three spindles -Horizonde 7.00 one vertical.

Plano -type milling machines



6

The silp can be machined in 4 different ways. () By moving the table & hoteting the custers in Position (2) By keeping the table Stationary & feeding the custers (3) By moving the table & milling head simultaneously (4) By keeping the table & milling head simultaneously (4) By keeping the table Stationary and moting the cross-frail downwars & also the side custers up & down.

Work Holding Derices !-() T-601+& clamps (2) Angle Planes (3) V-blocks 9 Machine vice (5) Dividing Lead @ Universal vice (7) Fixtures. Tool - holding Devices :-Anbons 0 2 Adaptors 3 collets Anbors:-(i) standard Anson (i), Stub Anson driving fug of the spindle Slot to espere with standard Anboni-Bearing Bush Shank - 14 Internal Spacing toread cute (ollars) Stub Asson when Interne SPACES thread 31 coller)





@ Angle Milling cutter :-











Deep sloty partice off the wp.

Dove -tool Slot milling cutter :-





Formed cuderd:-

for making Dove-tail Slots

 $\odot$ 



* The cuting edge may be formed to reproduce contoured surface. * considered as emergency fool other the standard tool is not a vailable.





MILLING PROCESS

O Periphend milling - Milled Surface II" to the axis of Totation of cutter
O UP Millingtor) Conventional milling ( Down milling (or) climb milling @ race milling - Milled Surface It to the assis of gotation of cuber

UP milling (or) conventional milling:-



* Direction of notation * Chip thickness. * acting force dimection * preferred over clims milling in the case of backlash. * chip welding & hear dimiparion

Advanage:-

* Backlash climitatory * Safer operation is not negurined

Down (or) Climb milling:-Adlamage !cuders + cutter win high rake angle. # cutter wear is less 5 (16) I

Face milling -

- * Machined Surface 1" to the axis of Protection of cutter.
- + generally face milling under und for finishing.







Producing flat Korzental Surface 11el 10 he are of he after.





operation of machining a flat Surface at an angle other than right angle to the arts of the revolving Cutter.



1/1/ Surface

Profile milling:-Post come wion とし すのします + Steproduction Endmill of outline of Templare Template (or) JP Complex Shape of masser die on the workpiece. Table

End milling :-



* used to Produce flax Surface which may be Vertical, norizondal (or) Inclined to the table Surface * 510ths Key ways, GrooVer etc.



* rannow Slots & warrow Grooves on a wife. * Also used for earring off the workpiele



Gear cutting:

T-shots on a up using T-stot cutter. First stage: - Plain slot is made by using end milling cutter. Second Stage: - T-slot is made by using T-slot futter.

3

used to produce

year cutting Machining process:-1) Formed cutter method (a) by formed disc cutter in Horizontal milling m/c (b) by formed End will in Vertical Milling m/c ( by Single point form tool in Shaper (or) planer (d) by Shear speed Shaping process @ by Geor broaching (f) by template method. 2) Geor Generation @ Gear sharing process (b) Geor Planing Process C) Gear Hobbing Process. () year cutting by formed disc cutter in Horizontof milling machine -1) To form a spur years column & knee type Horizontal milling machine is used.



2 Universal Dividing head & TailStock is fit in the correct position on the table

3) The Dividing Head Spindle has Intersore & outer tweeded portion for holding the Live center and catch plate respectively.

(1) The Gear Slank is fit into the mandmel which is supported in between Live & Dead center with the help of catch plate & Dog Corrier.

(5) Now, the formed disc curder of Required Profile in taken & is fit into arbor of the milling machine.

(6) The cutter teeth is made to coincide with the Standle axis by Various modelment a vailable in the milling machine

1) Based on the number of divisions hequired on fine work piece, Indexing method is selected & then Indexing Calculation in done so that required amount of crank along the hole Circle of Index plate novement along the hole Circle of Index plate after each tooth is formed can be found out. (8) NOW, the depth of cut is given by elevating the table 18 the workpiece is fed against the notating cutter. (g) After one tooth is formed, it will be indexed to the next position by notating the Indexing Crank upto the Required number of holes in the selected hole circle of the Indexig place.

( In this way, SAM gear is formed in the Column & knee type Horizontal milling machine. Spur year calculation:-Indexing !-(a) Blank diameter = m(2+2) ho of holes ]= to to be moved ]= Z (b) Tooth Depth = 2.25 m (c) cutter patch = 3m.

Dividing Head & Inderling!-

- Indexing is the process of dividing the periphery

CE

- For doing this indexing, An attachment called dividing Head is used with the milling m/c. There are 3 types of dividing Head

- () Plain (or) Simple directing Head
- 2 priversal dividing Head
- 3 optical dividing Hend.



* Simplest of our divinding heads

* used for making Small number of divisions on the Periphery of the wife [ 2Pto 24]

Universal Dividing Head :-6 Swive block Morried in degrees Digness Index place pluger Conch plane Index Orank Index Pla 00 Inder - Body plate M)c table Π П seel Dines Ide Spindle Gearble 05 00 yearn or [in] (dotter) Stock 591:Ven sive Dear Cere yes Sut Conter ock An Worm Geor = 40 teeth 1 turn of 7 Main Beve EARINE Inder Place Indering Spinke -Ur Georg ank Ah Chank / Physe From I have to next have Indexing along 18 hole Circle Crank 10×18 = 1 herof spindle

() To set the will in defined position [Horizontal, Vertical (0) in relation to the m/c table Inclined]

Uses:-

5' below Horizontal & 10' beyond Vertical

- 2) To turn a workpiece Feriodically through a given angle (Indexing)
- (3) To provide continuous rotary molement to the job during milling of Helical fears
- ( To hold the workpiece & Support it in Conjuction with the tail Stock

Indexing Methodsh () Disnect (or) Ropid Indexing (2) Plain (or) Simple Indexing (3) Differential Indexing (4) Contrained Indexing (5) Angulur Indexing. (0) Disnect (or) Ropid Indexing!

* obtained by Plain (or) Universit dividing head. * In Universal dividing head, it is obtained by notating the spindle by hand after disengaging the warm wheel & worm. * Direct Index plate - 24 holes

factors of 29 -> (2, 3, 4, 6, 8, 12, 24)

Rules for Dinec+ (or) Rapid Indexing-

No of holes to be moved =  $\frac{24}{N}$ . N = No of divisions sequired.

example:-1 Find out Index Crank indrement to mill a Hetagonal bolt by dishect Indexing.

No of holes to be moved =  $\frac{24}{5} = 4$ So, lifter maching one side, the Index place will have to be moved by 4 holes for 6 number of times to machining the generating faces of the bolt.

7

Bhown (S)

& Share(s)

Simple (02) plain Indexing:

* Suitable for divisions beyond the stange of Rapid Indexing

Formula for Simple (or) Plain Indexing

No of holes to be moled = <u>40</u> N-NO of divisions B&S Index Plates Plates

Plate no! 1 - 15, 16, 17, 18, 19, 20 Plate no! 2 - 21, 23, 27, 29, 31, 33

Plate no; 3 - 37, 39, 44, 43, 47, 69 My Contany

Ctample!-2 Set the dividing head to mill 30 teeth on a spir wheel blank by simple Indexing.

Index Chark molement = 
$$\frac{40}{30} = 1\frac{1}{3} = 1\frac{1}{3}\times\frac{7}{3}$$

Thus for Indexing, one complete turn and Tholesin 21 hole circle of Index place will have to be moved by the Index Crank

## Compound Indexing! -

* Called compound Indexing due to the two separate movements of the Index chank in two different hole Circle of one Index Plate

* First molement - is as plain Indexing

* The effective novement will be the summing of the two novement.

9 example for compound Indexing first molement :- 3 holes on a 15 Loles circle by crank pin  $\bigcirc$ Second molement: - 4tholes on a 12 hole circle formed. by Index Plate So, effective indrement ) 3 + 4/2 = 8 relidenten by worm ) 15 + 1/2 = 15 relidenten Since to turn of worm notates the spindle by 1 ster; 8 sev of worn notes the spindle by 8 1 = 1 sev : 75 divisions can be produced on workpiece first movement :- 6 holes on 18 hole circle by crone (2) Second advenuer: - Afdes on 16 fole circle backing by Index Place So, effective notement  $\frac{3}{18} - \frac{6}{16} = \frac{1}{12}$  ser : Spindle molement = 1 ×1 = 1480 ger .: Also dirisions can be produced on the will. Rules' for compared Indexing!- $\frac{40}{N} = \frac{n_1}{N_1} \pm \frac{n_2}{N_2}$ Ne se ni fat d'un a a d'friter agente a plateir, e a d'esta de

where, N= Number of divisions Required () N1, N2= The hole Circle used by the Crank Pin & lock Pin Respectively n1 = No of hole Spaces moved by the Crank Pin in N1 thole Circle N2 = No of thole Spaces moved by the lock Pin in #2 thole circle

Procedure for Indexing -For example, take a indexing for 69 division by Compound Indexing. () Resolve into factors the number of divisions neguired 3 69 69= 23×3 22 23 2 choose at gradom hole circle 23 & 33 Plate => 21,23,27,29,31,33 (3) Subtract the fide number of one Circle from 33 - 23 = 10

(4) Factor the difference 55 (e-) 10=2×5 (5) Factor the no of turns required by the worm to make one nevolution of the Spindle 240 40= 2×2×2×5 220 2/10 () Factor the selected the circle 515 33 = 3×11 23 = 23×1 I place the factors for no of divisions neguired be the factors for difference of hole circles above the Horizontal line and place the factors for

no of turns required by worm for 1 nev of spindle & hole circles selected below the horizon of line.

69		2/3+7
(0	1	\$+\$

 $40 = 2 \times 2 \times 2 \times 2$   $23 = 2/3 \times 1$  $33 = 2 \times 11$ 

(8) Cancel out the Common terms If the outher factors above the horizonal line is cancelled, the Chosen the circles are connect. Otherwise Choose another Set of hole Circles. In this case, the Choosen hole circles [2363] are connect as all the factors above the horizontal line are (ancelled.

$$\frac{40}{69} = \frac{44}{23} - \frac{44}{33} = 1\frac{21}{23} - 1\frac{11}{33}$$
$$\frac{40}{69} = \frac{21}{23} - \frac{11}{33}$$
$$\frac{40}{69} = \frac{21}{23} - \frac{11}{33}$$

There fore, After each tooth is cut

- O First, more the Grank of Index plate by 21 holes doop 23 hole circle
- @ Second, mole the Rock pin on the backside of the index plate by 11 Roles along 33 hole circle in a greverse direction.
( Differential Index: p!-

() The novement of Index Crank Similar to the Simple Indexing

as

- 2) The Simultaneous indement of the Index Plane, when the Crank 13 turned.
  - Charge geors :- 24, 28, 32, 40, 44, 48, 56, 64, 72, 86, 100.

with this Charge gears & BAS Index place, It & POSSible to Index any number for Upto 382.

Special genis :- 46, 47, 52, 58, 68,70,76,84

with this georgy index = 383 to loop

example:-4

Index 83 divisions.

First of all, Check it can be indexed by plain indexing (ar)

Index crank novement =  $\frac{40}{N} = \frac{40}{83}$ AS \$3 Lole Circle available So, Differential Indexing for the 23ed.

Rule for Differented Indexing:-

D Gear statio = Driving gear on sandle Driven gears on bevel = (A-N) × 40 A Geor shaft

where,
A = the selected number which can be indexed by
plain Indexing & the number Shall be rearer
to the no of divisions bequired
N= Number of dirbing to be indexed.
(2) Index crank undement = 40.
then the index crack will have to be noted by an
anount for N number of times for complete division of
work. TC (A-N) is positive, the index plate must thate in
the some direction. the some direction.
If (A-N) is regime ato the crank
The chieve these conditions, the number of integeors
to actually on the following factors
used determination of the the A-N) is positive, only one
(a) gen man is wheel.
(b) geormain is conpared & (A-+) is restrive, no idle
gear is used.
(c) fear train is simple & (A-r) is repartive, two solls
foors are used.
(d) fear train is compained and (A-ri) is regarine,
only one idle georg me used.

Example: 4

Index for 83 divisions.

First of all, findout whether the number can be indexed by plain indexing (or) not.

Index crank movement =  $\frac{40}{N} = \frac{40}{83}$ 

since, there is no 83 hole circle, the number cannot be indexed by plain Indexing. Therefore it is the case of differential Indexing.

Place no: 3 37, 39, 41, 43, 47, 49

Assume A: as 86 O Geor vario =  $(A - N) \times \frac{40}{A} = (86 - 83) \times \frac{40}{86}$ =  $3 \times \frac{40}{86} = \frac{72}{24} \times \frac{40}{86}$ 

2) Therefore, Driver 3 = 72,40 Driven = 24,86.

3 Index Crank molement = 40 = 20 86 = 43

For complete Indexing, the index crank will have to be moled by 20 holes in 43 hole circle for 83 times.

(+) AD (A-n) is positive & the fear ratio is compound, no idle fear is sequired.

Angular Indexing !-



40 ner of the Crank = 1 her of the : Spindle = 360

: 1 her of the crank = 300 = 9°



Etample!-5 Index an angle 19' 40' 19' 40' = (19×60) +40 = 1180' .: Index crank and event = -1180 540 = 2 %2 The index crank Should be moled two complete

turns & 5 holes in 27 hole circle

Sector arms :-



* Inadial dignance blus the arms can be adjusted depending on the no of holes to be moved.

Helical Geormilling in voiversal milling ble Lead Scie charge year Helix angle 1.itre rdexela Dn: Shafer The Gear blank is fit into the mandred which 0 Supported in between Live center & Dead Center 15

(3) Cutter, of negnined profile in taken & fit

of

universal Dividing head & Tail Stock enertectively

3 then the workpiece axis is made to coincide with the custer teeth by Uprions molements available in the milling machine,

(4) Then, the table is suivelled to the required Helix angle.

- 5 * For forming a Helical teeting the Gear blank shall be () notated to a distance of fead when machining takes place. So, here the mittre Gear of the Universal dividing head in connected to the table lead screw through a Gear train.
  - * So when the feed is fiven, continuous rotary motion is given to the workpiece from the table leaf Screw through a set of gear train in the wriversaf Dividing head.
  - * As the gear train is connected to the bable lead Sciew, differential Indexing cannot be done. only Simple Indexing method is used for Indexing.
- ( row, the table is fed against the notating cutter to form a tooth on a Gear blank.
- After one tooth is formed, up is indexed to the newsol next position by moving the indexing crank to the negwood number of holes in the Selected hole circle and the next tooth is formed.
- (2) In this way, Helical is formed by whitersal milling machine.

Helical Geor milling calculation:-

(a) Blank Demener 
$$= m \left(\frac{z}{\cos \beta} + 2\right)$$
  
(b) Tooth depth  $= 2.25m$   
(c) Cutter Pitch  $= 6m$   
(d) Index Crank movement  $= \frac{40}{N}$   
(e) Lead of the Helicol Geor,  $T_2 = \frac{T_2 D}{N}$   
(f) Geormanic  $= \frac{DPriver}{Driven} = \frac{40T_1}{T_2}$   
Ti-P Pirch of lead scent  
 $T_2 - freed of the helicol Geor.$ 

(3) the teetn, z'= 2 cos2p

Curtier NO	no of teeth to be cut	Based on z' value, the
NO.1.	fron 135 55 - 134	currer shall be chosen from
NO. 4	35-54	the table
ND.5	21 - 25 (7 - 20)	
NO.7	14-16	





* All teeth are formed Smultoneously by a ning of formed blades * Work- Ram & AleciProcetey * Radial Adjugament for the author for ( selef during remaction 2) Depmofut.

uses:-Spurlear, splined shaft, Ratchet wheels etc.,

Gear milling using a formed End mill!-* Done in VMC * Simple Indexing is used Crank molement = A= * spur; helical, herrigebone georg.

year broaching:-

Geerblank



Concernic Circle denotes dean of cut ar tooth.

Template method!-



gear generating method:-

O It involves the Production of a geor tooth Profile by a single point Single Point cutting tool which (exchanged in reciprocated & made on a frame) to follow a guided Ram by a template whose Profile Corresponds to the Shape of the geor tooth being cut.

Gear sharing process
 Gear Hobbing process

## Principle)-

Gear Generation is based on the fact that any two involute Georg will mesh together.

> * Here one Geor is made as a cutter of the other is made as a Geor blank. * cutter is made to reciprocare aller the envire width. of the Geor blank.

* cutter is fed Howards w/p (or) Vice-versa to give a deput of cut.

Gear teeth are penerated on the Gear blank.



- Derth of cut.

* Gear shaping is one of Gear Generation method used for cutting cylindhical external Georg.

* Gear shaping is done on a special type of markine Called Gear Shaper.

* Here, pinion type cubler with proper pake of Clearance angle is used.

* Here, the axis of notation of cutter & Geor blank

* Here the cutter & work spindle are separately connected with Gear traing. It gives connect nelative speed of notation to these two spindles. So, the notation of the cutter generates the tooth Profile on the Gear blank. The nolling movement is continued with all the teeth of the blank are cut.

* During return Stroke, the work in relieved from the cutter by a Suitable mechanism. It is done to avoid the rubbing of cutter over the cut surface



- The Various indements a Kailable in the geor shapen are given below.
- O Rotational feed for cutter & workpiece
- 2 Radial feed of the cutter towards the blank for giving the depth of cut.
- 3) Reciprocating motion of the cutter along the width of the Geor Bank
- ( withdrawd notion of the blank away from the cutter during neturn stroke

Application !-

- O Gear shaping is used for generating both internal
- & external Spor Geor.
  - 2 Helical Geor can also be generated using stering Attachment.

Advantages:-() Both internal & external Gears can be generated. (2) Various Sizes of years can be generated using a Single Cutter. (3) For the Same modules a single type cutter can be used innespective of the number of teeth in the gear. (4) As the cutting action is continuous, the rate of Production will be high. (24)

Limitation 1 :-1) Worm Geor can not be Anduced. 2) There is no custing in the neturn Stroke of the cutter. So, there is a need to make Return Stroke faster than the cutting stroke

Geor Hobbing !teeth

Hob

* the Phocess of generating a gear by means of a multi Point rotating cutter called hab is known as habbing. * this hab looks like a worm & this Process looks like a meshing of worm & worm wheel.

* The hob may be either single threaded (or) multi threaded Part. * In year hobbing opreation, the fear blank is mounted on a Vertical arbon but the hobig nound on a horizontal hotating arbon. 4 of hob feed Genethol onnected to drive movements available in a Gear hobbing The Various machine () Rotation of the hob [ cutter] 2 Verrical feed of the hob over the width of the Geor Hank

3 Rotational feed of the work prece (4) Radial feed of Gear blank towards the Cutter for piving the depth of cut. 26 read parts Georblank * In gear habbing, the axis of notation of cutter (hob) & the work piece are perpendicular

to each other.

* Here both Georblank & hub are made to notate like worm & worn Geor in mesh

For custing a helical Gear, the axis of hus is inclined

Lead angle, d= O+ (90°-d,) - & Gearblack are different. d = O-(qo'-d.) - Helix of hobb Geor blank are some a > Helix angle of the year to be formed. d, -> Helix apple of the hub.

Applications :-

Hobbing is used for generating spur, helical &

Advantages :-

- O using a single hob, my number of teeth of the same module can be produced.
- 2 spur & helical geor can be produced using the same tob.
- (3) Several Georgianky mounted on the Same arbor can be processed Simultaneously. So it can be used for mass production.

Dimitations:-Dirternal Gear cannot be produced (2) Rolling motion by the Gear black of Hob is not continuous. So, Production time is more



* It is done on the Georplanner. * Here rack cutter is used for making the teeth on the Georplank

- I Here, the anters the Gen blank's movements are like a movement. of a Mack & Pinion in mesh.
- * Here the Gear blank is fitted on the table. The Relative Rolling movement between the Gear blank & cutter is obtained by the Gear brain.
- # Here, after the Rack has cut 2 (or) 3 teeth on the Gear blank, it will be brought to the Starting position & the oppeation is nepeated till

all the teeth are cut on the Georblank (23) * In the Geor danning Process, the following movements will be given. () Radial feed of the cutter towards the Georblank for giving the depth of cut. (2) Relative Inductional feed & harizontal feed of the Georblank & cutter respectively (3) Reciprocating molement of cutter over the width of the Georblank.

(f) The withdrawl of culter from the Gear blank during the Return Stroke. It will avoid the gubbig action of culter during the Return Stroke

Application :-

used to cut external sourd helical year.

Advantage:-() the same module gear of any number of teeth Can be cut using a single rack cutter. (2) Used to cut external spurb helical gear. Limitation:- (1) Internal & worm gear cannot be produced. (2) Bue to stepping back of cutter, production time is high.

Geor Finishing process :-* Gears mann factured by different machining process will have grouph surfaces. * The machined georg may have errors in tooth profiles, concentricity, Itelix angles. * For quiet & Smooth opreation of George these errors & grouph Surfaces should be Removed. Geor finishing operations are done for this purpose. 1) Burnishing - for Gears not hardered. 2) shaving - for Georg not handered.

30

2.4

il,en II

3) Grinding - for Georg which are hardened. ( Lapping - for Georg which are hardened Gear Burnishig: -There there, the Hartened burnishing sear of some module of that of the 1 15 es that of the Geor to be finished is Work Geor made to mesh ) with the year Lubricant - 1 ( ) & Burnish Geor (to be finished. -nishig (2) The idler geory are used to support to give the Phessure Gear shaving :-* Most common method of Gear finishing. * In this method, a Very hand fear shaving Cutter is used to she over fine chips from the Gear teets.

Helicof teen cutter Lo - Helitage Mandhel travel of the cutte

Servated tooth of the cutter.

* Rotation of the work Geor * Rotation of Cutter & RECIProcation of Sharing cutter.

Geor Grinding:-

It is used for finishing of fears after hardening. Gear Grinding is done for

) Increasing the accuracy & Surface

finish of the sears

2) Removing the distortion after heat treatment.

There are two methods of Geor Grinding.

they are 1 a) corned wheel Grinding (33) b) Generation Geor Grinding.

Formed wheel Grinding :-



- cude

work year.

* Three Passes Required for Completing one tooth space. finishing.

Generation Gear Grinding: -

molement of cutter like a hack over pinion + * The work gear in rolled along an imaginary

Mack.

* Rolling is done in both the dinection to frind both Sides of the tooth. * The Grinding wheel notates & the ci procates along the length of the tooth.

Geor lapping !-

* The Surface of the Lapping Georg are inclined at about 4° to the work Geor Surface where of the Surface of the Driving Pinion is n'' to the work Gear Surface Lapping

Georg

* when the georg rotate, a lapping company is applied by them. The compound is a mixture of a very fine abrasive rouder and Kerosene.

Unit-IV ABRASIVE PROCESS AND BROACHING Introduction :-* Grinding * Self-sharpening of Grinding weel. * for what purpose ? TYPES of Abrasivess-(is manual Abratives dis Artificial Abratives. (a) Aluminium Okide (a.) Sand Stone (b) Silicon Carbide (b) Emergy () Anificial Diamod (c) conundum (d) Diamond (d) Bonon Cartille rypes of bond :-* Adhenive Substance what to hold assume grains together to form the Grinding wheel * Sufficiently smong to with stand Stresses * Their Choice - Grinding speed, cutting presses, hear formation etc. * TYRY :-> Metalic (i) Organic > vinified (v) Silicene (S) ? Resinced (B) (1) Non-organic - Rubber (R)

-> Shellac (E)

> oxy-chloride (0)

Grit (or) Grain Size!-

- Indicates the Size of the abrasive grains (or) Size of the cutting teeth of the Grinding wheel.
- Denoted by the number indicating the number of meshes per linear inch (25.4mm) of the Sieve through which the growing can ress through.
  - Larger is the grit number, smaller will be the Grit (or) Grain Size (or) vice-versa.

Grinding	Grit (or) Grain Size								
Coarse	(0	12	14	(6	20	24			
nedium	.30	36	46	54	60				
Fine	80	100	120	150	180				
very fine	220	240	280	320	400	500	600		

Grade:-

- Grade (or) Handness indicates the strength with which the bonding material holds the abranive grains in the grinding wheel.

Sof+	A	ß	<	.P	E	F	9	Ŧ		1
Medium	I	J	K	L	Μ	2	0	P		
Hand	æ	R	5	т	U	r	5	*	Y	2

STRUCTURE OF WHEELS!-

* Denotes the spacing blu abrasive grains (or) the desity of the wheel.

Structure	Symbol								
Duse	1	2	3	4	5	6	7	8	
open	9	10	-	12	13	14	15	more	

Designation of Grinding wheel!-

Sequence > Prefix Abrasive Grain Grade structure Bond Siffix 36 K R 17 A S W Mfr's abovie MfrsAb -marive type symbol tre (approved) Sympo) Dence (oriend) 1-8=) Dense A-Abo3 9-15=) den C-Sic Corre redium fine D-Dianard V- untified 10 30 80 B-Rennoid 36 (00 12 R - Rubber 46 120 14 E-Shellac 54 150 (6 S_ Silicate 20 60 180 24 0-otychloride (ade) scale) A-H=) lof+; I-P=) medium; Q-Z-Hand

Selection of Grinding wheels-

* quick stock hemoval high-class surface finish, close dimensional tolerances. * Parmeters () constant factors @ Wariable factors.

constant factors :-

- () physical properties of the material to be fround
- (2) Amount and more of south to be removed
- 3 Area -1 contact
- ( Type of grinding mile.

Variable factor 1:-

- 1) work speed (2) wheel speed
- 3 condition of the grinding rele @ Personal factors.

Reconditioning of Grinding meel:-

* wear? wheel loves its cuting carecing Loading glazing

* Avoid =) Dressing, Truing.







(iii) pecessed on one side











(iii) Tapered

(vi) claring cup

Ser. 71 12: 5 32

(rin) SAUCER typ



ipher Grinding wheel Standard Shapes of Some faces

Glazing of Grinding wheel !-

* Glazing of wheel is a condition inwhich the face of the grinding wheel takes a glats-like appearance. That is, the cutting points of the abhasives have become dull & Smooth due to its wear.

* Continued work with the glazed wheel increases the smoothness of the face & decreases its custing capacity.

> * Glazing of wheel takes place when a wheel () is too frand (2) revolves at high speed.

* Remedy for Glazing is to 1 to give optimum speed for the wheel. 2 to use a softer wheel.

Loading of the Grinting wheel!-

* the Grinding wheel may become loaded if the particles of the metal being ground will adhere to the face of the grinding wheel & fill up the parts of the wheel face. The adhered particles of the metal being ground with the face of the Grinding wheel Prevent the Grinding wheel to cut freely.
* Loading may be caused by (3)
(1) Grinding softer material
(2) Using a wheel of too hand a bond and numing it too showly
(3) taking cuts that are too deep & by not using the hight cutting fluid.
* The henedy for loading is

1) to show the wheel at optimum speed 2) to use a softer wheel.



* process of renowy Loaded Particles and breaking away the glazed Surface. by the tool called "dresser" in the

a blassive Particles are again Presented to the work Surface.

a) star dressing Tad b) Round abrasive stick c) Dramond dressing tool.

Truing !-

* Thing in the process of changing the share of the ghinding wheel as it becomes worn from an original shape owing to the breaking away of the abrasive particles & bond.

If this is done to make the wheel notate . the with its axis.

* It is also done to change the face contour for form Grinding.

* Truing & dressing are done with the Same books but not for the same purpose.

Mounted wheeld & Points !-Mouning of Grinding wheel !-- Flage 9 Shoft -sut metal The second secon Grinding wheel Types of Grinding Machines !-1. Type of operation - @ Tool @ cut-off Grinder 2. Quality of finish - @ Rough B Precision Ginter @ cylindrical (B) Internal 3. Type of S-rface -C surface a sprid purpose RAC., 70 floor stand yrinders Rough Grinderg > Bench grinders 3 Porsable grinders Abasive belt prinder E sing frame Grinder Cylindrical center type plain Grinder center type voiversal SIncernal Chucking type Ginder Cemerless precision Grinder S-rface Grinder Tool Surface and special Grinder



Precision Grinders:-Cylindnical Grinders !-> Plain type (1) center type Grinders ( > Universal type (i) centerless type grinders. Center type plain Cylindrical Grinder Grinding sheet wheel head weed week Tail Stock table • ۰ > Base Adjushade Table heversing frip dogs lever Various movements !! 1) Longitudinal feed along prideways of the bed. [Hand (or) Power) (2) Swivelling of UPPer table on the lower table [ lo' on either side ] 3 Rotation of a Grinding wheel. () The Movement of the wheel Ferrendicular to Table ways. by hand (or) Power. [cross-feed]



* Revolution of workpiece best the centers
* Swivelling of Head Stock in a horizontal plane
* Swivelling of upper table in a horizontal plane
* Swivelling of wheel head in a horizontal plane.
* Longitudinal feed. of the table
* coss-wite movement of the grinding wheel.
Types of operations in cylindnical Grinding active;(i) Traverse Grinding

(is pluge Grinding.


(0)

Centerless Grinders:quan theel to 10 Regularing wheel Regulation sheel Head Grinding Base - Regularing wheel wheel. * Method of - [33-130 Pm] Grinding exterior Grandert (1850men) Cylindnicol, taper sore nest & formed Surfaces (8. (max) on the wire that are not held & gidased on consers. * the sections wheel is included at arangkaf to permit the axial molement of 8'

in between the wheeld.

S= Transind



chucking type Internal Grinders! -According to general construction, there are Type-I 2 types. . W/P -> hotation (rinding) =) Rotation, wheel] =) longitudinal feet, cross-feed. (R-I up -> notations longituded

of wheel feed. Appation Grinding ] =) easting sheel ] =) cross-feed. chuck 9 Longitudinal feed of chuck.

plain Internal Grinder :- The workhead can be fuilelled to 49'.

2) niversel Internal Grinder:-

* work head - cross feed can be given & It is I welled up o go'.

planetary type Internal Grinders :-17 Movements [] Longitudinal (or) Reciprocating move - ment of Chuck. 2 Planetary motion & cross-feed of wheel. used for finishing holes for heavy Jobs that conit be conveniently rotated by a Chuck Convertess Grinding!-(least partial veel ressure + phessure god can be Granding Sworg for heading & wheel. Support enloading of whe ROY more means Ganding wheel = sections carrien, notation, Crois-feed.

Advantages of conterless Griding! -() As the wife is supported throughout its ensine length when grinding takesplace, there is no tendency for chatter (or) deflection of the work. 2 Small, fragile (or) Slender work pieces can be ground easily. (3) The process is continuous & is adopted for Production work (4) Less metal is removed due to floating condition. (5) no center toles, no chucking (or) mounting of work on mandhelp (or) other work holding devices are required. Disadvarages:-

In hallow workpiece, there is no certainty that the autside diameter will be concertric with the inside diameter.

2 work having multiple dianeter 13 not easily hardled.

Surface Grinding MIC :-* used to produce . & finish flat & plane Surfaces * Angular & formed Surfaces Heavy work pieces - fixture * Small work prece - Magnetic chuck TYPES [] Horizontal Spindle Reciprocating table Surface Grinder (2) Horizontal Spindle Rot Instace 10/10 Grinder (3) Vertical Spindle Recipros Sur Ginder Versical Spindle Rot ble Surface 4 Grinden torizontal Spindle Recipicating table Surface (minde Grinding meet wheel I inide ways Table Column

Horizontal Spindle Rotary table Surface Grinder:-Grinding where digeneel de notation O Rotation of wheel & cross-feed futed (2) Rotation of the table Vertical Spindle Recipiocaring table surface Grinder head Fasle - C. feed & Table L. Feed wheel - verical & gotation_ vertical Spindle Rotary Table Surface Grinder:used to grind

Lange q

large quarting of workpieces.

Unit-T

CNC machine Tool & Part Programming

Introduction !-

* Numerical control has been developed out of need for higher productivity, lower cost & more precise manufacturing.

* In ML System, opposition instructions are inputted to the machine as a code of numbers, letters, & special characters. These coded instructions are then automatically carried out in the machine tool in a predetermined sequence with Phe set speed, feed, etc., without human interlention.

NC & its components:-

* NC Stands for numerical control. It is a technique of automatically opreating the machine tool based on a code of letters, numberg and special characters.

* The complete set of coded Instructions responsible for executing an opprection is called as

" Part program".

* This Part Program is translated into electric Signals to delive Various motors to opreate the m/c to carry out the Required opreations.

* NC System contains the following components.

Program of Instructions
 Take Punch
 Take Punch
 Take Preader
 Machine Controller
 NL Machine.

O Program of Instructions :-

& The Program of instructions, often called Part Program is the detailed set of instructions for the Nic machine to produce a component. The Part Program is a mixture of Alphabetic Codes, numeric data & Special Characters.

* This Part Program is Punched in a input media (usually paper tape) in a specified format

* This input is head by a take header which converts the instructions on a Paper take into the electric Signally & transfers it to the mechine controlle to oprease the mechine Slides I to generate specific.

Surfaces on the job.	3
Part drawing	
writtenNe Program	
on Program Runched on take	Program of Instructions Sent to Nic machine
Tape Punch Micro Punch Punch Do 00 Lone	neader vic machine
Tape Punch:	( i width Paper
Mylay, Aluminium mylow (or) plastics	are also used as
a tape materials. * punching machine (flexo write	ers) of Various types
are used to key in Program of inst * presently tapes are prepare	d by micro-computers
by keying in the information from the . O once the entitle program has	been entered it in
Checked & connected if needed. 2) Then the computer actives	es the tage Built
Unit to produce the tape.	The total ronaling

3 the computer can also generate Print-out through its printer. (4) 3 Take Meader:-

A tape reader reads the hole pattern on the tape & converts the pattern to a corresponding electric Signal.

(4) Machine controller:-

* controller Receives the electric signals from the tape meader & causes we machine to respond.

* It contains a decoder/encoder, an interpolater and facilities to execute auxillary functions which are machine dependent.

* the decoder encoder necessies data & stones then in two separate memory locations. one for the part geometry data & the other for process data. Phocess data includes Switching functions for adjusting feed notes, spindle speedy, tool changes, cutting fluid applications etc., Geometric data Consists information about tool motion, tool length, tool radious, tool compens -ation etc.,

* The function of interpolater is to break down the curves (on) simple line into snew individual increments

olled fo 5 lzo nducerg ces de tool. of iong In ter alater Fol legent (or and to) Longer Leven Zeek hediew And: fier Ne Phogram Take Punch Tare gender Lefination Genetric Storage > Decoder (encoder) Georethic data to Po Sition Cervo Systemy Reference OPreating Panel L'PP4 inder can Severs Switching resument machine devices Data fron data to Coolon on off, Syon tool selection, Integace for Spindle Stead Technica etc., Controller Machine

Machine tool

5 NC machine :-

* NE machine responds to the electric signals from the controller. Accordingly the machine executes Various slide motions & spindle potations to manufacture a Part.

6

* Transducers are fitted to feed back () The A.P.M of the Spindle (2) the amount of cut on the job

It NC machine tools hange from single spindle dhilling machine to complex machines having multiple motions, tool changers, high capacity Tool magazines and multi axis control.

Position & motion Control in the machines-In the machine, there is a Servo control Unit which is a group of electrical, mechanical, hydraulic & Prematic denses used to control the Slide Position of the machine tool. The Servo Control Unit is Classified into two types. a) Open food Systen. open loop System:-



* It involves feeding of take, intrepretation of Information by a take header, storing the data in the buffer stohage. * After stohing, it is converted into electrical

* After storing, it is sent to the signal and the electrical signal is sent to the machine control unit [mcv]

* The control unit is connected to serve control Unit which controls the slide movement.

* In open loop System, there is no feedback to ensure devices whether the obtained Slide movement is some as desided (or) not and if not, what error is

Phesent.

Closed loop System:-

* It is similar to open loop System, but it carries an additional feed back device

* A feed back device is nothing but an transducer

a ccompanied by a comparaton.

* As this is similar to open loop system, the motion is some up to the Servio Control.

+ The transducer fed back the obtained Slide displace

It the comparator compares the obtained slide displacement with the applied slide motion and error if any, is fed back to the control Unit through an amplifier

to serve noton & the Cycle continues.



* the transducer used in the closed loop system is classified into two types.

> a) Analog transducen 5) Digital transducen

a) Analog transducer :-

* It Produces a Variable electrical voltage which Varies with the notational speed of the shaft. * This voltage can be easily measured and converted into the linear distances moved by the slides.

(9)

b) Digital transducer:-

* It converts the Robary motion of mechine Screw intro the countable electric pulses.

* The number of electric pulses indicates the linear distance moved by the table corresponding to the head Screw Rotation.

NC machine - Axis of notion :-

* The location of Nic tool at any Point in the Nic machine is mentioned by Cortesian Co-ordinate System. It Consists of X, Y, Z axes which are mitually Perpendicular to each other.

It the tic machine axis of movement follows the hight find hule.



(2) Rotation about an axis Ranallel to Yaxis is "B" (3) Rotation about an axis Ranallel to zaxis is "c"

* U, V, W axes are parelled to X, Y & z axes nespectively.

Classification of me system:-

O According to the motion control of tools in NC System.

Point-to-Point Ne System
 Straight cut Ne System
 Contouring Ne System

() Point to Point (PTP) System:-

* It hefers to the motion of tool at a faster have to a Point followed by a manufacturing opreation at that Point. The dimilling opreation is one of the opreation inwhich PTP System is adopted

* As Shown in figure, the tool is moved from a starting point to point 1 & drilling offen is done at Point 1. Then the tool is moved to Point 2 & Point & followed by the drilling operation at the connesponding Points.



(2) Straight line (or) Straight Cut SJStem:-

* In Straight cut NC, the tool moves Parallel to one of the major axis at a desired Note suitable for machining.

* It is not possible to combine the exis of motion. Hence the tool motion is only along X-axis, Y-axis, Z-axis. Due to this, Angular Cuts can not be produced in this type of machine. * example:-

Milling workpieces of he chargelow Profile

* Any NE machine tool capable of Straight Cut movement can perform Point-to-Point opreation also.



(3) contouring (or) continuous Ne System:-

* In this type of system, there is a nebtive motion between the tool 4 the workpiece.

* All the arcis of notion might note Simultaneously. Due to this, different curves to Profiles Can be Cut.

* Actually it is a combination of PTP & Straight Cut NE System

* An NC meetine tool capable of doing Contouring type NC opreationing capable of doing PTP & Straight cut NC opreationally.

example we milling machine control in NC

2 According to the tool Positioning (or) model of Programming a) Absolute Programing Ne system b) Incremental Programming Ne System.

a) Absolute Syster:-

* In this system, all the Position of the tool are measured from the same zero Point. * The following figure shows the Positions

of the tool measured from the same zero point



b) Incremental System: -

* An incremental System is one inwhich the Reference Point to the next instruction is the end Point of the Preceding opprection.

If the main digad variage of this System is that if an error occurs into the dimension of any hocation, all the location marked after that will carry the same error.

* The following figure shows the Verious Position of tool as per the incremented system.



Point 1= 10, 5; Point 2 = 10, 5; Point 3 = 10, 5

(3) According to the serve control Sylver, the NC System in classified into 2 types a) open loop control Sylten 7 It way 5) Closed loop control system J Pheviously discussed.

There are two types of zero point in NL machine.

Z. Cro Point -

1) Machine Zero Point 2 workpiece zero points fixed zero point > floating zero Point.

1) Machine Zero Point:-

* It is called as Reference Point. It is set by the manufacturer when the machine is manufactured. It is far away from the Spindle axis.

(7)

* USually after all the offeration is completed on the workpiece, the tool is brought back to the Reference point.

* Tool charging also is done after the tool 13 sent to the Reference point.

2 Workpiele Zero Point!-

* It is the origin Point from where on the Position of the tool & work table is defined. It is of two types

Fixed zero point
Floating zero point.

Stixed zero Point:Here, the origin is always predefined and fixed. Usually it is at lower left corner of the work table.
B Floating zero point:-

In modern Mic machines, Floating Zero

concept is provided, which allows the opreaton to define this origin. (18)

* In this type of machine, the operator can Set the origin where ever the want it to be set on the workpiece.

It the setting of zero point is done manually by the oppreator, by bringing X, Y& z axes to the point at which the origin is to be defined and by Pressing the zero button at that point.

NC Part Programming:-

* It is a set of instructions which instruct the machine tool about processing Steps to be performed to mann facture 2 component.

* There are three types of Programing techniques

Manuel Part programming
 Computer-Assisted Part Programming
 Manuel data input.

Manual Part Programming:-

# In manual Part Programming, the NL Part program nequired for a Particular Part is whitten by a Phogrammer. This Part Program is typed with a flexo writer where typing causes the typed paper and punched take to be phepared simultaneously. [9] Drawing Program by Take Punch Take Programmer Punch Take

* In a Part Program, each line of instruction is called as a block which is composed of one word (on) an amongement of words. Blocks may Vary in length [ie) they contain Variable number of words]. The block ends with end of block (eob) character. Each word is hephesented by an adhess followed by a number. (ex):- N30 G90 G01 × 30.0 Z-20.0 F150; T T T T T T T T T T

O sequence number (N code):-

This code (or) address is used to indicate the block number. The NL Part Program contains number of blocks. Each block is identified by the block number. N30 => Block number: 30. 2 Preparatory function (4-codes):-(20) * This codes inform the controller what type of action is to be carried out. * In general, G-codes is typed at the beginning of block after N-code So that it can set the control for a particular mode when acting on the other words in the Same block (on) all other Subsequent block. * G-codes may be model (or) Non-model. * For model type, G-codes specification will herain in effect for all subsequent block unless neplaced by onother G-code. * X1 Y, Z codes are used to indicate howmuch distance the tool (or) work table along a Particular dihection. 3 Feed have (F-code)!-This code is used to indicate the feed Note by which the tool (or) worktable shall move along a Particular diffection. It is interms of inch finite ( spindle speed (s-code): -

This code is used for the notation of the

Spindle at a Particular Mpm. 21) (5) Tool number (7-code):-It is used to indicate which took is to be used for a Particular opreation. ( Miscellaneous codes (M-codes): -* This codes are used to control the Party of the Nic machine ( spindle motor on at a speed of 1500 A.P.n) Ex:- N20 Mo3 31500; Mog ; 430 ( Coolant motor off) ( Tool should be changed ) by tool number : 2 ) MO6 TO2; N40 Computer Aided Part programming: -It In computer aided Part programming, much of the computational work needed in manual programming is performed by the computer processor * In this programming type, the programmer Phepares the set of instructions in the high level computer language which is converted to machine tool level program with the help of processor.

Manual Data input:-

* It is a procedure inwhich the part programmen diffectly keys in the program into the MCU of the mechine tool.

22

* Most of the modern ( we machine is having this facility.

* This facility helps the programmer to change any existing program before the machining opeations. Advantages of the System:-

* High Productivity due to less Set up & lead time * Less Scrap

As human errors are eliminated, Accurate components are produced. Hence Scrap is hedred.

- * High quality due to high accurery.
- * Flexibility in design In Nic System, Complicated Profile can be easily produced at a faster rate.
- * Reduction in inventory
- * Safety to the oprestor

Disadvantages of Nic System:

- * High initial Cost
- * High maintanence cost
- * Skilled opreator

for Part Programming, well trained and highly skilled opreator is required.

23

* The program can not be stored & edited. So for every program, take Punch Should be used.

CNC System:-

* CNL Stands for "computer numerical control". CNL machine is having computer attacked with machine control whit [mcu].

* Here, the Part programming can be fed into the computer memohy by Pendnive (or) tape purch. * The part programmes which was fed into the crie machine can be stoned & edited.

* The Part Programmes is converted into electrical Signals by the micro Processor in the computer.

The features of the Cric machine :-

( (athode May tube which is capable of simulating cutting parameters and show the positions of machine

table & the cutting tool before the Part is (24) actually loaded on the machine tool. Actual custing Position may also be shown when the part is being machined. The entine program also can be listed on the screen. 2) provisions of absoluted incremental programming which are incorporated by Ggo (absolute) and gas [incremental] codes. 3 Provision of inch (or) metric data input through Gto (inch) and GtI (metric) address. ( Availability of manual data input (MDI) to in corporate changes in part programming as & when necessary so lot of programmes can be stored and can be used as & when necessary. (5) Point-to-Point Systemy Straight cut System & Contouring path System are available in one CNC machine. 6 cutter diameter & Length compensations are in corporated. 7 Phorision of high Volume Program & data Storage area for furture storage & use are incorporated with hard disks.

- (8) Use of carned (or) fixed ydle programming to neduce complexity in programming (S allowed.
- 3 Incorporation of provision of Subroutine/sub programming and macros:
- ( Capability to create axes inversion ( minnon image) to Produce right (or) left thand Part from the same program.
- Digitizing to make Part Programming directly from the existing Part.
- (2) A program can be loaded in McU & here, dependency on take greader is eliminated
  - 3 Adaptable to both EIA on AscII take formets
  - Advanced interpolation methods like helical and cubic make it more versatile. In previous available we systems only linear, circular and parabolic interpolators are available.



Diffect numerical control :-

* It is a manufacturing System in which a number of machines are controlled by a central computer through a direct connection of tele communication lines.

27

* Instead of using a take reader as in NC machines, the Part Program is transmitted to the machine directly from the computer memosity. One computer an control more than 200 separate machines. * The Direct Numeric control System consists of

four components O cantral computer 2 Bulk menohy which stones NC Part Program 3) Tele commication lines ( Machine tools surractives kentrafkomputer Advantages of CAL machines:- VI E E E E

Advantages of cric machines are Similar to re

machine.	Some	additional	advantages	due	60	additiond

feature in CNC mechine are as follows.

1) Phogram Stohage As conduter is available, multiple programy can be stoned in the machine. 2 Reliability of Systen :-Any the data is directly entered with the help of computer, no need to use punched take. It imphoves the reliability of the System. 3) Online Part Programming !-The part program can be done online with editing if Required. ( methic (on) inches !-The program can be written in metric (or) inches through G70 (inch) & G71 (metric) address. (5) Inter Polations: -In Mc System, there is interpolation for straight and circular path, but in CNC, helicaf, Parabolic and cubic interpolation also can be made (6) Tool compensation :-
For the purpose of tool offset & tool wear, (29) cutter dianeter & its keyptin compensation are available in chic machine (7) Axis inversion !capability to create axes inversion (minnor image) to produce right (or) left hand Part from the same program. ( carred (fixed) cycle !-Use of conned (fixed) Cycle Programming to reduce complexity in programming is available. Digadvantages of care machine :-() High initial cost 2) High maintanence cost. 3 Costly control system. @ need of skilled opreator for Part Phograming. (5) whole machine will stop functioning if there is my problem in computer Costly Software 6

Advantages of Dar System:- 30				
0	Control of mohe than one wir machine			
2	Elimination of Runched take & take reader			
3	Convenient Stopage of Nic Part Programy in			
	Computer files.			
Ð	Greater computational capability & flexibility			
5	The data for tools & cuttery can be certally			
	maintained & updated.			
6	The data related to manufacturing can be			
effectively collected & hence inventory can be				
better controlled				

Digadvartages of Dric System:-

- If the central goes down, all machines becomes inactive
- 2 Initial cost is too high.

Comparison between Ne, Crie & DNE Systen: -3)

sl.no	Parameters	NE	CNE	DNC
۱.	Flexibility	Less	High	High
2.	Take editing	Not Possible	Possible	Possible
3.	Phoductivity	Less	High	Hiphen
۴	Number of Phogramy Stoked	only one at a time	multiple Programs	Multiphe Phograns
5.	Number of oprections done at a time	one	one	multiple
6.	Initial cost	دما	Hiph	Higheyt

Various .. Nic machiness-

- ① Single spindle dhilling machine
- 2) Latre
- 3 milling machine
- ( Turning centers

(5) Machining Centers Horizontal mechining center ( Vertical machining center

[] Single spindle dhilling machine! -# It is the most simple NE machine. * It is programmed on three axes. X-axis -) Toble movement to the night (0.) left of the column Y-exis -> Table movement towards (or) away from the colomn Zaxis - ) UP & down movement of the Spindle (2)Lathe !-* Machine tool to man facture & machine hound Party * It is Programmed on two axes. X-axis -> Cross notion of the culture tool. z-ears -> Comape travel towards (or) away from the Head Stock (3) Milling machine !-* Accepted -) one of the most Vergetile machine

tools used in the manufacturing industry.

(33) * It is programmed on three axes. X-axis -> Table indepent left (or) right of the column Yakis -) Table advent towards log away from the Column. Zaxig - ) up & down molement of the SANdle (4) Turning Centers: -* Turning centers are more accurate and Productive than engine lathe & hay a higher standle note. * It is having Turnet tool head which can accordate 12 Tools and as such can produce wide range of componenty without tool charge. * It is programmed for two axes. x-axis -) Cross wige movement of the Tool zaxis -) Movement of the Tool towards Ear) away from the head stock.

(5) Ne machining centers:-

Machining centers are of two types

0	Horizontel	l machining	center (HMC)
2	Vertical	machining	center (VMC)

Machining Center are capable of a Variety of machining operations. For this headon, a variety of tooks are hequired in a machining center. thus a machining center must have Automatic took changer (ATC); Automatic Paulet changer apart from other Parts.

( Horizontal machining centers (HMC) !-Yax's Serve - Tool mapszine Horizonto Spindle (4) 24) Teble

* Horizontal machining center (HMC) has horizontal Spindle Read. Here the following movements are there () X axis for table movement (33) (2) Y axis is for Vertical movement of the spindle (3) Z axis is for horizontal movement of the spindle Rependicular to X & Y axis.

* In this machining Center, tool mapazine which holds lot of tools is there and Automatic tool changer is there. After completing one operation, Automatic tool changer gremove the old tool from the spindle flead & fix the new tool into the Spindle flead.

- * Horizontal machining center may be fixed column type (or) thavelling column type.
- * Fixed Column type Carries a genolable table Called as Pallet
- * After machining, a powet with a component is thenoved & another power which was altheady loaded with the workpiece is then clanged

on the pallet necesser & machined.

In travelling column type machining center, there are two tables. After machining, components are on one table and column thavens to the Second table which carries a fresh workpiece for machining.
* Components which is to be machined is unloaded from the first table & a fresh workpiece is loaded on it.

# Machine comes under this lategory D CNC Horizontal milling machine (2) CNC Grinder. etc.,

Vertical machining center:- [rmc]

* these machines are generally single spindle machine.

- * Vertical machining Centers has
  - ( or ) right
  - 2 Y-axis control for the table movement towards (or) away from the column
  - 3 Z-exil control for the Vertical movement of the spindle

* It carries a Vertical Spindle man zine Vertical Westing 1/2 Read which can slide along a vertical guide ways provided on the column. (37) * It has tool mayzine, bool thansfer arm, Automatic Pallet changer etc., Table (E2): - CNC Vertical milling marching, Crie drilling machine etc., Advantages of machining center:-O machining centers have high metel removed note Capabilities (2) Machining centers are highly versatile and in creases productivity. (3) It is more plexible and economical that conventional machined. (4) It is mainly used for mess production. Automatic Tool Changer (ATC)!-In order to reduce the time for changing over of tools, mechining centers are Provided with automatic tool changing facility. It is done by

Automotic tool changer (ATC) whit of the mechining Center. The ATC consists of the following two Whith (38)

() Tool mapazine (2) Tool transfer arm

Tool mapazine !-

It is a tool stoping whit, attached to the maching center. It contains number of Pockets (from 10 to 400) to hold number of tools. Each tool is inserted into the Pockets and numbered. To select the grequired tool, in the Part Program these numbers are denoted.

The tool pockets are amaged in drum (or) Chain. Based on that, it is classified as " drum type tool mapazine" and " chain type tool mapazine".







b) chain type tool mapzine

Tool transfer Asim! chain type tool mogazine 39 O Lange 180° to load & unload thereugh 180° to the tool from the spindle 0  $(\mathbf{0})$ D 0 4 Table O 0 O spindle O

It tool transfer arm is used to pick the tool from the tool mapazine & the spindle and fix the new tool to the spindle & fix the old tool to the tool mapazine by hototing through 180°.

* As per the part Phoppen instruction, after one opreation is over, the mage zine indexes to the next tool Position. Then one end of the tool transfer arm picks the grequired tool for next opreation from the tool mage zine and the another end of the arm picks the old tool from the smalle then it will notate through 180° & fix the new tool to the spindle & old tool to the tool mage zine

Automatic Pallet Changer :-

40

* Machine downtime because of loading-unloading, clamping-helpsing of the workpiece can be minimized with the kelp of automatic workpiece loader/unloader System.

* In this Sistem, the workpieces are nounted on the pallet and the Pallets are noted around the machine in a logical manner. This system is called as "Pallet Changing System".

* According to the logical movement of the Pallet, the System can be linear (or) gotang.



- * In the fig (a), the workpiece on the left side thack is waiting for completion of machining oppreation of earlier workpiece. (41)
- * In the fig(5), after completion of earlier warepiece it moves onto the unloading table and the next component is neady to move onto the machining table.
- * In the fig(c), the next Component mokes onto the machining table and this phocess Continuous.



* In this pallet charger Sister, the number of fallety one changed on the notating table.

It for the machining Purpose of the workpreces, the table is moved in noting motion with the help of indexing mechanism.

Canned cycle (on) Multiple cycle (on) fixed cycle:-

A canned cycle is a combination of tool movements that Performs any one particular machining function such as drilling, boing, turning etc., This cycle automatically generates multiple movements from a single block. (42)

Ez:- multiple turning clayle & finishing cycle

GFI U = R = iGFI P = R = -iGFI P = R = -iGFO P = R = -i

where, U -> Depend of cut for each Pass along x-axis R -> Retraction amount in x axis. P -> Starting block; R - Ending block; U -> Stock in taxis U -> Stock in taxis F -> feed hate G71 -> Multiple Rough turning click G70 -> Multiple finish turning click Subhoutine (or) sub programe:-

when a component has repetitive pattern machining at different places, in stead of writting the Same program each& every time, the Program for the repetitive opreation is written & stoned in a separate file & is called wherever needed. This program is called as "Sub-programme".

(43)

Syntax for Sub Program

M98 00112341

M99; M99; M98-Subprogram cau; 001 - No of nefects;

1234 - Sub Program number; Mgg - Sub program End.

Interestation :-

It is the method of specifying the Path to be generated for machining. There are the following types of Interpolation. () Linear Interpolation (2) Circular Interpolation (3) Helical Interpolation (6) Cubic Interpolation.

(5) Parabolic InterFolation. () Linear Interpolation :-* It is used when a straight line path is to be generated on the workpiece of NZ machine. * The linear path can be Horizontal, Vertical (or) Inclined. * the G-code - Gol is used for linear interpolation 18 four Parameters [x, y, z &f] are required to specify Gol code. Syntax for Gol :-Go1 X_Y_Z_F_; x = Value for x co-ordinate y = value for y co-ordinate 2 = Value for 2 Co-ordinate F = feed rate ezample:-(20,20) ~~~ Gol X 20.0 yo.0 Z -1.0 F1.5; X 20.0 Y 20.0 Z-1.0 ) x0.0 y0.0 2-1.0;

Of ircular Interpolation:-

# The movement of the tool along a circular path is called as " Circular Interpolation"

# Five Parameters are required for specifying the G-code used for circular Interpolation [G03 (07) G02]

# Go3 code is used for making the circular path in counter clockwise direction and Go2 code is used for making the circular inter-Polation in a clockwise direction

* Syntax for Go3/Goz Lode:-

Go2 ( go3 X - Y - Z - R - F - ;

x, y, z -> co-ordinate values; R > Radions of the Athc; F > Feed note in mm[nev (or) mm[minute.





(3) Helical Interpolation:* The notement of the Cutting along a
Helical Path is called as "Helical Interpolation".
* To marke this interpolation happens the cutting
tool is noted Simultaneously along 3 axis X, Y&Z.
* It is mainly used for making hero Parts.
* By means of Helical interpolations any bigger dia
hole can be made with Smaller diameter tool

with less torquess less power.



Producing a bigger hole with a Smaller dea Tool

slide movement in cric machines:- (47)

Precise Positioning and refeatability of mechine tool slides are the major functional requirements of Cric Machines. A Plain Slide way will give stick -slip. To Prevent this, there are different slide way systems are used. These have low wear, negligible stick slip, good damping capability low co-eff of friction Properties.

Requirement of a good slide way system:-

12 Low coneff of friction (2) Low note of wear

(3) Must have good danping capacity

(4) Must give a smooth drive.

(5) There must be no stick-slip.

In Cric machines, the following slide ways type may be used.

> a) plastic inserted Slide ways b) Recirculating ball Screw&nut type Slide ways.

a) Plastic inserted slide ways

In this slide ways, plastic inserts are bonded to the Underside of the sliding members. The inserts can be thermo plastic (or) thermo setting types. For these coated slide ways, the friction is less.

* Recirculating Ball screw & nut arrangement are used to transmit motion to the Slides.



* It consists of screw thread which acts as bey gave to hold steel balls. The balls are surrounded by a nut.

* The balls Rolling in the phooves exit from the trailing end of the nut and are picked up by Return tupe inserted from outside and are recirculated into the leading end of the nut.

* the notation of the ball between the screw & the nut moves the slide attached to the nut.

* Here the Sliding Contact between the screw of nut is changed into the Point contact due to the Steel ball. So, the Friction & herce wear is Reduced.

Advantages! O Very law co-eff of friction (2) Higher transmission efficiency (3) No Stick-Slip. (4) Backback between the Parts are eliminated by

Pheloading the assenbly.

5 Reduced friction & hence wear.

Tool offsetton) compensation:-

* the word offset refers to the allowence made by the (NC machine for the hadious & length of the tool to cut the job. Programming on a CNC machine is always done according to the center point of the cutter. If the offset is not sets the tool will follow a wrong Path.

50)

* since the diameter & length of a tool may vary, on offset value needs to be set so that the tool can be moved to the contract position for the culture Required.

* For example, if you were using a lorm Cutter the workpiece would be reduced by 5mm on each edge (or) (orm overall. To overcome this the, the hadiogs of cutter is given as a compensation.



Tool length offset (01) Tool length compensation :-

Normally, Part Programmes are Prepared for a Particular tool length. The Variation if any in a tool is piven in the form of tool keypth offset and it is the difference between the Phogrammed length and actual length of the tool. The same will be taken into account by the machine during areation.

51

example:-

943 H1 ZIO;

* HI hefers to tool length compensation of tool one, which has a Value of -3.000 in the offset table * A minus Value increases the tool length whereas the Positive Value decreases the tool length. (or) diameter Tool Madious compensation:-(or) diameter they the tool hadious is given as a compensation value (41 - Cutter radious compensation to the left (42 - Cutter radious compensation to the gight 440- cancels the cutter hadious compensation.









Formulaes used for calculating the slide movement:-



open loop System Each pulse makes the Stepping motor to gotate at an angle (or) a fraction of herolution Step angle, d = 360; N-> NO of Pulses frequired for 1 herolution of Stepping motor.

Let n -> Total no of pulses received by Stepping motor (2) made by the A => n x (360) Stepping motor) 53 for 1:1 Sear harro between lead screw & motor shaft 3 mo of nevalution = n () If the pitch of the head such is P (in Mer), then the distance made by the worktable (X) axially  $X = P\left(\frac{n}{2}\right)$ (5) pulse frequency (f) in pulses [see is given by f= NXRPM 6 Speed of the worktable, V= PXRPM in min Problem ! -A stepping motor that N= 150, P= 0.2" (nev; 0 If n= 2250 Pulses, what is the distance that led in × direction? what should be the pulse frequency for a travel speed of 16 m/min?

Soln'-1) Distance travelled by } X= P (A)  $= 0.2 \left( \frac{2250}{150} \right)$ X= 3" Pulse frequency f= N(RPM) 2  $= \frac{150 \times \left[\frac{v}{p}\right]}{60} = \frac{150 \times \left[\frac{16}{0.2}\right]}{150 \times \left[\frac{16}{0.2}\right]}$ = 150×80 = 200 HZ 2 A stepping motor of 200 steps prevalution, is mounted on the lead screw of a dhilling machine. It the pitch is 0.1" (hey & f= 2000 Hz, what is the speed of the table? ≤dn:-→= 200; P=0.1" | her; f=2000 Hz; RPM=? f = N(RPM)- RPM= 60xf = 60+2000 = 600 91Pm

problems in a closed loop System

(3) consider a cric worktable driven by a closed loop control system consists of a Servo motor, lead screen Roptical encoder. The lead Screw has a pitch  $P = 0.2^{11}$  and is compled to the motor shaft with a screw to motor geor statio of 1:4. The encoder generates iso pulses (nevolution of the lead screw. If the no of pulses (nevolution of the lead screw. If the no of pulses & pulse nate necessed by the control system are 2250 & 200 Hz respectively, calculate

(55)

a) Table speed b) motor speed in n.P.m () Distance travelled by the table

Soln:_ N=150 Pulses / nev; pitch of lead screw ) P=0.2"/nev

- n= 2250; f=200 Hz;
- (i) RPM for toble & motor = ? (ii) Distance by tosle ancielly X=?

f= N(RPM)

RPM2 60+f 60+200 = 80 rpm. of the table

motor shaft) = 4 × 80 = 320 91PM.



56

NC Part Programming Important 4-codes and (57) Goo - Rapid traverse :-0 Syntax: - Goo X Y Z (millig) 400 × 2 ( Turning) (2) Gol - Linear Inter Polation :-(milling) Syntax: - Gol X Y Z F GOIXZF (Turning) F -> Feed have GAS - Go to Reference Point 3) u → 600 to reference(x) Syntax 428 00.0 w-) go to reference (z) 928 woo ( 403 402 - Spindle oncew & cw SYN+0+:- G03 402 - X Y Z R F 200 aw (1 Freed name 402

490 - Absolute Dimensioning Gai - In cremental Dimensioning 420 - Imperiol Units 921 - Metric Units 998 - Feed minute Gqq - Feed grevelution.

58)

M codess-

Mod/ Mos - Spindle on CCW & CW respectively Mos - Spindle Stop. Mob - Tod Chaye Mo7 - Codent on Moq - Codent off Mzo - Program Stop and Setum M98 - Sub Program Call M99 - End of Subprogram

Multiple carned cycles:-1) Turning cycle! BLOCKO G71 U - R - > BLOCK @ GAT P_ Q_ U_ U_ 8-1 Block 3 G70 P _ Q _ F _ ; stores G71 - Rough turning cycle 470 - Finish turning cycle Block U -> Depth of cut for each Fass. R - Retraction amount at the end of each Pass. Brack . P-> Block Number for start of open e ) Block number for End of open U -) Stock in X 2X:3 W -) Stock in 2 axig

F -> reed state

* Feed some for finishing cycle should be less.

Grooving cycle:-

975 R 0.5

975 ×40 2-10.0 PS00 \$1300 F0.05

R -> Retraction amount P > Depth of cut - Peck amount (micans) a ) movement along z direction (microns) F-> reed in mm/her

Drilling cycle:-

474 Ro,5

674 2-50.0 ×0.0 \$500 FO.2

- R-) Remaction
  - a) Depth of cut Reck amount [microns]
  - F-) read in malaey

Multiple facing Cycle!-

Block: 1 G72 " WO.25 R 1.0 ;

Block: 2 972 Plo & 11. UO.O W O.S FO.S;

Block: 3 (30 PIO QUI FO.25)

NO Goo 20.0%

NU 401 X0.0%

Black :1	w->	Depth of	cut along	Zaxis
	R->	Retraction	'mound'	

Black: 2 U, w=) Stock along x & Zaxis Respectively

G30 - finishing cycle

CNC Part Programming

Write a Manuel Part Program to turn the Component Shown on a civic Lathe from Tomm bar stock. The following Date may be assumed.

(a) there will be two rough turnings and one finish turning. The first cut is with a depth of 3mm for a length of 58mm. The second with a depth of 3mm for a length of 59mm and the third with a depth of 1.5mm for a full length of 60mm.

(b) the shoulder of the workpiece is also machined during each cut.

(C) the spindle speed is tooppon and the feed state is 0.5 mm/hev.

Make a free hard sketch showing relevant tointy of tool position for each of the twee turning opening and then write the manual tart program. State also that each line of the program does.

01234 [ Billet X75 Z 100 G28 00.0 ; 428 wo.0 ; 921 999 690; Mab Tolol; May Sta ; MO7 ;

400 262.0 ×76.0;

(63) [ go to reference point] [ Metric Drits & reed Preve Absource [ Tool change : old offser no: 1 [spindle on ccw; speed = qoorpm] [ coolam on ] . [ Rapid traverse]

471 00.25 R1.0; (71 Flos RIOI UD.0 WO.0 FO.5) N100 901 X 69.0% H101 2.2.0%

G71 00.25 R1.0; (71 Ploz Q103 U3.0 Fo.s; w1.0 G70 Ploz 2103 F0.25; N102 Gol X60.0% N103 20.0;

Mosj

Mog;

928 00.0%

(28 wo.0)

M30

[ program Stop & heturi]

[ Spindle off]

[ Coolant off]

Roughting: 1 Multiple Rough turning cycle to a depen 3 mm & length 58mm

> Rough turning: 2 deptn:-Jm Length:-59mm G70->Finish turning for depun = 1.5 length = 60m

[ program member]


( program number) (65) 01234 EBILLET +20 280 428 00.0; ( 40 to reference point) [Metric Units & Feed / Step ( Tool Charge) & Absoluterg G28 W0.0 ; 421 499 690; Mob Tolol; ( spindle on ccus) M04 51000; Moz; ( coolant on ) 400 x0.0 20.0; (Rapid traverse) (Point B) (Point C) Rough (Multiple, timing cycle) ×30.0 Z -20.0; X 30.0 Z-60.0; (71 Jo.25 R1.0; (31 Ploo @ 200 UO.5. WO.S FO.5; (multiple finish turningycle) G20 Plos 2200 F0.25; N100 GOI × 10.0; (Linear Interpolation) Z-25.0% N200 401 X20:0 Z-20.0; Mosi (spindle stop) Mogi ( Coolant off) 928 00.0j (40 to Reference Point) 428 wo.0% ( Angran Stopd Menn) M30; A norm long cylindrical good of \$75mm is 3) be turned into a component of shown in fig using a Cric Lathe , write a Cric program for manufacturing this component.





01234 975 RO.5% BILLET X 35 285 475×20.02-55.0P50021500 F0.05; 921 999 990% 928 vo.0; G28 00.0; 928 wo.oj 928 wo. 0; Mob Tos; Mob Tol; Mo3 S1500; Mo7; 400 ×31.0 22.0% 400 × 35.022.0; G71 U0.25 R1.0; GAI PIORII U0.25 W0.25 FO.5; (92×29.52-50.0F1.2; (70 PID RII F0.25) (92×29.0; NIO 401 × 30.0; 492 × 28.5; Go1 2-75.0% NA GP2 × 28.44; 62800.0; 428 00.0% G28 w0.0 ; 428 00.0% Mob To2; Mob TO3; Goo × 0.0 22.0; 400 ×31.0 22.0; 474 Ro.s; 400 2-52.0j 474 2-25.0 2500 FO.2; 428 00.0; 428 wo.0; Mos; Mog; M30;



- 01234
- [BILLET X30 Z 60
- 421 999 990;
- G28 00.0;
- G28 wo.0;
- Mob Tolol;
- M03 S1000;
- MOTI 230.0 22.0; GOO 230.0 22.0; GTI 00.25 RIO;
- G71 Plo0 2200 U0.25 W0.0 FO.5; G70 Plo0 2200 FO.25; NO0 G01 × 10.0; NO0 G01 × 10.0; NO0
  - ×20-0; 2-25.0;
    - ×25.0)
  - 472 W 0.25 R 0.5;
    - 432 PIOI 2111 UD.0 00.25 FOS
    - 470 PLOQUE0.25;

- NOTE: 6121 Pao in mm GIQQ: Feed since / Siev GIZI, Hultiple Tuan
  - cycle-

- NIOI GOI Z-1.0; NIII GOI X0.0; G28 00.0; G28 00.0; MOS; MOS; MOS;
  - M30;

CHE MILLING
(69)
G-codes
G94 - reed (min
995 - reed Prev
M- codes
M98 - Sub Program call
M99 - End of Sub Program
1) write a CNC program for the following
Profile
BILLET X100 Y100 25
[ Tod Def TI DS
SAT IN
421 694 690 G54; (x4) 200 x
428 WO.0; 100
928 UDio VO.0 j 12t
MOGTI;
M03 S1000;
G00 x25.0, 425.0 25.0;
401 Z-1 F60.0%
Gol x25.0 475.0%
x65.0 475.0%

(183 ×25 ×25 Z-5 QIRO.5 F40K1)

Goo ×25 ×25 22;

MO7;

M03 5800;

MO6 T3;

928 VO.0 VO.0;

928 WO.0;

421 994 990 G542

BILLET X100 YIOD ZIO [ Tool Def TI DS [ Tool Def T2 DIO [ Tool Def T3 D20

3 write

454 - offset no 494- Feed) min 490-Absolute Progr 421 - Metric Units



CNL

2

Program for the following Profile



3 Write a Part Program for drilling holes for the Part shown in figure. The plate thickness in



( write a program so drill five lde in the five

location.



write the cuic milling program for the componen Shown using Marrowing command.



BILLET X 100 Y 100 Z 10 [ Tool DEF 71 DS [ Edge more X-50 Y-50 421 494 454 690; 428 wo.0; G28 U0.0 VO.0% MOG TI; Mog Si000; Mog ; Goo xo yo zs; M98 P0011234; M70; M98 Pool 1234; M80;

(91)  $(90 \times 10 \times 10)$   $(91 \times 2-6 \times 50)$   $(91 \times 20 \times 0)$   $(90 \times 20 \times 90 \times 20 \times 30)$   $(91 \times 0 \times -20)$   $(91 \times 0 \times -20)$   $(90 \times -10 \times -20)$   $(90 \times -10 \times -20)$   $(90 \times -20)$ (9

Sub mogran 1234

Model for minhoring!-- Laxis Minhor on M70 M80 - Xaxis Minnon off - Yaxis work on M71 - Yakis Minnor off MPI

continuention of the program

M71;

M98 Pool 1234;

M81;

MZO;

M71

M98 POD11234;

M80;

M81;

G28 60.0%

428 vo.0 vo.0;

Mosj

M09;

M30;

write the CNC program for the Profile shown below



01234 [BILLET X 63 Z 130 G28 UD.0; G28 UD.0; G28 WD.0; G21 G99 G90; Mob Tolol [Tool Change to Tol-Sigle Point Tool] Moy S 1000; M07; G00 X 63.0 Z 2.0;

APT Programming:-

* APT means automatically programmed Tools.

* To program in APT, the workpart Geometry must first be defined. Then the tool is directed to Various point location and along the surfaces of the workpart to carryout the machining opreations.

* there are four types of statements in the APT

Degenerge Statements () Geometry Statements () Motion Statements () Post Processor Statements () Auxillory Statements

() Geometry statements:-

a points, fines, circles etc., of the work Part.

Syntax of Geometry Statements

Symbol = keyword to define the | co-ordinates to define seonerry | the geometry.

Ezemple:- PI = POINT (20,30,0

It defines the co-ordinate (20, 30, 0) as a Point

and assign the same to "Pi". 2) Motion Statement !--It describe the path of the cutting tool. Syntax:motion connand keyword / co-ordinate Resition erander O GOTO PI 2 FROM PO (3) Post Processon Statement:-It is used to control the oprestion of the spindle, feed & other features of the machine. Syntax:-Post Processon keyword nelated data ezaneles O SPINDLE/450 [Spindle Speed = 450 91Pm] [ tead note = (- 5 mg nev] 2 FEDRAT 1.5 (4) Auxillary Statement:-It is used to specify other details like cutter size, tolerance and so on.





1) Write the APT Program for Following Profile



(Geometry definations)  

$$P_0 = P_0 INT | 0, -10, 0$$
 [Initial cutter resition]  
 $P_1 = P_0 INT | 10, 30, 10$   
 $P_2 = P_0 INT | 10, 10, 10$   
 $P_3 = P_0 INT | 30, 20, 10$ 

(Preprocessor (Antillary definations) 82) SPINDLE S50 [ Takes the spindle speed 550 n.P.m) FEDRAT 11.5 [ feed note = 1.5 m [ner] COOLT (ON [ coolant motor on] CUTTER/18 [ 18m die duillbit] [ MOTION STAtements] FROM PO [ Tooks Starts from Po] GOTO PI [ Tool go to PI] GO DLTA 0,0,-00 [ Dhilling takesplace at PI to a 40 DLTA 0,0,+10 depth of - womm] GO TO / P2 [Drilling of hole at P2] 40 SLTA ) 0,0,-0 [ Tools travels back) GODLTA 010, +10 40 TO |P3 40 DLTA 0,0,-10 GODLTA 0,0,+10 4070 PO [ Finishes line of the proprint] FINI





$$MACHINE/MILL
SP = POINT/0,0,0
LI = LINE/4,2,0,4,8,0
PT = POINT/4,8,0
L2 = LINE/4,8,0
L3 = LINE/PT, ATANGL,45
L3 = LINE/8,12,0, 12,12,0
L4 = LINE/14,5,0, 14,10,0
L5 = LINE/4,20, 12,2,0
C1 = CIRCLE/12,10,0,2$$

C2 = CIRCLE/14, 20, 3 INTOL 0 out Tol 0.005 CUTTERIS SPINDLE 2000, CCW COOLANTION FEDRAT 20.0 FROMSP Golto, LI [ Until it is just targent to LI TLLFT, GOLFT/LI, PAST, L2 GORGT/L2, PAST, L3 GORGT L3, TANTO, CI GOFWER/CI, TANTO, LIF GOFWD/L4, PAST, C2 GORGT (C2, PAST, LS GORGT/LS, PAST, LI GOTO SP COOLNT OFF SPINDL OFF FINI .