

# STELLA MARY'S COLLEGE OF ENGINEERING

(Accredited by NAAC, Approved by AICTE - New Delhi, Affiliated to Anna University Chennai)

Aruthenganvilai, Azhikal Post, Kanyakumari District, Tamilnadu - 629202.

## ME8491 ENGINEERING METALLURGY (Anna University: R2017)



*Prepared By*

**Dr. J. JENIX RINO**

**Professor & Head**

**DEPARTMENT OF MECHANICAL ENGINEERING**



# STELLA MARY'S COLLEGE OF ENGINEERING

(Approved by AICTE, New Delhi, Affiliated to Anna University, Chennai  
Aruthenganvilai, Kallukatti Junction Azhikal Post, Kanyakumari District-629202, Tamil Nadu.

## DEPARTMENT OF MECHANICAL ENGINEERING

### COURSE MATERIAL

<b>REGULATION</b>	<b>2017</b>
<b>YEAR</b>	<b>II</b>
<b>SEMESTER</b>	<b>04</b>
<b>COURSE NAME</b>	<b>Engineering Metallurgy</b>
<b>COURSE CODE</b>	<b>ME8491</b>
<b>NAME OF THE COURSE INSTRUCTOR</b>	<b>Dr. J. JENIX RINO</b>

### SYLLABUS:

#### UNIT I ALLOYS AND PHASE DIAGRAMS 9

Constitution of alloys – Solid solutions, substitutional and interstitial – phase diagrams, Isomorphous, eutectic, eutectoid, peritectic, and peritectoid reactions, Iron – carbon equilibrium diagram. Classification of steel and cast Iron microstructure, properties and application.

#### UNIT II HEAT TREATMENT 9

Definition – Full annealing, stress relief, recrystallisation and spheroidising – normalising, hardening and Tempering of steel. Isothermal transformation diagrams – cooling curves superimposed on I.T. diagram CCR – Hardenability, Jominy end quench test - Austempering, martempering – case hardening, carburizing, Nitriding, cyaniding, carbonitriding – Flame and Induction hardening – Vacuum and Plasma hardening.

#### UNIT III FERROUS AND NON-FERROUS METALS 9

Effect of alloying additions on steel-  $\alpha$  and  $\beta$  stabilisers– stainless and tool steels – HSLA, Maraging steels – Cast Iron - Grey, white, malleable, spheroidal – alloy cast irons, Copper and copper alloys – Brass, Bronze and Cupronickel – Aluminium and Al-Cu – precipitation strengthening treatment – Bearing alloys, Mg-alloys, Ni-based super alloys and Titanium alloys.

**UNIT IV NON-METALLIC MATERIALS****9**

Polymers – types of polymer, commodity and engineering polymers – Properties and applications of various thermosetting and thermoplastic polymers (PP, PS, PVC, PMMA, PET, PC, PA, ABS, PI, PAI, PPO, PPS, PEEK, PTFE, Polymers – Urea and Phenol formaldehydes)- Engineering Ceramics – Properties and applications of Al<sub>2</sub>O<sub>3</sub>, SiC, Si<sub>3</sub>N<sub>4</sub>, PSZ and SIALON –Composites- Classifications- Metal Matrix and FRP - Applications of Composites.

**UNIT V MECHANICAL PROPERTIES AND DEFORMATION MECHANISMS****9**

Mechanisms of plastic deformation, slip and twinning – Types of fracture – Testing of materials under tension, compression and shear loads – Hardness tests (Brinell, Vickers and Rockwell), hardness tests, Impact test Izod and Charpy, fatigue and creep failure mechanisms.

**TEXT BOOKS :**

1. Avner, S.H., “Introduction to Physical Metallurgy”, McGraw Hill Book Company, 1997.
2. Williams D Callister, “Material Science and Engineering” Wiley India Pvt Ltd, Revised Indian Edition 2014

**REFERENCES:**

1. Kenneth G. Budinski and Michael K. Budinski, “Engineering Materials”, Prentice Hall of India Private Limited, 2010.
2. Raghavan.V, “Materials Science and Engineering”, Prentice Hall of India Pvt. Ltd., 2015.
3. U.C. Jindal : Material Science and Metallurgy, "Engineering Materials and Metallurgy", First Edition, Dorling Kindersley, 2012
4. Upadhyay. G.S. and Anish Upadhyay, “Materials Science and Engineering”, Viva Books Pvt. Ltd., New Delhi, 2006.

**Course Outcome Articulation Matrix**

<i>Course Code / CO No</i>	<i>Program Outcome</i>												<i>PSO</i>		
	<i>1</i>	<i>2</i>	<i>3</i>	<i>4</i>	<i>5</i>	<i>6</i>	<i>7</i>	<i>8</i>	<i>9</i>	<i>10</i>	<i>11</i>	<i>12</i>	<i>1</i>	<i>2</i>	<i>3</i>
<b>ME8491 / C213.1</b>	3	2	1	1	0	1	0	0	2	3	0	3	3	3	1
<b>ME8491 / C213.2</b>	3	3	2	1	2	1	2	0	2	3	0	3	3	3	1
<b>ME8491 / C213.3</b>	3	0	1	0	0	1	0	0	2	3	2	3	3	3	1
<b>ME8491 / C213.4</b>	3	1	1	0	0	1	1	0	2	3	2	3	3	3	1
<b>ME8491 / C213.5</b>	3	3	3	3	2	3	0	1	3	3	0	3	3	3	1
<b>Average</b>	3	2	2	1	1	1	1	0	2	3	1	3	3	3	1

## Introduction :-

UNIT - I

The Process or act of measurement consists of obtaining a Quantitative comparison between a Predefined standard and a Measurand. The standard of comparison must be of the same character as the measurand, and usually but not always is Prescribed and defined by the legal (or) recognized agency (or) organization.

Such Quantities as temperature, strain and the parameters associated with fluid flow, acoustics and motion, in addition to the fundamental Quantities of mass, length, time and so on, are typical of those further the scope of mechanical measurement.

"Measurement is also a fundamental element of any control Process"



## METROLOGY :-

Metrology is a science of measurements. Metrology may be defined depending upon the quantity under consideration into metrology of length, metrology of time etc.... Depending upon the field of application it is divided into Industrial metrology, medical metrology etc.,

### Need of metrology :-

Metrology is the process of inspection. Inspection means checking of all materials, products (or) components at various stages during manufacturing.

The Need of metrology are as follows

- \* To ensure that the part, material or a component conforms to the established standard.

- \* To meet the interchangeability of manufacture

- \* To maintain customer relation by ensuring that no faulty product reaches the customers.

\* Provide the Means of Finding out short coming in Manufacture

Principles of Measurement :-

Measurements is an essential part of the development of Technology and as it becomes more complex the technique of measurement becomes more sophisticated. We must be able to express this difference in Quantitative terms (i.e.) in terms of Numbers.

Process of Measurements :-

There are three elements of Measurement to be considered as Important. They are:

Measurand :-

It is a Physical Quantity (or) Property like length, angle, diameter, thickness etc. to be measured.

Reference :-

It is a Physical Quantity to which Quantitative comparisons are made.

Comparator :-

It means of comparing Measurand with some reference.

## Methods of Measurement :-

In Precision measurement various methods of measurement are adopted depending upon the accuracy required and the amount of Permissible error.

The Methods of Measurement can be classified as Follow

- \* Direct method
- \* Indirect method
- \* Absolute (or) Fundamental method
- \* Comparative method
- \* Transposition method
- \* Coincidence method
- \* Defective method
- \* Complementary method
- \* Method of Measurement Substitution
- \* Method of Null Measurement
- \* Contact method
- \* Contact lens method.



Direct Method of Measurement :-

This is a simple method of measurement in which the value of the Quantity to be measured is obtained directly without any calculations. This method is mostly used in production.

Indirect Method of Measurement :-

In Indirect method, the value of Quantity to be measured is obtained by measuring other Quantities which are fundamentally related to the required value.

Absolute (or) Fundamental Measurement :-

It is based on the Measurement of the base Quantities used to define the Quantity.

Comparative Method :-

In this method, the value of the Quantity to be measured is compared with known value of the same Quantity (or) other Quantity Practically related to it.

### Transposition Method :-

It is a method of measurements by direct comparison in which the value of the Quantity measured is first balanced by an initial known value A of the same Quantity, then the value of the Quantity measured is put in place of this known value and is balanced again by another known value B.

### Coincidence method :-

It is a differential method of measurement in which a very small difference between the value of the Quantity to be measured and the reference is determined by the observation of the coincidence of certain lines signals.

### Deflection method :-

In this method, the value of the Quantity to be measured is directly indicated by a deflection of a pointer on a calibrated scale.



complementary method is

The value of the Quantity to be measured is compared with a known value of the same Quantity. The combination of is adjusted that the sum of these two values is equal to predetermined Comparison Value.

method of measurement by substitution is

A direct comparison in which the value of a Quantity to be measured is replaced by a known value of the same Quantity, so selected that the effect produced in the indicating device by these two values are the same.

Method of Null measurement

It is a method of differential measurement. The difference between the value of the Quantity to be measured and the known value of the same Quantity with which it is compared is brought to Zero.

## Contact method :-

It is a method the sensor (or) measuring tip of the instrument actually touches the surface to be measured.

Example :- Measurement by micrometer.

## Contact Lens method :-

In contact lens method of measurement, there is no direct contact with the surface to be measured.

## Measuring system :-

A measuring system is made of the basic elements, These are

- \* Standard
- \* Work piece
- \* Instrument
- \* Person and
- \* Environment

## Accuracy of Measurement :-

The Purpose of measurement is to determine the true dimensions of a part. But no measurement can be made absolutely accurate. There is always some error. The amount of error depends upon the following factors.

- \* The accuracy and design of the measuring instrument.

- \* The skill of the operator.

- \* Method adopted for measurement.

- \* Temperature Variations.

- \* Elastic deformations of the part or instrument etc.,.

## Precision AND Accuracy

### Precision :-

The terms Precision and accuracy are used in connection with the performance of the instrument.

" Precision is the repeatability of the measuring process".

It refers to the group of measurement for the same characteristics taken under identical conditions.




It indicates at what extent the identically performed measurements agree with each other.

**Accuracy :-**


Accuracy is the degree at which the measured value of the quality characteristics agree with the true value. The difference between the true value and the measured value is known as the error of measurement.

**Distinction between Precision and accuracy :-**

Accuracy is very often confused with precision and through much difference the distinction between the precision and accuracy will become clear by the following example.



(a) Precise but not accurate



(b) Accurate but not precise

factors affecting the accuracy of the measuring :-  
The basic components of an accuracy evaluation are the five elements of a measuring system such as

- \* Factor affecting the calibration standards.
- \* Factor affecting the Workpiece.
- \* Factors affecting the inherent characteristics of the instrument.
- \* Factors affecting the Person, who carried the measurement.
- \* Factors affecting the environment.

SENSITIVITY :-

Sensitivity may be defined as the rate of displacement of the indicating device of an instrument, with respect to the measuring quantity. In other words, sensitivity of an instrument is the ratio of the scale spacing to the scale division value.

for example, if on an dial indicator, the scale spacing is 1.0 mm and the scale division value is 0.01 mm, then sensitivity is 100. It is called as "Amplification factor" or "gearing ratio".



## Readability :-

It refers to the ease with which the readings of a measuring instrument can be read. It is the acceptability of a measuring device to have its indications converted into meaningful numbers.

## CALIBRATION :-

The calibration of any measuring instrument is necessary to measure the quantity in terms of standard unit. It is the process of framing the scale of the instrument by applying some standard signals. Calibration is a pre-measurement process, generally carried out by manufacturers.

The accuracy of the instrument depends upon the calibration constant. Use of the instrument affects their accuracy.

## MAGNIFICATION :-

In order to measure a small difference in dimensions the movement of the measuring tip in contact with the work must be magnified. For this the output signal from a measuring instrument is to be magnified.

This Magnification means increasing the magnitude of output signal of measuring instrument many times to make it more readable.

### Repeatability :-

It is the ability of the measuring instruments to repeat the same results for the measurement of the same quantity, when the measurement are carried out.

- \* By the same observer.
- \* With the same instrument.
- \* Under the same conditions.
- \* Without any change in location.

Repeatability may be expressed quantitatively in terms of dispersion of the result.

### Reproducibility :-

It is the consistency of pattern of variation in measurement, (i.e) closeness of the agreement between the results of measurement of the same quantity, when individual measurement are carried out.

- \* By different observer.
- \* By different methods.
- \* Using different instruments.
- \* Using different conditions, location, etc.,



## Errors in Measurement :-

It is never possible to measure the true value of a dimension, there is always some error. The error in the measurement is the difference between the measured value and the true value of the measured dimension.

$$\text{Error in Measurement} = \frac{\text{Measured Value} - \text{True Value}}{\text{True Value}}$$

### ABSOLUTE Error :-

#### True absolute error :-

It is the algebraic difference between the result of measurement and the conventional true value of the quantity measured.

#### Apparent absolute error :-

If the series of measurement are made then the algebraic difference between one of the results of measurement and the arithmetical mean, is known as Apparent absolute error.

## Relative error :-

It is the Quotient of the absolute error and the value of comparison used for calibration of the absolute error. This value of comparison may be the true value the conventional true value or the arithmetic mean for series of measurements.

★ Calibration standard.

★ Workpiece

★ Instrument

★ Person.

## Types of error :-

During measurement several types of error may arise. These are

1. Static errors which include

(a) Reading errors.

(b) Characteristic Errors.

(c) Environmental Errors.

2. Instrument loading errors.

3. Dynamic errors.

## Static error:

These errors result from the physical nature of the various components of measuring system. There are three basic sources of static errors. The static error, divided by the measurement range or measurements gives the measurement Precision.

## Reading error:

Reading errors apply exclusively to the read out device. There do not have any direct relationship with other types (or) errors within the measurement system.

Reading error Includes,

Parallax error

Interpolation error.

## Characteristic Errors :-

It is defined as the deviation of the output of measuring system from the theoretical Predicted Performance or from Nominal Performance Specification.



## Environmental Errors :-

These errors result from the effect of surrounding such as temperature, Pressure, humidity etc., on measuring system.

External influences like magnetic or electric fields, nuclear radiation vibrations or shocks etc., also leads to environmental error.

## Loading error :-

Loading error results from the change in measrand itself when it is being measured (i.e.) after the measuring system (or) instrument is connected for measurement.

## Dynamic Error :-

Dynamic error is the error caused by time variations in the measrand. It results from the inability of the system to respond faithfully to a time varying measurement. It is caused by inertia, friction and other physical constraints in the sensing or readout or display system.

\* Systematic errors.

\* Random error.

## Systematic Error:-

Systematic errors are regularly repetitive in nature. They are of constant and similar form. They result from improper conditions (or) procedures that are consistent in action. Out of the systematic errors all except the personal error varies with individual to individual depending on the personality of the observer.

## Calibration Error :-

These are caused due to the variation in the calibrated scale from its normal value. The actual lengths of standards such as slip gauge and engraved scales will vary from the nominal value by a small amount.

## Random errors :-

Random errors are non-consistent. They occur randomly and are accidental in nature. Such errors are inherent in the measuring system. It is difficult to eliminate such errors.



The Possible source of Random errors are

- \* Small Variations in the Position of setting standard and Workpiece
- \* slight displacement of lever Joints of measuring instrument.
- \* Operator error in scale reading
- \* Fluctuations in the friction of measuring Instrument etc.,

Comparison between systematic errors and Random errors.

Systematic Error	Random error
These errors are repetitive in nature and are of constant and similar form.	These are non-consistent. The source giving rise to such errors are random
These errors result from improper conditions of producers that are consistent in action.	Such errors are inherent in the measuring system (or) measuring instrument.
Except Personal error, all other systematic errors can be controlled in magnitude and sense	Specific cause, magnitude and sense of these errors cannot be determined from the knowledge of measuring system or condition.

### Direct Measurement :-

Let us consider a gauge block being measured directly by interferometry. Here the effect of using a non-standard temperature produces a proportional error

$$E = l_a (t - t_s)$$

Where  $l$  = Nominal length,

$a$  = Coefficient of expansion

$(t - t_s)$  = Deviation from standard temperature.

$t$  = Temperature during measurement

$t_s$  = standard temperature.

### Comparative Measurement :-

If we consider two gauges whose expansion coefficients are respectively  $a_1$  and  $a_2$ , then the error due to non-standard temperature will be error

$$E = l (a_1 - a_2) (t - t_s)$$



Control of error in measurement :-

- \* Against the primary cause (Planning, design, calibration, filtering)
- \* Against the secondary cause (Disturbance error and load error)

Types of standard :-

Primary standard

Secondary standard

Working standard.

Primary standard :-

for precise definition of the unit these shall be one and only one material standard which is to be preserved under most careful condition it is called Primary standard.

Ex :-

International metre

International yards



secondary standard :-

Secondary standard are made as nearly as possible exactly similar to Primary standard as regards to design material and length. They are compared with Primary standard after long intervals and the records of deviation are noticed.

Tertiary standard :-

The Primary and secondary standards are applicable only as ultimate control. Tertiary standard are the first standard to be used for reference purpose in laboratories and workshop. They are used for comparison at intervals with working standards.

Working standard :-

Working standard are used more frequently in laboratories and workshop. They are usually made of low grade of material as compared to Primary secondary and tertiary standard for the sake of the economy. They are derived

from fundamental standard. Both line and working standard are used. Line standards are made from H-iron sections.

Most of the Precision Measurement involve the distance between two surface and not with the length between two lines.

Other standards:-

Reference standard - for reference purpose.

Calibration standard - inspection, working.

Inspection standard - inspection.

Working standard - operation.

Line and End Measurements:-

Line standard.

End standard.

Line standard:-

When the length is measured as the distance between the centre of two engraved line.

Ex:  $\hat{A}$  The line measure ment is the rule with divisions shown at line that works on it.

End standard:  $\hat{A}$

When length is expressed as the distance between two flat parallel face, it is known as end standards.

Ex:  $\hat{A}$

Vernier Caliper, Slip gage, end bar.





# Linear and angular measurement

## Introduction:-

Linear measurement applied to measurement of length, diameter, height and thickness includes external and internal measurement.

The dimension to be measured is aligned with the graduation of the scale. Linear measuring instrument are designed either for line (or) end measurement.

## Classification of the instruments:-

The instruments used for the linear measurement are classified as

1. Direct
  2. Indirect
- └

Graduated  
Non graduated

The graduated instrument includes rules, Vernier caliper, height gauge, depth gauge, micrometers, dial gauge etc.

The Non graduated instruments includes Telescopic gauge, surface gauge, wire gauge etc.

They are also classified as,

- a) Precision instrument (vernier, dial gauge)
- b) Non Precision instrument (steel rule)

### 3. Spirit level:-


Spirit level are used for

1. Measuring small angle (or) inclination
2. To determine the position of surface
3. To establish a horizontal datum.

The spirit level consist of a sealed glass tube mounted on a base.

The inside surface of the tube is ground to a concave barrel shape having large radius. The precision of the level depend on the accuracy of this radius of the tube. A scale is engraved on

the top of the glass tube.





The tube is nearly filled with either ether (or) alcohol except a small air (or) vapour in the form of a bubble.

Principle:-

The bubble always tries to remain at the highest point of the tube. If the base of the spirit level is horizontal, the centre point is the highest point of the tube.

If the base of the level is tilted through a small angle, the bubble will move relative to the tube, a distance along its radius corresponding to the angle. ( $OA_1$  &  $OA_2$ ) are two positions of the base of the level. ( $B_1$  &  $B_2$ ) are the bubble positions.

Let  $L$  be the distance travelled by the bubble along the tube and " $h$ " the difference in height between the end of the base,

$$L = R\theta \quad \text{and} \quad h = L\theta$$

$R \rightarrow$  Radius of curvature  
 $\theta \rightarrow$  angle of base



#### 4. Sine bar:-

Sine bar is a precision instrument used along with slip gauge for measurement of angle. Sine bar is used to measure the angle very accurately and it is used to locate the work to a given angle within very close limits.

It consists of a steel bar and two rollers. The sine bar is made of high carbon and high chromium corrosion resistant steel, suitable hardness. The rollers are of accurate and equal diameter. They are attached to bar at two ends. The axis of the roller is 100 mm, 200 mm (or) 300 mm.

When the rollers are brought in contact with a flat surface, the top of the bar is parallel to the surface. The various parts are hardened and stabilized before grinding and

Sine bar are graded as A Grade (or) B grade sine bar. A grade sine bar are made with an accuracy of  $0.01 \text{ mm/m}$  of length and B grade sine bar with an accuracy of  $0.02 \text{ mm/m}$  of length.

### Type of Sine bar

a) Form in which the rollers are so arranged that their outer surface on one side are level with the plane top surface of the sine bar.


b) Shows a sine bar with hollow roller which outside diameter equal to the width of sine bar. It is useful in instance where the width of the enter into calculate of work height.

c) Shows a sine bar with pins on both side. This is used where the ordinary sine bar cannot be used on the top surface due to interruption.



### Principle of Sine bar

The principle of operation a sine bar is based on the laws of trigonometry. To set a given angle, one roller of the bar is placed on the surface plate and the combination of slip gauge is inserted under the second roller.



$h \rightarrow$  height

$L \rightarrow$  Distance b/w roller

$$\sin \alpha = \frac{h}{L} \quad (\text{or}) \quad \alpha = \sin^{-1} \left( \frac{h}{L} \right)$$

Thus the angle to be measured or to be set is determined by indirect method as a function of sine for this reason, the device is called "sine bar".



## Angle Gauge:-

The Angle gauge enable any angle to be set to the nearest 3". There are pieces of hardened and stainless steel. The measuring face are lapping and polished to a high degree of accuracy and flatness.

They are 75mm long and 15mm wide and are available in two sets. One set consists of 12 pieces and a square block in three series of value of angle.

$1^{\circ}$ ,  $3^{\circ}$ ,  $9^{\circ}$ ,  $27^{\circ}$  and  $41^{\circ}$

$1'$ ,  $3'$ ,  $9'$  and  $27'$


$6'$ ,  $8''$ , and  $30''$

Another set contain 13 pieces


$1^{\circ}$ ,  $3^{\circ}$ ,  $9^{\circ}$ ,  $27^{\circ}$  and  $41^{\circ}$

$1'$ ,  $3'$ ,  $9'$  and  $27'$

$3''$ ,  $6''$ ,  $12''$  and  $30''$



Addition



Subtraction

Each angle gauge is accurate to which one second and is marked with engraved "V" which indicate the direction of indicated angle.

These gauge together with a square block can be so wing that any angle between  $0^\circ$  to  $360^\circ$  can be set.

Each angle gauge is a wedge thus two gauge with their narrow ends together provide an angle which is the sum of the angle of the individual gauges. Subtraction of angle is obtained when the narrow end are opposed.



## Clinometer:-

A Clinometer is a spirit level mounted on a rotary member. The angle of inclination of the rotary member relative to its base can be measured by circular scale.

### Types of Clinometer

1. Vernier
2. Micrometer
3. Dial
4. Optical

### Vernier Clinometer:-

It consists of a spirit level mounted on a rotary member carried in a housing. One face of the housing forms the base can be measured by a circular scale. The scale may cover the whole circle (or) only part of it.

Clinometers are generally used to determine the angle included between two surfaces of a workpiece.






$$\alpha = 180 - (\theta - \phi)$$

### Micrometer clinometer:-


In this type spirit level is attached at one end of the barrel of a micrometer. The other end of the spirit level is hinged on the base. The base is placed on the surface whose inclined is to be measured.



The Micrometer is adjusted till the level is horizontal. This type of clinometer is used for measuring small angle.

### Clinometer:-

The dial clinometer is similar in principle to the level protractor. The spirit level is attached in a gear and a dial gauge. The whole angle can be observed through an opening in the dial on the circular scale on the gear and the fraction of the angle can be readed on the dial gauge.



### Optical Clinometer:-

It consist of rotatable turntable which is mounted on a base. Spirit level is provided in the turntable. The readings are taken by measuring microscope on a graduated scale provided on a fixed circular glass disc concentric with the spirit level (can be measured.)




## 7. Angular Measurements

To obtain these fine accuracy for high precision work, use is made of sine bar, angle gauge and optical instrument. The spirit level and the divided head are also employed.

## 8. Bevel Protractor:-

- a) Vernier bevel protractor
- b) Optical bevel protractor
- c) Universal bevel protractor

### Vernier bevel protractor:-



The bevel protractor are used to find the flatness, squarness, parallelism, etc.



The Vernier bevel protractor with acute angle attachment. The body of "V" bevel protractor is designed in such a way that its back is flat and there are no projections beyond its back.


The flatness of the body is tested by checking the squareness of blade with respect to base plate when the blade is set at  $90^\circ$ .

The base plate is attached to the main body and an adjustable blade is attached to a circular plate containing vernier scale. The main scale graduated in degree is provided on the main scale.

The blade can be moved along throughout its length and can also be reversed. It is about 150 (or) 300 mm long, 13 mm wide and 2 mm thick. Its ends are bevelled at an angle of  $45^\circ$  and  $60^\circ$ .

### Optical level protector:-

Optical level protector is a recent development of the vernier level protector. By using this instrument it is possible to take reading up to approximately 2 mins of an arc. The internal circular scale is graduated in division of 10 mins of arc.



Reading are taken against a fixed index line (or) Vernier by means of optical magnifying system which is integral with the instrument.

The scale is graduated as a full circle marked 0.90-0.90. The Zero position corresponding to the condition, when the blade is parallel to the stock.



## Auto collimator:-


Auto collimator is an optical instrument used for the measurement of small angular difference, changes (or) deflection, plane surface inspection etc.

### Principle:-

If a light source is placed in the focus of a collimating lens, it is projected as a parallel beam of light. If this beam is made to strike a plane reflector kept normal to optical axis, it is reflected back along its own path and its brought to the same focus. If the reflection is tilted to the small angle  $\theta$  the parallel beam is deflected twice that angle and is brought to a focus in the same plane as the light source, but a one side at a distance  $x = 2f\theta$

where,  $f$  = focus length of lens  
 $\theta$  = angle of inclination (Reflecting mirror)





The image seen after reflection in the internal reflection whose angular variation are being measured formed by the light from the objective lens. This light passes through the beam splitter and the image is picked up by the microscope.

Application :-

1. Measurement of straightness and flatness of surface
2. Precise angular inclination
3. Comparative measuring using master angle.
4. Assessment of squariness, & 11°
5. Small linear dimension measuring

6. Alignment tool adjustment setting

## Limit Gauge:-

The main requirement of using interchangeability in the manufacturing component is to attain the close adherence value.

## Types:-

Plug gauge

Ring gauge

Snap gauge

Position gauge

## Application:-

→ Thread gauge

→ Form gauge

→ Screw Pitch gauge

→ Feature gauge

→ Air gauge

→ Indicating gauge.

## Device used for linear measurement

1. Vernier
2. Micrometer
3. Slip gauge
4. Comparators

### Vernier Caliper

- Main scale
- Vernier scale

### Principle

Two scale of different size are used to measure dimension in high accuracy.

### Steps

- Check for zero error
- Fine adjustment of movable jaw
- Both jaw should touch the part
- Final adjustment depend on experiment

### Type

1. Type A
2. Type B
3. Type C



### micrometer:-

1. Has an accurate screw
2. 10 to 20 threads
3. End of screw act as measuring tip
4. While measuring dimension the lock nut is adjusted.

### Parts:-

→ Frame, Anvil, Spindle, Ratchet, adjustment nut.

## ADVANCES IN METROLOGY

Light is considered as an electro magnetic wave of sinusoidal form. The high point of wave is called the crest and the low point is called trough. The distance between two crests or two troughs is called the wavelength. The time taken by light in covering one wavelength is called time period.

The amplitude of a wave is the distance from the still position to the top of a crest or to the bottom of a trough. The frequency of a wave is the number of waves passing a point in a certain time (i.e.) the velocity of transmission.

Light is produced by any two methods

\* Incandescence is the emission of light from hot matter ( $\text{Temp} \geq 800\text{K}$ )

\* Luminescence is the emission of light when excited electrons fall to lower energy level.


Monochromatic Light is a narrow band of spectrum of visible light having the same wave length or colour.

## LASER

In Coherent beam, all the waves have the same frequency and phase. Lasers have greater coherent length of a light beam refers to the distance over which the beam stays in phase with itself.

\* An electromagnetic radiation is emitted whenever a charged particle such as an electron drops from a higher energy state,  $E_2$  to a lower energy state  $E_1$ .





The difference in energy level across which an excited electron drops determines the wavelength of emitted light. The wavelength, frequency of light determines its colour.

According to Quantum Mechanics, light is made up of particles called photons. Which exhibit both particle like and wave like properties.

$$E = h\nu$$

$\nu$  is the frequency of light and  $h$ ,

$$\lambda \nu = c$$

$\lambda$  is the wavelength of light and  $c$  is the speed of light in vacuum.

$$E = \frac{hc}{\lambda}$$

From the above equation we see that longer the wavelength of light lower the energy of photon. In the Ultraviolet light is more energetic than infrared light.

When an electron is in excited energy state, it must eventually decay to a lower level giving off a photon or radiation. This event is called Spontaneous emission.



A photon strikes an excited atom

First Photon

New photon

The atom emits a New Photon

Just like the first one.

There is a probability that the passing photon will cause the electron to decay in such a manner that a photon is emitted at exactly the same wavelength, in exactly the same direction and with exactly the same phase as the passing photon. This process is called a 'stimulated emission'.

The normal thermal population in any material will have most of the electrons in the steady state ground level. But it is preferred to have most of the electrons in the excited state so that we can get more photons through stimulated emission. Thus a population inversion.

The condition of having enough excited or higher energy states distributed in a material, that a chain-reaction of stimulated emission can occur is called population inversion.



Comparison between Laser Light and  
Light from an incandescent lamp.

### LASER LIGHT

Has single wavelength  
(i.e) Spectrally pure or  
Monochromatic.

Coherent radiation i.e  
all photons are in  
Phase

High directionality  
Prevails over long  
distance

### Types of Laser.

There are various kinds of  
Lasers like Solid state, ~~gas~~ Gas,  
Liquid and semiconductor Lasers. The  
different lasers and their applications  
are given below.

### ORDINARY LIGHT

Has a mixture of  
Various wavelengths i.e  
Polychromatic.

Incoherent radiation.

No Directionality.

Does not prevail  
long.

\* Types of Laser :  
Solid state :

Ruby Laser

YAG Laser

Liquid Laser :

Dye Laser

He-Ne Laser

Gas Laser :

Argon ion Laser

CO<sub>2</sub> gas Laser

Semi conductor Laser :

Ga As Al Laser

In Ga AlP Laser

In Ga AlP Laser

These are the types of

Laser are available.

## Advantages of Laser :-

\* Lasers are more intensive than any other monochromatic source.

Micrology lasers are low power instruments.

Lasers have wide dynamic range, low optical cross talk and high contrast.

Lasers are highly precise, accurate and can prevail over long distance.

Lasers allow fabrication of fine structures with high quality and low mechanical stress.

Lasers facilitate rapid non-contact drying of hot, delicate or hot moving parts.



## Applications :-

### Manufacturing :-

for high Quality cutting,  
drilling, welding and surface  
treatment etc.,

### Metrology :-

for Contact measurement of  
parts, for long distance range finding and  
Navigation, for scanning bar codes etc.,

### Medical :-

for surgery, kidney stone, treatment,  
eye treatment, in dentistry, for diagnosis,  
like laser microscopy.

### Data Storage :-

for optical data storage  
of compact disks, CD, DVD, etc)  
for holography.

### Communication :-

for optical fibre communication,  
for free space communication, (eg  
Inter satellite communications).

## SCANNING LASER PROBE :-

A scanning laser probe is used for non-contact dimensional measurements.

The main components in a scanning laser probe are

Transmitting Unit

Photo Cell (Receiver)

Microprocessor or Control Unit.

Signal from the light entering the photocell is processed by a microprocessor to provide display or dimension.

The scanning laser probe is used to measure the roundness and diameter of hot steel bars. It provides an accuracy of  $0.025 \text{ mm}$  for  $5-25 \text{ mm}$  diameter objects.

## Laser Telemetric System :-

Laser telemetric system is used for high speed, non contact dimensional and positional measurement and control. The system measures outside diameters, multiple dimensions or part positions of other opaque or transparent objects.

The laser telemetric system consists of three components: Transmitter, receiver and processor electronics.

## Photo Diode Array Imaging :-

This system consists of a laser source, imaging optical, photodiode array, signal processor and display unit. Here, the shadow of a stationary part is projected on a solid state diode array image sensor.



## INTERFERENCE :-

The phenomenon in which two waves of greater or lesser amplitude is called Interference.

### Principle of Superposition :-

When two or more waves of the same type are incident at the same point, then the total displacement at that point is equal to the vector sum of the displacement of the individual waves.

On the other hand, if they are out of phase, the resultant wave amplitude is the difference of the individual amplitudes which results in decreased brightness.

If the amplitude of both the waves are same, then they nullify each other and other will result in darkness.

The conditions necessary for the interference of light waves at a place are

The source should continuously emit waves of the same wavelength or frequency

The amplitude of the two interfering waves should be equal or nearly so for obtaining interference fringes.

The sources must be reflective

The source should be narrow.

### INTERFEROMETRY :

Metre was defined as the distance between two finely etched lines on the Platinum Iridium bar.

In order to reduce the dependence on the physical standard, the process which was prone to errors, the wave length of pure monochromatic light is used as the natural standard of length.

## Interferometer :-

It is an Instrument which generates and compares the difference between two light waves which are reflected off two different surfaces. It utilizes the effect of interference.

## Applications of Interferometers :-

Measurements of lengths and small changes in lengths.

Optical testing.


Studies of surface structures.

Wavelength measurements.

## Ac Laser Interferometry :-

A D.C Interferometer system mixes out of phase light beams of the same frequency where as the a.c system mixes beams of two slightly different frequencies, permitting the distance information to be carried on a.c wave form.





The envelope frequency is given by the difference of the two frequency components  $(F_1 - F_2)$  of the source radiation.

So, an A.C Laser interferometer measures mirror displacement by measuring the phase change due to the Doppler effect. It gives a much improved signal to noise ratio over amplitude modulation.

### Description of A.C Laser Interferometer.

1. Two frequency laser source.
2. Optical Elements.
  - (i) Beam splitter.
  - (ii) Beam Benders.
  - (iii) Retro reflectors.
3. Laser lead's measurement receiver.

Measurement display.

## Advantages of ACH :-

It is more tolerant to environmental factors like dust, smoke, air turbulence, etc that attenuate laser beam intensity.

It has high repeatability and resolution of displacement measurement.

It has high accuracy of measurement.

It facilitates to maintain long range optical path (60 m).

It is easy to install.

Alignment is good.

## Laser Interferometry :-

Conventional light source emit waves of differing frequencies and at different time from different point in

the source. Hence they are not

suitable for obtaining interference

fringes. Laser devices produce intense

beam of light which are monochromatic

coherent and highly collimated.

[www.studentsfocus.com](http://www.studentsfocus.com)

## Type of Laser Interferometer:-

Homodyne or Single - frequency (or)  
DC Laser  
Heterodyne (or) Dual - frequency or  
AC Laser Interferometer.

### Single Frequency DC Interferometer:-

For two beams of light to  
interfere, the beams must have  
same polarization state. A  
Polarizer transmits only a  
single, polarization state.

The orientation of the  
transmitted polarization state is  
based on the angle of the polarizer.

Wave plate (or) retarder  
change the polarization state of  
light. eg:- from horizontal to  
vertical



A Polarization beam splitter separates the source into beams with opposite polarization states referred to as the reference and measurement legs.

The homodyne or single frequency DC Interferometer is an improved version of the Michelson Interferometer.

Coordinate Measuring Machine :-




Diagram of Coordinate measuring system.

A Coordinate measuring system machine consists mainly of four elements. They are,

\* The Main Structure including the base area or motion,

\* The Drivly system,

\* The Machine Controller and Computer hardware.

\* Suitable Application software

### Types of CMM :-

Cmm are classified as follows :-

1. According to Control system

(i) Manual CMM or free floating CMM

(ii) Computer Numerical Control (CNC)  
(or) Direct Computer Control (DCC)

2. According to design of Main structure or Orientation of Probe arm

(i) Bridge type.

(ii) Cantilever type.

(iii) Column type.

(iv) Gantry type.

(v) Horizontal type.

According to Mounting Systems.

(i) Bench top.

(ii) Free standing.

(iii) Portable and Hand Held.

~~Adv~~  
Advantages of CMM :-

\* Reduced inspection cycle time.

\* Flexibility.

\* Reduce operator error.

\* Improved accuracy and precision.

\* Improved productivity.

Probes :-

CMM measure work place dimensions by moving a sensing device, called a

Probe

[www.studentsfocus.com](http://www.studentsfocus.com)



The Probes convert Physical measurements into electrical signals by using various measuring systems within the Probe structure.

Common Probes Fall into two general Categories.

- \* Tactile (or) Contact Probes.
- \* Non-Contact Probes.

### Contact Probes :

It means happens, gather data by physically touching the workpiece in the acquisition of its measuring points takes place by probing with stylus. Contact probes are classified.

- \* Hard (or) Fixed Probe.
- \* Touch Trigger Probe.
- \* Measuring type (or) Displacement

## Non - Contact Probe :-

Non Contact Probe also called Proximity Probe are used when fast, accurate measurements are required with no physical contact with the part.

These Probe enable the Measurement of flexible parts that soft material and geometry might be distorted with a Contact Probe.

## Applications of CMM :-

To check dimensional Accuracy of Part in various steps of production and of Part supplied by Vendor.


To inspect test equipment, gauges and tools.

To determine shape and position, Minimum metal condition, Linkage of results, etc., which conventional

Manual Contact Probe

## Machine Vision :-

Machine Vision is the ability of a computer to 'see'. Machine Vision is also called as 'Artificial Vision'. (or) Computer Vision. It is defined as a technique which allow a sensor to view a scene and drive a numerical or logical decision without further human intervention.





## UNIT - IV

### FORM MEASUREMENT

PRINCIPLES and Methods of  
Straightness - Flatness Measurement -  
Thread Measurement, gear measurement,  
Surface Finish Measurement, Roundness  
Measurement - Applications.

#### Introduction :

If the components of a machine have to function properly, accurate measurements of any dimensions to a specific length and other geometric feature must be considered. Geometrical features or a measurement include measurement of straightness, flatness, squareness, parallelism, roundness, circularity, cylindricity, co-axiality, etc.,. Various methods and techniques are discussed here to measure these geometrical features.

## STRAIGHTNESS MEASUREMENT :

Straightness is an important geometrical parameter of the surface on the part of machine. In case of shaping machine, tool must move on a straight path to perfectly cut the material by having the surface of guideways being straight.

A straight line is defined by the shortest distance between two lines. But it is very difficult to define straightness exactly. A ray of light is straight also, the liquid level is straight and flat.




Fig. Exaggerated View of a Surface Showing Undulations - up and down

# METHODS OF STRAIGHTNESS MEASUREMENT

## 1. SPIRIT LEVEL :-

Straightness can be measured by using spirit level. Spirit level is used in the shape of a bubble tube mounted on a cast-iron base.

Also autocollimator is used to test the straightness. While the spirit levels are used only to measure (or) test straightness of horizontal surface, the autocollimator are used on a surface in any plane.

## STRAIGHT EDGES :-

With help of surface plates and spirit levels, straight edges are also used for checking straight and flatness. A straight edge is a narrow, deep and flat sectioned measuring instrument. These are made up of steel (with up to 2 m) and cast iron (with up to 3 m). Straight edges are ribbed heavily and are built in two ways.



Straight edges are used for testing large areas or distances. The straightness of an edge or the flatness of a surface can be estimated by placing a standard straight edge on it and viewing against the lighting background.

### Laser Measurement System for Straightness

#### Measurement

Straightness Measurement Using Laser highlights the bending or misalignment in the guide ways of a machine. The laser systems comprise of straightness beam splitter and straightness reflector.

### Flatness Measurement

Flatness is a minimum distance between two planes, which will cover all irregularities of the surface to be tested.

Determining Flatness means to determine the best fit planes between two standard reference planes one above and one below the plane of surface to be tested. Flatness is a Quantitative term which can be Quantified by measuring the distance  $d$ .

Flatness Testing is done by comparing the surface to be tested with an accurate surface. Flatness is analyzed by Quantifying deviations from a least-squares reference plane. A least squares reference plane is a plane where the areas above and below the plane are equal and are kept to a minimum Separation.

## METHODS OF FLATNESS MEASUREMENT

Beam Comparator Used for Flatness

Testing :-

A Flatness reference plane is referred as surface plate. Beam Comparator checks the general degree of flatness with a method of Comparative Measurement. By Using Beam Comparator, the flatness of a surface to be tested is compared with a Master plate.

## Measurement of Flatness by Interferometry

Small Variations less than one or two microns are measured by using this method.

Flatness Measurement Using Laser Measurement  
System :-

This Measurement is used to check the accuracy of CMM tables and all types of surface plates.



It determines errors and then Quantities  
them. If these errors are significant,  
then remedial work, like further lapping  
will be done.

Flatness Measurement Electro-Mechanical Gauges

Large Variations of several microns  
are measured by using conventional  
electromechanical gauges, especially with the  
non-contact type for polished surface.

Surface Plates :-

The surface plate has top plane  
surface with a true and level plane.

Normally the flat surface plate is  
used as a reference datum plane.

It acts as a master for checking  
the flatness of a work surface.

## Cast Iron Surface Plates :-

These are used after rough machining is done then followed by seasoning (aging) for a suitable period then annealing up of  $500^{\circ}\text{C}$  for about three hours is done on the seasoned plates to relieve the internal stress.

## Granite Surface Plates :-

It has more rigidity than C.I. surface plates for the same depth without corrosion. They have high modulus of rigidity and do not have moisture content.

## Glass Surface Plates :-

There are also commercially available and comparatively light in weight and free from burr and corrosion.



## PARALLELISM

Two entities line or plane or surface are parallel to each other when the perpendicular distance between the surfaces under test does not exceed an agreed value over a specified time. Parallelism defines the angle between two surface of a sample specimen. It can be specified as a thickness difference per unit length, or as an angular deviation.

### Methods of Parallelism measurement

1. Using Dial Indicator and Test Mandrel

(i) Parallelism of two planes (or) surface

(ii) Parallelism of two axes (or) two cylinders

(iii) Parallelism of an axis of cylinder to a reference surface.

(iv) Parallelism of an axis of cylinder to the intersection of two planes.

2. Using Electro-Mechanical Gauge.

3. Using An Auto collimator.



## Applications :-

### Measuring the straightness of machine components

The straightness of machine components like guideways (or) the straightness of lines of motion of machine components, can be checked with the autocollimator and a base mirror. The base mirror is moved step by step along the guide way which is to be measured.

### Measuring Flatness :-

Measuring the flatness of large surface is usually done by measuring the straightness in the relevant direction of a series of lines in the surface plane in a certain pattern. The procedure for each line is the same as for single straightness measurement.

### Other applications :-

- \* Aircraft assembly Tigs.
- \* Rolling mills.
- \* Retro reflector measurement

## Thread

## Measurement

A screw thread is a helical structure used to convert rotational movement to linear movement and also used to convert rotational torque to linear force. A screw thread is a ridge wrapped around a cylinder or cone in the form of helix.

A screw thread is the helical ridge produced by forming a continuous helical groove of uniform section on the external (or) internal surface of a cylinder or a cone.

A screw thread formed on a cylinder is known as straight (or) parallel screw thread, while the one formed on a cone is known as tapered threads.

It is used to transmit the power and motion. The screw thread also

acts as a temporary fastener.

Nomenclature of screw threads:

Major diameter (or) Nominal diameter

It is defined as the diameter of an imaginary cylinder that bounds the crest of an external thread or root of an internal thread. It is the largest diameter of the screw thread.

Minor diameter or Core diameter or Root diameter ( $d_c$ )

It is defined as the diameter of an imaginary cylinder that bounds the root of an external thread or crest of an internal thread. It is the smallest diameter of the screw thread.

Pitch diameter or Effective diameter

It is defined as an imaginary cylinder diameter, the surface of which would pass through the thread at such points as to make equal widths of the thread and width of space between the threads.

[www.studentsfocus.com](http://www.studentsfocus.com)



### Pitch :-

It is an axial distance between two similar points on adjacent threads, it is measured in millimeters.

### Lead :-

It is defined as the axial distance which a screw thread advances in one rotation of the nut.

For single start threads,  $\text{Lead} = \text{Pitch}$

For double start threads,  $\text{Lead} = 2 \times \text{Pitch}$

For multi start threads,  $\text{Lead} = n \times \text{Pitch}$

Where  $n$  = number of starts of the thread.

### Crest :-

It is the top surface generated by the two adjacent flanks of the thread.

### Root :-

It is the bottom surface generated by the two adjacent flanks of the thread.

Depth of thread :-

It is defined as the Perpendicular distance between crest and root.

Flank :-

The inclined surface, which joins the crest and root.

Angle of thread :-

The included angle between two flank surface.

Slope of the thread :-

It is defined as the half the Pitch of the thread.

Screw thread :-

A screw thread comprises a helical groove of specified cross-sectional shape. The helix angle of thread can be determined by,

$$\tan \alpha = \frac{P}{\pi D}$$

Let

$\alpha$  - Helix angle

P - Pitch

d - diameter

**Flank angle :-**

It is the angle between individual flank and the Perpendicular to the axis of thread which passes through the Vertex.

**Helix angle :-**

It is the angle made by the helix of the thread at the pitch line with plane Perpendicular to the axis.

It is the angle between any helix & an axial line on its right circular cylinder or cone.

**Thread Per Inch :-**

Thread Per Inch =

$$\frac{\text{Length}}{\text{Pitch in inch}}$$



### Addendum :-

It is radial distance between the Major dia & Pitch dia.

### Dedendum :-

It is the radial distance between the Minor dia & Pitch dia.

### Thread Angle :-

The angle of the cross section which is standardized as 60 degree in V - threads, but any angle can be used.

### Tolerance :-

The Following are the requirements for proper external and internal thread engagement.

External thread and Internal thread must have sufficient contact at the flank.

External thread & Internal thread must have enough engagement.

## Types of Threads :-

Triangle Shaped Threads

Square Shaped Threads

Trapezoidal Shaped Threads

## Measurement of Screw Thread :-

It is necessary to measure following parameters of the screw thread to estimate the accuracy of the screw thread.

There are

major diameter

minor diameter

Effective diameter

Pitch.


## Errors in screw Thread :-

1. Pitch error.
2. Major diameter error.
3. Minor diameter error.
4. Effective diameter error.
5. Angle error.

## Gear Measurement

When the positive drive (without slipping) is required for some Precision Machines, and if the distance between the driver and follower is very small, the gear (or) toothed wheels are Used.

Gears Used for transmitting motion and power from one shaft to another with constant velocity ratio. When the Driver Gear is rotated by an input shaft it will rotate the follower in the opposite direction.





# Advantages and Limitations of Gear Drive

## Advantages :-

- \* There is no slipping, so exact Velocity ratio is obtained.
- \* Large Power can be Transmitted.
- \* High efficiency.
- \* Reliable service.
- \* It requires less space, Hence Compact layout is possible.

## Limitations :-

- Special Machines, tools and Technology are required for the Manufacturing of gears.
- The defective gear may cause Vibration and noise.
- Cost of Manufacturing is comparatively high.

## Classification of Gears :-

Based on Position of axes of the shaft

- (i) Parallel shafts.
- (ii) Intersecting shafts.
- (iii) Non Parallel and Non-intersecting shafts.

Parallel shafts :-

In this case, two parallel and coplanar shafts are connected by any of the following gears.

Spur gears, Helical gear, Rack and Pinion, Herringbone gears and internal gears.

Bevel gears for Intersecting shaft :-

Bevel gears are used to connect two non-parallel (or) intersecting but coplanar shafts.

(iii) Non - Parallel and non - intersecting shafts :-

Spiral gears are used to connect two non - Parallel and non - intersecting i.e., non coplanar shafts. It is also called skew bevel gearing.

Based on type of gearing :-

External gearing.

Internal gearing.

Rack and Pinion

Worm and Worm Wheel.

TERMINOLOGY AND DEFINITION :-

Spur gears are Normally straight tooth or involute gears. Some of the important terminologies of spur gear are defined as follows.

The Pitch circle :-

It is a theoretical circle on which all calculations are usually based. The Pitch circle is an imaginary circle. The pitch circles of a pair of mating gears are tangent to each other.



Pitch circle diameter :-

The diameter of the Pitch circle is known as Pitch circle diameter. The size of the gear is usually specified by the Pitch circle diameter.

Pinion :-

Pinion is a smaller of the two mating gears.

Gear (or) Wheel :-

The larger of the two mating gears is called the gear (or) wheel.

Pitch Point :-

It is a common normal to two gear teeth at the point of contact and the common tangent at the Pitch Point. The standard pressure angles are  $14\frac{1}{2}^\circ$  and  $20^\circ$ .

Addendum :-

It is the radial distance from the bottom of the tooth to the Pitch circle.

[www.studentsfocus.com](http://www.studentsfocus.com)

**Dedendum :-**

It is the radial distance from the bottom land and Pitch circle.

**Whole depth (or) Total Depth :-**

It is the sum of addendum and dedendum.

**Addendum circle :-**

It is the circle drawn through the top of the teeth and concentric with the Pitch circle.

**Dedendum circle :-**

It is the circle drawn through the bottom of the teeth (or) root circle.

$$\left. \begin{array}{l} \text{Dedendum circle dia} \\ \text{(or)} \\ \text{root circle dia} \end{array} \right\} = \text{Pitch circle dia} \times \cos \phi$$

**Circular Pitch :-**

It is the distance measured on the Pitch circle from a point on one tooth to the corresponding point on the adjacent tooth.

$$\text{Circular Pitch, } P_c = \frac{\pi D}{T}$$

Where,  $\phi$  = Dia of Pitch circle in mm.  
 $T$  = Number of teeth on wheel.

### Diametral Pitch

It is the ratio of number of teeth to the pitch circle diameter,

$$\text{Diametral Pitch } P_d = \frac{T}{D} = \frac{\pi}{P_c}$$

### Module :

It is the ratio of the Pitch Circle Diameter to the Number of Teeth (or) reciprocal of diametral Pitch,

$$m = \frac{D}{T} = \frac{1}{P_d}$$

### Clearance Circle :

It is a circle that is tangent to the addendum circle of the mating gear,

### Tooth thickness :

It is a width of the tooth measured along the Pitch circle.

### Tooth Space :

It is a width of space between the two adjacent teeth measured along the Pitch circle.



Backlash :-

It is the amount by which the width of a tooth space exceeds the thickness of the engaging tooth at the Pitch circle.

Face of tooth :-

It is the surface of the gear tooth above the Pitch surface.

Flank of tooth :-

It is the surface of the gear tooth below the Pitch surface.

Top land :-

It is the surface of the top of the tooth.

Face width :-

It is the width of gear tooth measured parallel to its axis.

Profile :-

It is the curve formed by the face and flank of the tooth.

Filler radius :-

It is the radius that connects the root circle to the profile of the tooth.

Errors in Gear :

Gear Blank Run out Error

Gear tooth Profile Error

Gear tooth Error.

Pitch Error

Runout Error of Gear tooth

Lead Error

Composite Error

Assembly Error

Recent Development :-

Due to the Improved Manufacturing Capability of gear Production equipment, higher accuracy Measurement equipment is required.

With the Introduction and development of Computer Numerical Control (CNC) Many Inspection Machines for lead / Involute Profile Checking and Pitch Measurement have been developed.

## SURFACE FINISH MEASUREMENTS :-

Generally Components are subjected to several Machining Operations for Producing required geometrical Surface. But it is not practically Possible to produce a Component in exact dimension & due to various factors like machine vibrations, Nature of Workpiece, Method of operations, Tool Conditions and Skills of the labourer etc.,.

### Surface Texture :-

The Surface texture is defined as the regular (or) irregular Surface Spacing which tend to form a Pattern on the Surface.

### Types of Irregularities :-

Primary Texture (or) Roughness.

Secondary Texture (or) Waviness.



Roughness Height (or) Height of

Unevenness :-

It is the height of the irregularities with respect to a reference line. It is measured in "mm" or Microns.

Waveiness Height :-

Waveiness height is the Peak-to-Valley distance of the surface profile. It is measured in "mm".

Lay :-

Lay indicates the direction of predominant surface pattern produced and it reflects the machining operation used to produce it. The various lay are given.

(a) Straight lay.

(b) Circular lay.

[www.studentsfocus.com](http://www.studentsfocus.com)

Reason for Measuring the Surface Texture :-

Surface Texture is measured for the following reasons.

\* To Predict the Performance of the Work Material.

To Control the Manufacturing Process.

Factor Affecting the Surface Finish :-

The following factors affect the surface finish.

(a) Machine Variables.

(i) Cutting Speed.

(ii) Feed.

(iii) Depth of cut.

(b) Tool

Tool Geometry also influence the surface finish.

Nose radius.

Rake angle.

Side cutting edge angle.

Cutting edge.

Important terms :-

Average Roughness.

The root mean square roughness :

The skewness  $S_k$  and the kurtosis.

The Maximum Peak height  $R_p$ ,

The Maximum Valley height  $R_v$ ,

The Maximum peak to valley height  
( $R_{max}$ )

Analysis of Surface Finish :-

A Numerical assessment of Surface Finish can be carried out a number of ways.

1. Peak to Valley height

2. The Average Roughness.

3. Form factor for only



## Measurement of Surface Finish :-

The inspection and assessment of surface Roughness of machine components are carried out by means of various Measurement Techniques.

Surface Finish can be measured by following.

- (a) Surface Inspection by Comparison Method.
- (b) Direct Instrument method.

### Surface Inspection by Comparison Method :-

The surface inspection by comparison Method is classified as.

1. Touch Inspection
2. Visual Inspection
3. Scratch Inspection
4. Surface Photographs
5. Reflected Light Intensity.
6. Micro Interferometer.

## MEASUREMENT OF POWER, FLOW AND TEMPERATURE

Force, Torque, Power - Mechanical, Pneumatic, Hydraulic and Electrical Type, Flow Measurement, Venturimeter, Orifice meter, Rotameter, Pitot tube - Temperature: bimetallic strip, thermocouples, electrical resistance Thermometer - Reliability and Calibration - Readability and Reliability.

### Force Measurement :-

Force is Nothing but Product of Mass and acceleration.

$$F = ma$$

The Force is a Vector Quantity.

Unit of force is Newton (N)

Generally Force can be measured by two methods.

1. Direct force Measurement.

2. Indirect force Measurement.

## Direct Force Measurement :-

- (i) Analytical Balance Method.
- (ii) Platform Balance
- (iii) Chemical Arms Balance Method.
- (iv) Pendulum Scale.

## Indirect Force Measurement :-

- (i) Accelerometers ✓
- (ii) Electromagnetic Balance Method.
- (iii) Load cells.
  - (a) Capacitive Load cells.
  - (b) Magnetoelastic Load cells.
  - (c) Strain Gauge Load cells.
  - (d) Hydraulic Load cells.
  - (e) Pneumatic Load cells.
  - (f) Piezo Type Load cells.



## Elastic Loaded Members :-

Elastic Loaded Members are also used to measure the force. The deflection can be measured either directly or indirectly by using secondary transducers.

Direct measurement of elastic load members are

- (i) Coil springs
- (ii) Proving rings
- (iii) Load cells.
- (iv) Electronic weighing system.

## Measurement of Pressure :-

### Fluid Pressure sensors :-

The fluid pressure sensors are used to measure the pressure within the fluid to various forces acting on the fluid during flow.

The Various types of Pressure sensors are discussed.

The Pressure in a fluid is measured by the following device.

1). Mano Meters.

2). Mechanical Gauges.

Mano Meters :-

Mano meters are defined as the devices used for measuring the Pressure at a point in a fluid by balancing the column of fluid by the same or another column of fluid.

Manometers are classified as.

Simple Manometers :-

Used to Measure Pressure at a point in a fluid flowing through Pipe (or) Contained in Vessel.

## Differential Manometers :-

Used to measure the pressure difference between any two points in a fluid flowing through pipe (or) contained in a vessel.

## Mechanical Gauges :-

Mechanical Gauges are devices used for measuring the pressure by balancing the fluid column by the spring or dead weight.

- (a) Diaphragm Pressure gauge
- (b) Bourdon tube Pressure gauge.
- (c) Dead-weight Pressure gauge.
- (d) Bellows Pressure gauge

## Pressure Measurement Methods

### 1). Elastic Pressure Transducers ;

Bourdon tube , Pressure Gauge

(C - type , Helical type , spiral type)

Diaphragm pressure Transducer , Bellows.



2. Manometer Method.

3. Electric Pressure Transducers:

Strain Gauge type, Potentiometer type (resistance type), Capacitance type etc..

SIMPLE MANOMETERS :-

A simple manometer consists of a glass tube having one of its ends connected to a point where pressure is to be measured and other end remains open to atmosphere.

Common type of simple manometers are .

(i) Piezometer.

(ii) U-Tube Manometer

(iii) Single Column Manometer.

## Piezometer :

It is the simplest form of Manometer used for measuring gauge pressure.



Piezometer


$$P_A = \rho \times g \times h$$

$\rho$  = Density of liquid in  $\text{kg/m}^3$ .

$g$  = Acceleration due to gravity.

## Simple U tube Manometer :-

U tube Manometer consists of a glass tube bent in U-shape. One end is connected to the pipe and other end is open to atmosphere.



## Single Column Manometer :-

Single Column Manometer is modified form of U tube Manometer having a very large reservoir. There are two types of Single Column Manometer.

(a) Vertical Single Column Manometer.

(b) Inclined Single Column Manometer.

## Torque Measurement :-

Torque is nothing but twisting Moment. Torque may be defined as the force applied on the body on which it acts about an axis, causing the tendency of body to rotate.

$$\text{Power, } P = \frac{2\pi NT}{60}$$

Let  $T$  = Torque in (N-m)

$N$  = Speed in rpm



## Dynamometers :-

### Hydraulic Dynamometer :-

The Water brake is of hydraulic nature and it is the simplest example for hydraulic dynamometer. Generally the water brake is used for large amount of heat is dissipated to the water in water brake system.

Other types of Dynamometer are .

Eddy current Dynamometer .

Strain Gauge type .

Slip ring type .

These are the types of

Dynamometers.

# Torque Measurement Using Torsion Bar :-

Bar :-

It is classified into following types :

- (i) Torsion bar
- (ii) Magneto stritive
- (iii) Laser optic method.
- (iv) Proximity sensor method.
- (v) Stroboscope method.
- (vi) SAW method.

## Flow Measurement :-

The fluid flow can be measured by flow meters. The flow meters (or) obstruction meters are generally Mechanical type,

- (a) Orifice meter.
- (b) Venturimeter.
- (c) Variable area meter
- (d) Flow Nozzle.

## Types of Fluid Flow:

The fluid flow can be divided into three categories.


There are

1. Laminar flow.
2. Transient flow.
3. Turbulent flow.

## ORIFICE METER:-

An Orifice meter is a simple device used for measuring discharge of fluid through a pipe.

It works on the basis of Bernoulli's equation like Venturi meter.





$P_1$ ,  $V_1$ , and  $A_1$  are Pressure, Velocity and Area at the section 1

Similarly  $P_2$ ,  $V_2$ ,  $A_2$  are section 2

Applying Bernoulli's equation

$$\frac{P_1}{\rho} + \frac{V_1^2}{2g} + Z_1 = \frac{P_2}{\rho} + \frac{V_2^2}{2g} + Z_2$$

$$\left( \frac{P_1}{\rho} + Z_1 \right) - \left( \frac{P_2}{\rho} + Z_2 \right) = \frac{V_2^2}{2g} - \frac{V_1^2}{2g}$$

$$\text{But } \left( \frac{P_1}{\rho} + Z_1 \right) - \left( \frac{P_2}{\rho} + Z_2 \right) = h =$$

Difference in head

$$h = \frac{V_2^2 - V_1^2}{2g}$$


$$2gh = V_2^2 - V_1^2$$

The Coefficient of Contraction

$$C_c = \frac{A_2}{A_0}$$

## Venturimeter :-

When a Venturimeter is placed in a pipe carrying the fluid whose flow rate is to be measured, a pressure drop occurs between the entrance and throat of the Venturimeter. This pressure drop is measured using a differential pressure sensor and when calibrated this pressure drop becomes a measure of flow rate.



It is used where high pressure recovery is required.

Can be used for measuring flow rate of water, wastes, gases, suspended solids, slurries and dirty liquids.


Can be used to measure high flow rates in pipes having diameters in a few meters.

Rotameter :-

A tapered transparent glass tube graduated to read flow rate directly.

A float whose density is greater than that of the flowing fluid. The float diameter is such that it completely blocks the inlet of the tapered transparent glass tube.





Can be used to measure flow rates of Corrosive fluids.

Particularly Useful to measure low flow rate.

Flow conditions are visible.

flow rate is a linear function.

## Pitot tube :-

Pitot tube is a device used for measuring the velocity of flow at any point in a pipe or a channel.

It is based on the principle that if the velocity of flow at a point becomes zero, the pressure is increased due to the conversion of the kinetic energy into pressure energy.

$P_1$  : Intensity of pressure at Point 1

$V_1$  : Velocity at 1

$P_2$  : Intensity of pressure at 2

$V_2$  : Velocity at Point 2.

$H$  : depth of tube in the liquid.

$h$  : rise of liquid in the tube

Applying Bernoulli's equation at  
point (1) and (2)

$$\frac{P_1}{\rho g} + \frac{V_1^2}{2g} + z_1 = \frac{P_2}{\rho g} + \frac{V_2^2}{2g} + z_2$$

$\rightarrow (i)$

But  $z_1 = z_2$


Pressure at (1) =  $\frac{P_1}{\rho g} = H$

Pressure at (2) =  $\frac{P_2}{\rho g} = (h + H)$

Substitute these values.

$$H + \frac{V_1^2}{2g} = (h + H)$$

$$h = \frac{V_1^2}{2g} \quad \text{or} \quad V_1 = \sqrt{2gh}$$



Pitot tube.



## Temperature :-

It is a Numerical Measure of hot and cold bodies.

Its measurement is done by detection of heat transfer. Temperature is one of the most frequently used parameters for measurement and controlling of industrial processes.


Examples : Metallurgical Processes.

## Temperature Measurement devices :

- \* Bimetallic Strips
- \* Thermocouples
- \* Thermometers
- \* Thermistors
- \* Pyrometers.
- \* Resistance Temperature Detectors.


## Bimetallic Strip Thermometer :-

It is a strip made of two different metals, one on each side. In a bimetallic strip, the two metals have two different coefficients of expansion and when the temperature changes, the strip bends. The principle behind the bimetallic strip thermometer relies on the fact that different metals expand at different rates as they get heated up. By bonding two different metals together, we can make a simple electric controller that can withstand fairly high temperatures. This type of controller is often found in ovens.



Thermocouple :-

A thermocouple is a device made of two different wires joined at one end, called Junction end. The two wires are called thermoelements.



The two thermocouples are distinguished as positive and negative ones. The one end of the thermocouple is called tail end or reference end.

The Junction end is placed in the environment whose temperature  $T_2$  has to be measured. The tail end is held at a different temperature  $T_1$  (at ambient temperature).




## Thermometer :-

Thermometer was invented by Daniel Gabriel Fahrenheit. One of the most common device for measuring temperature is the glass thermometer.

It consists of glass tube filled with mercury or some other liquid, which acts as the working fluid.

When the liquid mercury is heated, it expands inside a narrow tube that has been calibrated to show the temperature. Temperature can be recorded in Celsius.



Thermometer.

This is similar to the design of medical thermometer.

Thermistors

Thermistors are made up of solid semiconductor materials having high coefficients of resistivity.

Semiconductors used to measure the Temperature are called Thermistors.

When a thermistor is employed for Temperature measurement, its resistance decreases with increase in temperature.

The Valence electrons, which are mutually shared by the Metal atoms, move continuously and freely through the Metal during their movement from atom to atom.

Bead Thermistor

Wafer Thermistor

Disc Thermistor

rod Thermistor

Probe Thermistor.

## PYROMETERS :-

If the temperature of a very hot body has to be measured, then contact type temperature measuring devices will not be suitable, since they will be damaged.

When they come in contact with the very hot body.

So, Non contact type temperature measuring devices are needed and they are called Pyrometers.

## Types of Pyrometers :-

- \* Optical Pyrometers.
- \* Total Radiation Pyrometer
- \* Infrared Pyrometer.

Pyrometer derived from the Greek word Pyro means fire and Metro means measuring.



## Readability :-

It is a measure of an Instrument's ability to display incremental changes in its Output Value. This is known as Readability.

## Reliability :-

Reliability of an item is the Probability that it will perform a required function under a specified condition for a stated period of time is known as Reliability.